

Ctrl

Alt

118.2+
 1,431.4+
 141.65+
 60.+
 1,710.55+
 288.2+
 50.+

c. Adhered
 state
 15811.000
 2/2/8
 7 day.

118.2 +	
1,431.4 +	
141.65 +	
60. +	
1,710.55 +	
288.2 +	
50. +	
1,689. +	0
192.75 +	0
185.3 +	15 ✓
110.35 +	10 X
699.2 +	10 ✓
859.7 +	50 X
552.85 +	35
1,248.2 +	20
496.8 +	10
121.65 +	00 X
189.85 +	00
90.7 +	00 X
924.6 +	75
23.75 +	30
322.3 =	35
11,507. *	.00 X
	.20
11,507. * X	.70
5. %	.85
75.35 *	.20
	.80
11,507. * X	.65
95. %	1.90 X
10,931.65 *	1.85
	1.70
30. +	1.60
50. +	1.75
100. +	1.00 X
80. +	2.30
80. +	5.40
120. +	
60. +	
150. +	0.00 60
50. +	0.00 40
970. +	0.00
1,080. =	
2,780. *	

2,730 * *

120 * +	10.00 - 30
40 * =	10.00 - 50
160 * *	50.00 - 100
	30.00 - 80
	20.00 - 80
10,931 * 65 +	50.00 - 120
2,700 * +	50.00 - 60
160 * =	
13,791 * 65 *	
13,791 * 65 *	
80 * %	
11,053 * 32 *	

000

Special Nett Item:

1 PCS	REAR TYRE N/S
1 PCS	REAR WINDSCREEN SEALANT

Labour Charge:

- TO CHECK WIRING
TO DISMANTLE & REFIX PDC SENSOR
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY
TO SPRAY RUST PROOFING
TO CONDUCT WHEEL ALIGNMENT
TO DISMANTLE & REFIX REAR WINDSCREEN
TO DISMANTLE & REFIX REAR DOOR MECHANISM

45 @ \$11,000