

ASS. REC. BY:

REF: CS/msh18005590/Algo 521

Special Instruction:

SUIVOR
Meinmen

ASSIGNMENT (Office)

From (Person): Vimmala

of MSTH

Date/Time: 26032018 2:31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKG 4286Z

Insured:

at Workshop m/s Performance

Tel: 9116 5700

of 303 Alexandra Road.

Policy No: 289988303MP

Claim No: 551499

Sum Insured:

Excess: \$ 1200.00

Make of Veh:

D.O.A. 05-032018

(Client's Record)

CA / REV / REP. / REV 24 HRS

27032018 @ 11am

H.O.D. Endorsement:

Date/Time: 26032018 3:51pm

Person Contacted: Han

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKG 4286Z - X
28/3/18 @ 3:51pm	revert to Vimmala via Meinmen.
28/3/18 @ 4:33pm	Huey Ni informed C/A of ex: \$1200 via Meinmen.
29/3/18 @ 9:25am	informed Han C/A of ex: \$1200 by email.
31/3/18 @ 4:01pm	2nd revert to Vimmala via Meinmen (supplementary)
01/8/18 @ 12:24pm	Huey Ni informed C/A at \$7356.05 via Meinmen.

Surveyor: PARY

REF:

4
5635N

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKH 42862

at Workshop m/s PERFORMANCE

of 303, ALEXANDRA RD

Insured: MSLH

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1,200

(Client's Record)

Make of Veh: _____

(Policy Condition)

11 am from

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 128K

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKH 42862 Yr Regn: 2012, Auk

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W X6 c.c. 2979

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 075936 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPAFA 2205 0L59-6863

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/40R20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DUELER

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 05/03/18 D.O.I. 22/03/18

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/8/18 9.56am / Report finalised with candidate final fig to 7356.05, 5 days.
(Red to 1902.90, 21%)

RECEIVED 01 AUG 2018

[Signature]
1/8/2018

Date/Time, File Pass to? : Preli. Report

1) 01/8/18 *[Signature]* : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee: 200

Transportation: _____ \$ + RS, _____ SI

Photos _____

Others _____

TOTAL _____

Report Format: WER-07

Lump Sum / I.B.I. (\$) 7356.05

10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18005590/R1qb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 26-03-2018	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKG 4286Z
Policy No.	28998830SMP	Coverage (\$)	0.00
Claim No.	551499	Excess (\$)	0.00
Assign From	MERIMEN (VIMMALA)	Assign Date	26/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/03/2018	Inspection Date	27/03/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		26 Mar 2018 14:31 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	JUN HEESOOK, ID: G6255635N, Tel: +6597251208, Email: HEESOK.JUN@GMAIL.COM		
Vehicle Reg. No.:	SKG4286Z	Date of Loss:	05/03/2018 13:00 - :59
Claim Type:	OD / 551499	Policy/Cover Note No.:	28998830SMP (Comprehensive) Coverage: 28/07/2017 - 30/08/2018
		Excess:	S\$1,200.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/03/2018]		
Driver/Custodian:	JUN HEESOOK (41 / Female), NRIC: G6255635N, Tel: +6597251208		
Adj Asg. Remarks:	Please revert. PML request to arrange for survey tomorrow -27/03/2018 at 10am. Please arrange with PML. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Rasul (LKKAuto)
Sent: Wednesday, 25 July 2018 9:56 AM
To: PBSP; SUR
Subject: RE: FINAL REPORT / SKG4286Z

Hi Caroline,

Thank u for your cooperation
Finalised amount at \$ 7356.05 / 5 days before excess is confirmed

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Wednesday, 18 April, 2018 3:25 PM
To: Rasul (LKKAuto); SUR
Subject: FINAL REPORT / SKG4286Z

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,011.00
Total Parts : 3,345.05
Total Labour & Parts : 7,356.05

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	07 Mar 2018 09:00	Clim Veh Model Changed	(202665) BMW X6 XDRIVE 35I ABS D/AB 3.0 (A).	[I] Vimmala D/O Raja Singam
2	07 Mar 2018 09:00	Clim Created	Reg No: SKG4286Z. Policy No: 28998830SMP. Acct Date: 2018/03/05. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MPML18031355	[I] Vimmala D/O Raja Singam
3	07 Mar 2018 09:34	Clim Registration Modified	IsCoverNote:Yes->No.	[I] Vimmala D/O Raja Singam
4	26 Mar 2018 11:00	Notification Status Changed	Ins.Status => Incoming Claim	[I] Vimmala D/O Raja Singam
5	26 Mar 2018 11:00	Clim Registration Modified	Setl.Type:3->0. Rep:1137->200071. Claim Type:SC->OD. Init.Est.:->8,000 - 9,000.	[I] Vimmala D/O Raja Singam
6	26 Mar 2018 12:01	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):	[I] Eng Huey Ni
7	26 Mar 2018 12:01	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/27	[I] Eng Huey Ni
8	26 Mar 2018 12:01	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eng Huey Ni
9	26 Mar 2018 13:27	Assignment 1st Accessed		[A] Ho Pei Fang
10	26 Mar 2018 14:27	Adj Assignment Cancelled	I.H.S APPT FULL	[I] Vimmala D/O Raja Singam
11	26 Mar 2018 14:27	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Vimmala D/O Raja Singam
12	26 Mar 2018 14:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. PML request to arrange for survey tomorrow -27/03/2018 at 10am. Please arrange with PML. Thank you.	[I] Vimmala D/O Raja Singam
13	26 Mar 2018 14:31	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/27	[I] Vimmala D/O Raja Singam
14	26 Mar 2018 14:31	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
15	26 Mar 2018 15:25	Assignment 1st Accessed		[A] Nivitha Govindasamy
16	26 Mar 2018 16:24	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CATHERINE CHONG KAI LING
17	28 Mar 2018 15:44	Adj Rpt Initiated		[A] SHIAU CHAN
18	28 Mar 2018 15:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/25	[A] SHIAU CHAN
19	28 Mar 2018 15:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/25	[A] SHIAU CHAN
20	28 Mar 2018 15:50	Adj Mandate Request	Cur.Req:7645.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
21	28 Mar 2018 17:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/25. Mandate Remarks: Approved mandate \$7102 (before excess \$1200) Check items \$543.50 to be verified.	[I] Eng Huey Ni
22	28 Mar 2018 17:32	Adj Mandate Set	Approved:7102.00:Approved mandate \$7102 (before excess \$1200) Check items \$543.50 to be verified.	[I] Eng Huey Ni
23	31 Jul 2018 16:00	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/25	[A] SHIAU CHAN
24	31 Jul 2018 16:01	Adj Mandate Request	Cur.Req:7356.05:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
25	01 Aug 2018 12:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/25. Mandate Remarks: Approved mandate \$7102 (before excess \$1200) Check items \$543.50 to be verified.	[I] Eng Huey Ni
26	01 Aug 2018 12:24	Adj Mandate Set	Approved:7356.05:Approved mandate \$7102 (before excess \$1200) Check items \$543.50 to be verified.	[I] Eng Huey Ni

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1760969	28/03/2018 15:44	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKG4286Z		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmla D/O Raja Singam

Date: 31 Jul 2018

Preliminary Advice

Vehicle No	: SKG4286Z	Accident Date	: 05/03/2018
Make	: BMW X6 XDRIVE 35I ABS D/AB	Policy No.	: 28998830SMP
Assignment Date	: 26/03/2018	Excess	: S\$1,200.00
Date of Inspection	: 27/03/2018	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,258.95	(ESTIMATE \$8,764.50 + SUPPLEMENTARY \$494.45)
Revised Amount	:S\$	7,356.05	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	7,356.05	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	128,000.00
COE / PARF Rebate	:S\$	90,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,298.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 29 March 2018 9:25 AM
To: han.kwan.yong@simedarby.com.sg
Cc: PBSP; SUR
Subject: VEHICLE SKG 4286Z (DOA: 05/03/2018)

Dear Han,

As instructed by our client MSIG Insurance, please proceed to repair the insured vehicle **SKG 4286Z (excess \$1,200/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	07 Mar 2018 09:00	Clim Veh Model Changed	(202665) BMW X6 XDRIVE 35I ABS D/AB 3.0 (A).	[I] Vimmala D/O Raja Singam
2	07 Mar 2018 09:00	Clim Created	Reg No: SKG4286Z. Policy No: 28998830SMP. Acct Date: 2018/03/05. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => No tification. Created from SAS:MPML18031355	[I] Vimmala D/O Raja Singam
3	07 Mar 2018 09:34	Clim Registration Modified	IsCoverNote:Yes->No.	[I] Vimmala D/O Raja Singam
4	26 Mar 2018 11:00	Notification Status Changed	Ins.Status => Incoming Claim	[I] Vimmala D/O Raja Singam
5	26 Mar 2018 11:00	Clim Registration Modified	Setl.Type:3->0. Rep:1137->200071. Claim Type:SC->OD. Init.Est.->8,000 - 9,000.	[I] Vimmala D/O Raja Singam
6	26 Mar 2018 12:01	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):	[I] Eng Huey Ni
7	26 Mar 2018 12:01	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/27	[I] Eng Huey Ni
8	26 Mar 2018 12:01	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eng Huey Ni
9	26 Mar 2018 13:27	Assignment 1st Accessed		[A] Ho Pei Fang
10	26 Mar 2018 14:27	Adj Assignment Cancelled	I.H.S APPT FULL	[I] Vimmala D/O Raja Singam
11	26 Mar 2018 14:27	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Vimmala D/O Raja Singam
12	26 Mar 2018 14:31	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. PML request to arrange for survey tomorrow -27/03/2018 at 10am. Please arrange with PML. Thank you.	[I] Vimmala D/O Raja Singam
13	26 Mar 2018 14:31	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/03/27	[I] Vimmala D/O Raja Singam
14	26 Mar 2018 14:31	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
15	26 Mar 2018 15:25	Assignment 1st Accessed		[A] Nivitha Govindasamy
16	26 Mar 2018 16:24	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] CATHERINE CHONG KAI LING
17	28 Mar 2018 15:44	Adj Rpt Initiated		[A] SHIAU CHAN
18	28 Mar 2018 15:48	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/25	[A] SHIAU CHAN
19	28 Mar 2018 15:48	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/25	[A] SHIAU CHAN
20	28 Mar 2018 15:50	Adj Mandate Request	Cur Req:7645.50:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
21	28 Mar 2018 17:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/25. Mandate Remarks: Approved mandate \$7102 (before excess \$1200) Check items \$543.50 to be verified.	[I] Eng Huey Ni
22	28 Mar 2018 17:32	Adj Mandate Set	Approved:7102.00:Approved mandate \$7102 (before excess \$1200) Check items \$543.50 to be verified.	[I] Eng Huey Ni

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1760969	28/03/2018 15:44	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKG4286Z		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmla D/O Raja Singam

Date: 28 Mar 2018

Preliminary Advice

Vehicle No	: SKG4286Z	Accident Date	: 05/03/2018
Make	: BMW X6 XDRIVE 35I ABS D/AB	Policy No.	: 28998830SMP
Assignment Date	: 26/03/2018	Excess	: S\$1,200.00
Date of Inspection	: 27/03/2018	Est. Duration of Repair	: 5.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,764.50
Revised Amount	:S\$	7,102.00
Check Items (Estimated)	:S\$	543.50
Total	:S\$	7,645.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	128,000.00
COE / PARF Rebate	:S\$	90,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,298.00

Remarks

(X) The vehicle is economical/not economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/03/2018 11:46
Date Of Accident	05/03/2018 13:00
Exact Location Of Accident	OG CENTER POINT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG4286Z
Insured/Policyholder	
Name Of Registered Owner	JUN HEESOOK
Passport No/FIN	G6255635N
Email Address	HEESOK.JUN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97251208
Alternative Phone No	OFFICE-96498603

Vehicle Particulars

Manufacturer	BMW
Model	X6
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	10114990

Driver

Name of Driver	JUN HEESOOK
Passport No/FIN	G6255635N
Date Of Birth	30/08/1976
Occupation	INDOOR
Date Of Driving Pass	20/01/2010
Driving Experience	8 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97251208
Fax Number	
Contact Number	OFFICE-96498603
EMail Address	HEESOK.JUN@GMAIL.COM

Address	130 TANJONG RHU RD #11-10 PEBBLE BAY
Postcode	436918
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:
 March 5, 2018
 16:41


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:
 March 5, 2018
 16:41


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I tried to get into Entrance of car park,
I accidentally bump left side of my car into a
hidden block of wall. It caused scratches on
the left side of the car body

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:
5 March 2018
16:41


Driver's Signature
(If driver is not the policyholder)
Date & Time:
5 March 2018
16:41


Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	5635N
Vehicle Details	
Vehicle No.:	SKG4286Z
Vehicle to be Exported:	No
Intended De-registration Date:	28 Mar 2018
Vehicle Make:	B.M.W.
Vehicle Model:	X6 XDRIVE35I AWD SR DSC NAV HUD LED
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	05888155N55B30A
Chassis No.:	WBAFG22050L596863
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$72,405.00
Original Registration Date:	31 Aug 2012
First Registration Date:	31 Aug 2012
Transfer Count:	1
Actual ARF Paid:	\$72,405.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2022
PARF Rebate Amount:	\$50,683.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$92,700.00
COE Rebate Amount:	\$40,019.00
Total Rebate Amount:	\$90,702.00

The information contained herein is correct as at 28 Mar 2018

OK

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No: 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46128
Date Estimated : 06/03/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Jun Heesook
130 Tanjong Rhu Rd, Pebble Bay, Lob
#11-10

Singapore 436918

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG4286Z	L596863	31/08/2012	X6 xDrive35i	0

DESCRIPTION

To replace front bumper & attachments, front left fender, front left fender wheel arch cover including to knock out dented area caused by the accident

1700 ~~2,550.00~~

To respray front bumper and front left fender

1931 ~~2,146.00~~

To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.

150 ~~177.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~177.00~~

Sundries.

NEC 80.00

Total Labour 1: 5,130.00

DESCRIPTION

FRT LEFT FENDER INNER COVER
BLIND RIVET
BODY NUT
BLIND RIVET
FRT BUMPER (PDC)
FRT BUMPER LOWER TRIM (PDC)
FRT BUMPER REPAIR KIT
CLOSED GRID LH
CLOSED GRID RH
FRT LH FENDER (PRIMED)
FRT LH PRESSURE LIP SEAL
FRT LH FENDER WHEEL ARCH COV
FRT BUMPER LH SIDE MARKER RE

QTY	PRIC	VALUE
1	179.25	179.25
20	1.10	22.00
10	0.90	9.00
20	1.15	23.00
1	1,218.60	1,218.60
1	234.60	234.60
1	117.85	117.85
1	67.35	67.35
1	67.35	67.35
1	1,397.40	1,397.40
1	57.70	57.70
1	202.45	202.45
1	37.95	37.95

Total Parts : 3,634.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796801 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46128	Page No. : 2 of 2
Date Estimated : 06/03/2018	
Prepared By : Han Kwan Yong	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKG4286Z	L596863	31/08/2012	X6 xDrive35i	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 27/03/18 @ 1105 Excess \$S 1200

Surveyor's Name RASUL Sign RM

Surveyor's Tel 90010068 Authorised Yes No REVERT

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ P.M.L. Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

[Handwritten Signature]
29/3/18

Labour 1	:	5,130.00
Parts	:	3,634.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	613.52
Grand Total	:	<u>9,378.02</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

4258.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46128
Date Estimated : 06/03/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Jun Heesook
130 Tanjong Rhu Rd, Pebble Bay, Lob
#11-10

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 436918

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKG4286Z	L596863	31/08/2012	X6 xDrive35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# LH MODULE CARRIER,BOTTOM *	254.05	1.00		254.05 <i>CRA ✓</i>
# FRT LH FENDER WHEEL ARCH COVER *	202.45	1.00	<i>repeated</i>	202.45 <i>BE ✓</i>
# FRT BUMPER LH SIDE MARKER REFLECTOR *	37.95	1.00	<i>repeated</i>	37.95 <i>SC ✓</i>

Total Labour :
Total Parts : 494.45
Total Labour & Parts : 494.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46128
Date Estimated : 06/03/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Jun Heesook
130 Tanjong Rhu Rd, Pebble Bay, Lob
#11-10

Singapore 436918

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKG4286Z	L596863	31/08/2012	X6 xDrive35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, front LH fender and attachments include knocking out dents caused by the accident	1700.00		1,700.00	
To respray front bumper and front LH fender	1931.00		1,931.00	
To remove old PDC assembly and reconnect to new bumper include conducting checks for proper function	150.00		150.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT BUMPER (PDC)	1,218.60	1.00		1,218.60
FRT BUMPER LOWER TRIM (PDC)	234.60	1.00		234.60
FRT LH FENDER (PRIMED)	1,397.40	1.00		1,397.40
# LH MODULE CARRIER,BOTTOM *	254.05	1.00		254.05
# FRT LH FENDER WHEEL ARCH COVER *	202.45	1.00		202.45
# FRT BUMPER LH SIDE MARKER REFLECTOR *	37.95	1.00		37.95

SUPPLEMENTARY ITEMS

Total Labour :	4,011.00
Total Parts :	3,345.05
Total Labour & Parts :	7,356.05
Deduction for Excess :	1,200.00
Total Repair Costs less Excess:	6,156.05
GST @7%:	430.92
Grand Total :	6,586.97

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018		26 Mar 2018 14:31 Edit Adj Rpt	S\$7,356.05 Edit Estimates	S\$7,356.05 View Rpt		Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	JUN HEESOOK, ID: G6255635N, Tel: +6597251208, Email: HEESOK.JUN@GMAIL.COM		
Vehicle Reg. No.:	SKG4286Z	Date of Loss:	05/03/2018 13:00 - :59 [66 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 551499	Policy/Cover Note No.:	28998830SMP (Comprehensive) Coverage: 28/07/2017 - 30/08/2018
		Excess:	S\$1,200.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmla D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 25/04/2018]		
Driver/Custodian:	JUN HEESOOK (41 / Female), NRIC: G6255635N, Tel: +6597251208		
Adj Asg. Remarks:	Please revert. PML request to arrange for survey tomorrow -27/03/2018 at 10am. Please arrange with PML. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG_SG (01/08/2018): Alert - Adj Mandate Approved (S\$7356.05) - SKG4286Z - Claim Handler: Vimmla D/O...
- MSIG_SG (01/08/2018): SKG4286Z (551499)
- MSIG_SG (28/03/2018): Alert - Adj Mandate Approved (S\$7102.00) - SKG4286Z - Claim Handler: Vimmla D/O...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKG4286Z (551499)**

OD

Mar 5 2018 1:00PM

[JUN HEESOOK]

Performance Motors Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	06/03/18 12:30	Accident Statement	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/18 15:48	Adjuster Immediate Advice	Load HTM	
2	31/07/18 16:00	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	06/03/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
2	06/03/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
3	06/03/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
4	06/03/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
5	06/03/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
6	06/03/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
7	06/03/18 11:50	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/03/18 15:48	Odometer Reading	Load JPG <input checked="" type="checkbox"/>	
2	28/03/18 15:48	Chassis Number	Load JPG <input checked="" type="checkbox"/>	
3	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
4	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
5	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
6	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
7	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
8	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
9	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
10	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
11	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
12	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
13	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
14	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
15	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
16	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
17	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
18	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
19	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
20	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	
21	28/03/18 15:48	General View	Load JPG <input checked="" type="checkbox"/>	

Assessment Reports				
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail Print
22	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
23	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
24	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
25	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
26	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
27	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
28	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
29	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
30	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
31	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
32	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
33	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
34	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
35	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
36	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
37	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
38	28/03/18 15:48	General View		Load JPG <input checked="" type="checkbox"/>
39	02/08/18 17:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	02/08/18 17:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
41	02/08/18 17:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
42	02/08/18 17:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
43	02/08/18 17:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	26/03/18 11:02	Estimate from Performance Motor to arrange for survey on 27/03/2018 at 10am		Load PDF <input type="checkbox"/>
2	26/03/18 11:02	Driver NRIC/Driving licence & CI		Load PDF <input type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail Print
1	06/03/18 12:29	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/03/18 15:49	ESTIMATE		Load PDF <input type="checkbox"/>
2	01/08/18 11:03	SUPPLEMENTARY LIST		Load PDF <input type="checkbox"/>
3	01/08/18 11:03	REVISED ESTIMATE		Load PDF <input type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Performance Motors Limited (Alexandra)		
1	06/03/18 12:30	Accident Statement		Load HTM <input type="checkbox"/>
Photos/Images			3 per page	
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail Print
1	06/03/18 11:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	06/03/18 11:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	06/03/18 11:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	06/03/18 11:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	06/03/18 11:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	06/03/18 11:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	06/03/18 11:50	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Assessment Reports				<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	06/03/18 12:29	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18005590/R1QBS2
Date: 02/08/2018

REFERENCE

Insured/Claimant:	JUN HEESOOK	Policy No:	28998830SMP	Claim No:	551499
Date of Loss:	05/03/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG4286Z	Engine No:	05888155N55B30A
Make & Model:	BMW X6 XDRIVE 35I ABS D/AB, 3.0 (A)	Chassis No:	WBAFG22050L596863
Reg. Date:	31/08/2012 (Man. Year: 2012)	Odometer:	75936 km
Colour:	Blue		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/40 R20	Rear Tyre Size:	275/40 R20
Front Left Side:	Dueler 6 mm	Rear Left Side:	Dueler 6 mm
Front Right Side:	Dueler 6 mm	Rear Right Side:	Dueler 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,208.95	3,425.05	783.90	18.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	3,931.00	1,119.00	22.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,258.95	7,356.05	1,902.90	20.55
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	8,058.95	6,156.05	1,902.90	23.61
+ GST 7.00/7.00% (S\$)	564.13	430.92	133.21	23.61
Nett Amount (S\$)	8,623.08	6,586.97	2,036.11	23.61

INSPECTION

Date of Assignment:	26/03/2018	
Date Inspected:	27/03/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Aug 2018)
Parts: M1-SUV	BMW X6 XDRIVE 35I ABS D/AB 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG4286Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LEFT FENDER INNER COVER	Serviceable	179.25 FS	*- FS
2	20		*BLIND RIVET	Serviceable	22.00 FS	*- FS
3	10		*BODY NUT	Serviceable	9.00 FS	*- FS
4	20		*BLIND RIVET	Serviceable	23.00 FS	*- FS
5	1		*FRT BUMPER (PDC)	Scratched	1,218.60 FS	*1,218.60 FS
6	1		*FRT BUMPER LOWER TRIM (PDC)	Scratched	234.60 FS	*234.60 FS
7	1		*FRT BUMPER REPAIR KIT	Serviceable	117.85 FS	*- FS
8	1		*CLOSED GRID LH	Serviceable	67.35 FS	*- FS
9	1		*CLOSED GRID RH	Serviceable	67.35 FS	*- FS
10	1		*FRT LH FENDER (PRIMED)	Deformed	1,397.40 FS	*1,397.40 FS
11	1		*FRT LH PRESSURE LIP SEAL	Serviceable	57.70 FS	*- FS
12	1		*FRT LH FENDER WHEEL ARCH COV	Deformed	202.45 FS	*202.45 FS
13	1		*FRT BUMPER LH SIDE MARKER RE	Scratched	37.95 FS	*37.95 FS
14	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
15	1		*LH MODULE CARRIER, BOTTOM	Cracked	254.05 FS	*254.05 FS
16	1		*FRT LH FENDER WHEEL ARCH COVER	Repeated	202.45 FS	*- FS
17	1		*FRT BUMPER LH SIDE MARKER REFLECTOR	Repeated	37.95 FS	*- FS
Total Parts (S\$)					4,208.95	3,425.05

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS, FRONT LEFT FENDER, FRONT LEFT FENDER WHEEL ARCH COVER INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.	New	2,550.00	1,700.00
2	TO RESPRAY FRONT BUMPER AND FRONT LEFT FENDER.	New	2,146.00	1,931.00
3	TO REMOVE OLD PDC ASSEMBLY AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	New	177.00	150.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.	New	177.00	150.00
Gross Labour Cost (\$\$)			5,050.00	3,931.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >