FAX Number : 63685592





Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No SHB1807C

Ref. No TAX/03/18/2086

Reg. Date 11/02/2015

Vehicle Type TAXI

Make TOYOTA PRIUS

Model **PRIUS**

Name of Driver GOH KOK GAN

Type of Accident SIDE SWIPE

Date / Time of Accident 16/03/2018 11:50:00 PM

Accident Reported Date / Time : 17/03/2018 12:00:00 AM

Surveyor is Required? Yes

Survey by

Vehicle is Towed Back? No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No : 000024095136

Special Instruction to ARC, if any :

SLC6400G - AIG - LKK

Prepared Date : 21/03/2018 10:03:34 AM @sma

21/3/18. - Lunp Sun Repair. - Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display demaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Control of the Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U205758530

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Total Labout Charges

Quotation from ARC Adjusted by Surveyor, if applicable

338.00 0.00

Total Spray Painting Charges 378.00 0.00 **Total Material Charges** 335.04 335.04 Other Charges 140.00 0.00

TOTAL 1,191.04 0.00 Lum Sum Total

1,200.00 0.00 No. of Repair Days 3.00 0.00 2 days.

Prepared / Adjusted By

Arc / Surveyor Sing Off Date : 21/03/2018 11:34:10 AM 01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 21/03/2018 11:33:10 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR LH FRONT PORTION	338.00	0.00 200		
Total Labour	338.00	0.00		

Part 2 - Spray Painting & Panel Beating Related Works

Total Spray Painting & Panel Beating	378.00	0.00		
TO REPSRAY FRONT BUMPER	378.00	0.00 200.		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Total Other Costs	140.00	0.00			
TO WASH AND VACUUM	60.00	0.00 × 0.00 ×			
TO CHECK WIRING AND SYSTEM FUNCTION	80.00				
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen	Surveyor Approved	Photos Attached	
52119- 47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No R	
52116- 47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace	No 7	
TOTAL MATERIALS							418.80 418.80				
TOTAL MATERIALS(Discounted)						335.04	335.04				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price	Discount (%)	Final Price	ARC Check	Surveyor Check	LT
TOTAL SUPPLEMENTARY MATERIALS								CHECK	Check