

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9733T****AAD1803-191***Not Autharise  
L1 Qty \$32000*

Vehicle No.:	<b>SHD 9733T</b>
Chassis No.:	VF1ABL15AUC276136
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	22.3.2018
Third Party Insurer :	<b>AIG</b>

	<b>PART</b>		<b>LIST</b>
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77 X
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP LH	\$	<i>Cut</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84 X
1	FENDER BRACKET LOWER LH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84 X
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66 X
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78 X
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36 X
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75 X
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54 X
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36 X
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46 X

<b>TOTAL</b>	<b>\$</b>	<b>16,398.73</b>
<b>10%</b>	<b>\$</b>	<b>1,639.87</b>
	<b>\$</b>	<b>14,758.85</b>

**Trans-cab Auto Services Pte Ltd**

AAD1803-191

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9733T

**Special Nett**

1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT LH	\$	<i>nn</i> 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>nn</i> 10.50
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>nn</i> 69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>nn</i> 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>nn</i> 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>nn</i> 30.00
1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i> 30.50
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>nn</i> 80.00
1	FRONT DOOR STICKER 'Chassis'	\$	<i>nn</i> 50.00

<b>TOTAL</b>	<b>\$</b>	<b>438.00</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>15,196.85</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00 <i>4001</i>
Putty and spray painting of the affected portion.	\$	3,200.00 <i>4401</i>
To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>

**Trans-cab Auto Services Pte Ltd**

**AAD1803-191**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9733T**

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i>	380.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>na</i>	170.00	<i>X</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i>	170.00	<i>X</i>

**TOTAL** \$ 8,910.00

**Over All Total** \$ 24,106.85

**LUMP SUM (REPAIR DAY)**

~~10 DAYS~~

*2 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: