



# SLC8296C

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
6 Benoi Sector, Singapore (629904)  
Tel : 6358 3031 | Fax No : 6694 4929

### ACCIDENT REPAIR ESTIMATE

TP INSURER :	<u>INDIA</u>	Vehicle Reg. No. :	<u>SLC8296C</u>
OWN INSURER :	<u>AIG</u>	Vehicle Reg. Date:	<u>26-May-2016</u>
CLAIM TYPE :	<u>TP</u>	Make / Model :	<u>T. SIENTA 1.5X CVT</u>
Date of Accident :	<u>22/3/2018</u>	Engine No. :	<u>2NR8596220</u>
		Chassis No. :	<u>NSP1707025641</u>

### COST OF CLAIMS

Parts Cost / List Items :	\$	<u>20,598.30</u>
Plus/Less <u>25%</u>	\$	<u>5,149.58</u>
Total Cost / List :	\$	<u>15,448.73</u>
Special Nett Items :	\$	<u>1,070.00</u>
<b>Total Parts Amount :</b>	\$	<u>16,518.73</u>
<b>Total Labour Amount :</b>	\$	<u>4,800.00</u>
<b>Gross Total :</b>	\$	<u>21,318.73</u>
GST % : <u>7%</u>	\$	<u>1,492.31</u>
<b>Nett Amount :</b>	\$	<u>22,811.04</u>

### Surveyor Name and Company :

Rasul (LKK)  
Date of survey : 27/03/18 @ 1730  
Part by Part (Lump Sum) : 6 days  
Resurvey Before Paint (After Paint)  
Authorize/Not Authorize/Without Prejudice  
Email : \_\_\_\_\_  
Fax No : \_\_\_\_\_  
HP No : 90010068

This claim is handled by : PAULO BALDOZ

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLC8296C  
 Vehicle Reg. Date: 26/5/2016  
 Make / Model : T. SIENTA 1.5X CVT  
 Engine No. : 2NR8596220  
 Chassis No. : NSP1707025641

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	Ne ✓	\$ 168.40		
2	1	Rear number plate lamp assy	X	\$ 158.00		
3	1	Rear bumper	TR ✓	\$ 838.80		
4	1	Rear bumper cover center	SCA ✓	\$ 182.40		
5	2	Rear bumper cover LH/RH	X	\$ 391.00		
6	1set	Rear bumper clips	Ne ✓	\$ 50.00		
7	2	Rear bumper side retainer LH/RH	X	\$ 164.00		
8	2	Rear bumper bracket LH/RH	Ne ✓	\$ 164.00		
9	1	Rear bumper sponge	?	\$ 98.00		
10	2	Rear bumper reflector LH/RH	X	\$ 216.00		
11	2	Rear bumper splash shield LH/RH	X	\$ 340.00		
12	1	Tail gate	BT ✓	\$ 1,360.00		
13	1	Tail gate lock	BT ✓	\$ 246.60		
14	1	Tail gate striker	X	\$ 48.00		
15	2	Tail gate stay LH/RH	X	\$ 320.00		
16	1	Tail gate logo	Ne ✓	\$ 50.00		
17	1	Tail gate emblem RH	Ne ✓	\$ 59.40		
18	1	Tail gate outer garnish	DE ✓	\$ 84.50		
19	1	Tail gate weatherstrip	Ne ✓	\$ 145.00		
20	2	Tail gate lamp LH/RH	BT ✓	\$ 720.00		
21	1	Tail door trim	.	\$ 280.00		
22	1	Tail gate inner side trim LH	X	\$ 750.00		
23	2	Tail lamp LH/RH	X	\$ 780.00		
24	1	Tail lamp bracket LH/RH	X	\$ 180.00		
25	1	Tail gate inner handle	X	\$ 90.00		
26	1	Antenna sensor	X	\$ 190.00		
27	1	Rear wiper motor	?	\$ 400.00		
28	1	Rear wiper motor link	?	\$ 240.00		
29	1	Rear wiper arm	ad ✓	\$ 200.00		
30	1	Rear wiper blade	at ✓	\$ 400.00		
31	1	Rear end panel outer	*R	\$ 498.20		
32	1	Rear end panel inner	X	\$ 498.20		
33	1	Rear end panel garnish	?	\$ 195.20		
34	1	Spare tyre well panel	X	\$ 822.60		
35	1	Spare tyre board	X	\$ 256.00		
36	1	Spare tyre bracket	X	\$ 60.00		
37	1	Spare tyre insulator	X	\$ 280.00		
38	1	Spare tyre tool tray	X	\$ 758.00		
39	1	Exhaust muffler	X	\$ 700.00		
40	1	Exhaust muffler mounting	X	\$ 70.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLC8296C  
 Vehicle Reg. Date: 26/5/2016  
 Make / Model : T. SIENTA 1.5X CVT  
 Engine No. : 2NR8596220  
 Chassis No. : NSP1707025641

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust heat shield	X	\$ 90.00		
42	2	Rear fender LH/RH	X	\$ 3,352.00		
43	2	Rear fender garnish lower LH/RH	X	\$ 1,214.00		
44	2	Rear fender garnish upper LH/RH	X	\$ 360.00		
45	2	Rear fender air duct LH/RH	X	\$ 150.00		
46	1set	Tail door trim clips	new /	\$ 40.00	new	
47	1set	Tail gate inner side trim LH clips	X	\$ 40.00	X	
48	1	Rear windscreen	new /	\$ 1,900.00		
49	1	Rear end panel sealant	X		\$ 80.00	
50	1	Spare tyre panel sealant	X		\$ 80.00	
51	1	Spare tyre sound damper	X		\$ 250.00	
52	1	Sundries	10		\$ 60.00	
53	1	Tail gate seal	new /		\$ 60.00	40
54	1	Rear fender sealant		X	\$ 80.00	
55	1	Reverse sensor			\$ 300.00	200?
56	1	Rear number plate with frame		X	\$ 50.00	
57	1	Rear windscreen "decal"		new /	\$ 30.00	
58	1	Rear windscreen sealant		new /	\$ 80.00	60
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

