

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJY8319D

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES1890303/YISHUN
 Date: 26 Mar 2018
 Policy No: 5074263429-02
 Veh Reg No: SJY8319D
 Make/Model: TOYOTA VIOS E
 MANUAL
 Chassis No: MR053HY9305174513
 Engine No: 1NZY121007
 Reg. Date: 06/10/2010

WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 25/03/2018
 TP Veh Reg No: GBH133J

Not Authored
1/1 Sur & ?
Resurvey After Paint

Estimate Repair Cost to Vehicle No :SJY8319D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	427.50	1 PC	427.50	✓
2 REAR BUMPER RH REFLECTOR	82.80	1 PC	82.80	✓
3 REAR BUMPER SIDE RETAINERS	92.33	2 PCS	184.66	✓
4 REAR BUMPER RH BRACKET	63.77	1 PC	63.77	?
5 REAR BUMPER CLIPS	3.89	6 PCS	23.34	✓
6 TAILLAMPS <i>old Br</i>	277.62	2 PCS	555.24	✓
7 TAILLAMP PANELS <i>old Br</i>	105.00	2 PCS	210.00	?
8 TAILLAMP LOWER GARNISHS	31.22	2 PCS	62.44	?
9 REAR BOOT	510.85	1 PC	510.85	✓
10 REAR BOOT INNER LOCK	95.97	1 PC	95.97	✓
11 REAR BOOT INNER RUBBER	175.35	1 PC	175.35	50% ✓
12 REAR BOOT LOGO	50.20	1 PC	50.20	✓
13 REAR BOOT EMBLEM (VIOS)	44.20	1 PC	44.20	✓
14 REAR BOOT EMBLEM (E)	34.37	1 PC	34.37	✓
15 REAR BOOT OUTER GARNISH	198.80	1 PC	198.80	✓
16 REAR BOOT HINGES	154.28	2 PCS	308.56	X
17 TAILLAMP INNER RUBBERS	26.25	2 PCS	52.50	?
18 REAR CENTRE PANEL	571.89	1 PC	571.89	✓
19 REAR CENTRE PANEL INNER TOP GARNISH	200.76	1 PC	200.76	?
20 REAR SPARE TYRE SIDE SPONGES	177.57	2 PCS	355.14	?
21 REAR SPARE TYRE FRT SPONGE	132.80	1 PC	132.80	?
22 REAR EXHAUST PIPE	595.13	1 PC	595.13	?
23 REAR RH FENDER INNER GARNISH	224.20	1 PC	224.20	✓
			5,160.47	
			Less 25%	1,290.12
				3,870.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department


Estimate No: ES1890303/YISHUN
Date: 26 Mar 2018
Policy No: 5074263429-02
Veh Reg No: SJY8319D
Make/Model: TOYOTA VIOS E
 MANUAL
Chassis No: MR053HY9305174513
Engine No: 1NZY121007
Reg. Date: 06/10/2010

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 25/03/2018
TP Veh Reg No: GBH133J

Estimate Repair Cost to Vehicle No :SJY8319D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Special Net				
24 REAR NUMBER PLATE	35.00	1 PC	<i>nd</i> 35.00 ✓	35.00
			35.00	35.00
Labour				
25 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, HINGES, TO CUT, WELD & RENEW REAR END PANEL, TAILLAMP PANELS, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS & REALIGN THE SAME	1,200.00	1 LA	1,200.00 <i>1000</i>	
26 PUTTY & RESPRAY ON REAR BOOT, HINGES, REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, REAR PANEL & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00 <i>900</i>	
27 RUSTPROOFING	60.00	1 LA	60.00 ✓	
			2,260.00	2,260.00
Total				S\$ 6,165.35
Add GST @ 7%				431.57
Total Amount Payable				<u>S\$ 6,596.92</u>

For Cheng Hoe Motor Pte Ltd



 AUTHORIZED SIGNATURE