



Pte Ltd

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

AIG Building
 78 Shenton Way #07-16
 Singapore 079120

Vehicle number	SLL138G
Make / Model	BMW/535I
Chassis number	WBAFR72030C26479
Accident date	20 March 2018
Reference	1803-21

Qty Particulars Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	BOOTLID HH	1932.00 X
1	BOOTLID INNER TRIM HH	146.40 X
2	BOOTLID HINGE HH	138.00 X
2	BOOTLID LAMP HH	816.00 X
1	BOOTLID CENTR LOGO HH	82.80 X
1	BOOTLID LOCK MECHANISM HH	254.40 X
1	REAR BOOTLID LOCK CATCH HH	63.60 X
1	REAR BOOTLID CONTROL UNIT HH	706.80 X
1	END PANEL <i>paper</i>	981.60 X
1	END PANEL GARNISH HH	135.60 X
1	END PANEL LOCK SENSOR HH	445.00 X
1	SPARE TYRE COMPARTMENT COVER HH	822.00 X
2	FENDER INNER TRIM HH	384.00 X
2	REAR BUMPER RETAINER <i>SVC</i>	240.00 X
1	REAR BUMPER BRACKET CENTRE <i>broken</i>	91.20 ✓
1	REAR BUMPER CENTRE UPPER HOLDER <i>deformed</i>	78.00 ✓
1	REAR BUMPER CENTRE LOWER HOLDER HH	58.80 X
1	REAR BUMPER REINFORCEMENT <i>Deformed</i>	858.00 ✓
2	REAR BUMPER REFLECTOR HH	84.72 X
1	REAR BUMPER TOW COVER HH	67.20 X
4	REAR BUMPER PARKING SENSOR <i>2pc Dam 2pc HH</i>	1480.00 ✓ 740.00
4	REAR BUMPER PARKING SENSOR HOLDER HH	307.20 X
2	REAR BUMPER LOWER SIDE GARNISH HH	348.00 X
2	REAR TAILLAMP HH	1375.20 X
1	REAR EXHAUST MOUNTING HH	64.00 X
1	REAR BUMPER LOWER TRIM HH	210.00 X
		10% 7048.92
		Less 5% 352.45
		Subtotal 6696.47
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
		Balance B/F 6696.47
		<i>After Market</i> 1650.00
1	REAR BUMPER (AFTER MARKET) <i>custom</i>	2500.00
1	REAR BUMPER LOWER GARNISH (AFTER MARKET) <i>broken</i>	1500.00 <i>1000</i>
1	REAR EXHAUST ASSY (AFTER MARKET) <i>1st</i>	3500.00 <i>1960</i>
1 SET	REAR BUMPER CLIP <i>HC</i>	60.00 <i>30</i>
1 SET	REAR FENDER INNER TRIM CLIP HH	50.00 X
1	JOINT SEALANT HH	150.00 X
1	REAR NUMBER PLATE HH	80.00 X
		Subtotal 7840.00
		Balance C/F 14536.47

1767.20
 1590.48


4640.00

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	14536.47
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 NA
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
3	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	200.00 80/-
4	DIAGNOIS CHECK AND CLEAR FAULT CODE	400.00 NA
3	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 NA
4	PANEL BEATING ON AFFECTED AREAS 1270/-	1500.00 500/-
5	SPRAY PAINTING ON AFFECTED AREAS	1400.00 500/-
6	REMOVE AND RENEW REAR STICKERS ON AFFECTED PANEL	800.00 150/-
	Subtotal	4710.00
	Grand total	19246.47

26/03/2018 @ 1045 hrs
 N/A Andrew

7500.48
 4/56000/-

L/smm 4 days


 Ryan

LKK Auto



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: