



Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

JARMAY ENTERPRISES PTE LTD  
18 BOON LAY WAY, TRADEHUB 21 #06-119  
SINGAPORE 609966

Attention : THE OWNER

Contact : 81806724 66590388 90903134

Estimate : ES006294

Date : 25/03/2018

Vehicle Num. : GBC7996R

Make/Model : TOYOTA HIACE-2013

Chassis/Eng# : JTFHT02P300125005/1KD2333952

Accident Date : 21/03/2018

Claim No. :

Reference :

Policy No. :

*Not Authorized  
1-B-1  
Runny B & pain  
4 days*

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

- |     |   |                                   |
|-----|---|-----------------------------------|
| 1.  | 1 | LIST ITEMS :                      |
| 2.  | 1 | TAIL GATE                         |
| 3.  | 1 | TAIL GATE INNER LOCK              |
| 4.  | 1 | TAIL GATE LOCK CATCH              |
| 5.  | 1 | TAIL GATE W/SCREEN GLASS MOULDING |
| 6.  | 1 | TAIL GATE OUTER HANDLE            |
| 7.  | 2 | TAIL GATE NUMBER PLATE LAMP       |
| 8.  | 1 | TAIL GATE TOYOTA LOGO             |
| 9.  | 1 | TAIL GATE INNER BOARD             |
| 10. | 1 | TAIL GATE RUBBER SEAL             |
| 11. | 1 | HIACE STICKER                     |
| 12. | 1 | TOYOTA STICKER                    |
| 13. | 1 | REAR BUMPER                       |
| 14. | 2 | REAR BUMPER BRACKET               |
| 15. | 6 | REAR BUMPER CLIP                  |
| 16. | 1 | REAR END PANEL INNER              |
| 17. | 1 | REAR END PANEL OUTER              |
| 18. | 1 | REAR END PANEL SCUFF PLATE        |

List TotalS\$ :

25.00% Discount S\$ :

- |    |   |                                  |
|----|---|----------------------------------|
| 1. | 1 | SPECIAL NETT ITEMS :             |
| 2. | 1 | TAIL GATE W/SCREEN GLASS SEALANT |
| 3. | 1 | TAIL GATE NUMBER PLATE           |
| 4. | 1 | 70KM STICKER                     |

Special Nett Total S\$ :

|      |          |   |
|------|----------|---|
| BH   | 2,178.00 | ✓ |
| R    | 392.30   | X |
| R    | 103.00   | X |
| mc   | 179.00   | ✓ |
| Sh   | 187.20   | X |
| Sh   | 135.80   | X |
| mc   | 72.20    | ✓ |
| Sh   | 195.80   | X |
| Sh   | 405.00   | X |
| mc   | 49.00    | ✓ |
| mc   | 46.00    | ✓ |
| Bu   | 597.30   | ✓ |
| Sh   | 90.20    | X |
| 8.50 | 51.00    | ✓ |
| R    | 943.20   | X |
| Sh   | 581.60   | X |
| Sh   | 291.60   | X |
|      | 6,588.40 |   |
|      | 1,647.10 |   |
|      | 4,941.30 |   |

|    |        |   |
|----|--------|---|
| mc | 65.00  | ✓ |
| Sh | 25.00  | X |
| mc | 15.00  | ✓ |
|    | 105.00 |   |

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

JARMAY ENTERPRISES PTE LTD  
18 BOON LAY WAY, TRADEHUB 21 #06-119  
SINGAPORE 609966

Attention : THE OWNER

Contact : 81806724 66590388 90903134

Estimate : ES006294

Date : 25/03/2018

Vehicle Num. : GBC7996R

Make/Model : TOYOTA HIACE-2013

Chassis/Eng# : JTFHT02P300125005/1KD2333952

Accident Date : 21/03/2018

Claim No. :

Reference :

Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

LABOUR :

REMOVE & REINSTALL TAIL GATE W/SCREEN GLASS  
TRANSFER TAILGATE COMPONENT TO NEW GATE  
RUST PROOFING TREATMENT  
SPRAY PAINT DAMAGED AREA AFFECTED  
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR  
CHASSIS FRAMES, AND CHANGE ALL NECESSARY PARTS

Labour Total S\$ :

1201  
601 180.00  
301 150.00  
4501 100.00  
1,000.00  
1,100.00 ?  
2,530.00

SingDollars : Seven Thousand Five Hundred Seventy-Six & Cents Thirty Only

Total S\$ : 7,576.30  
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun