

ASS. REC. BY:

REF: CS/FCI18005613/ Uqd3ⁿ²

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

FCI

Date/Time:

26/3/18 @ 4.45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLM 486 X

Insured:

SHC 2166G

at Workshop n/s:

Pegasus Trading

Tel:

6858 1846

of

51 Defu Lane 10

Policy No.:

D/18088936MFSH

Claim No.:

D18002423MFSH

Sum Insured:

Excess:

Make of Veh.:

(Client's Record)

D.O.A.:

21/3/2018

CA / REV / REP. / REV 24 HRS 'Ds'

H.O.D. Endorsement:

Date/Time:

9:37am @ 27/3/18

Person Contacted:

William

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 486 X-X

SHC 2166G - CS/AWA16007119/H/qbn2

D.O.A. 15/4/16

26/3/18 @ 4.48pm revised to Karen Tan by email.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLM 486 X*at Workshop m/s *Pujosus / an*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *2* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLM 486 X* Yr Regn: *3 1 17*Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or *Car*Make: *Toyota* c.c. *1496*Colour: *silver* A/C: Insured / Std / NI / NASp. Reading: *5-135-P* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *MHF829F-3702008128*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *195/50R16*

R: _____

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6* Rear *6*R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *24/3/18* D.O.I. *27/3/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/3/18 Confirmed L/S of 1200 with sum. (Red 6368.32, 73%)

RECEIVED 29 MAR 2018

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: *2**11/4/13* *hmm*☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format : *TP*Lump Sum / I.B.I. (\$) *1200*

130

50

25

205



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005613/Uqd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2166G	Veh. Inspected	SLM 486X
Policy No.		Coverage (\$)	0.00
Claim No.	D18002423MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	26/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/03/2018	Inspection Date
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002423MFSH

Date: 28 March 2018

Our Ref: CS/FCI18005613/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLM 486X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/03/2018 at the premises of M/s PEGASUS TRADING, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>1,568.32</u>
Revised Estimate Amount	: S\$ <u>1,200.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-03-2018	Our Ref No. D18002423MFSH
Accident Date	24-03-2018	Claim Type. Third Party
Insured Vehicle	SHC2166G	Third Party Vehicle. SLM486X
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236336)



PRI Documents



Close



PRI Header Details

Claim No	D18002423MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2166G	TP Vehicle No	SLM486X
PRI Recieved Date	26-03-2018 05:43:38 PM	Surveyor Appointed Date	26-03-2018 04:44:07 PM	Surveyor Accept Date	27-03-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 28 March 2018 4:48 PM
To: 'Claim Workflow System'; assignments
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002423MFSH/1
Attachments: CSFCI18005613Uqd3.pdf

Dear Karen,

Enclosed herewith preliminary advice of SLM 486X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 March 2018 9:39 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002423MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 26 March 2018 4:44 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002423MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 7200G

Vehicle Details

Vehicle No.: SLM486X
Vehicle to be Exported: No
Intended De-registration Date: 26 Mar 2018
Vehicle Make: TOYOTA
Vehicle Model: VIOS 1.5E CVT
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: 2NRX134631
Chassis No.: MHFB29F3702008128
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$12,946.00
Original Registration Date: 20 Mar 2017
First Registration Date: 20 Mar 2017
Transfer Count: 0
Actual ARF Paid: \$7,946.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Mar 2027
PARF Rebate Amount: \$5,959.00

Intended COE Rebate Details

COE Expiry Date: 19 Mar 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,101.00
COE Rebate Amount: \$44,959.00
Total Rebate Amount: \$50,918.00

The information contained herein is correct as at 26 Mar 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

No f Arthur
2/5/1200h
2dy.
27/3/18
Tah... off the...

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
539216
Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :
confirmed LKK
W Morris
LS \$1200

Quotation No : QO18/03-1227	Quotation Date : 26/03/2018	Terms : 30 DAYS
Vehicle No : SLM486X	Chassis No : MHFB29F3702008128	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: MS FIRST CAPITAL, VEHICLE NO: SHC2166G, DOA: 24.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER <i>np/2e</i>	1	504.9000	504.90
2	REAR BUMPER REINFORCEMENT <i>n</i>	1	379.2000	379.20
3	REAR BUMPER CLIP <i>nee</i>	6	4.3000	25.80
4	REAR BUMPER REFLECTOR <i>n1</i>	2	130.8000	261.60
5	REAR BUMPER SIDE RETAINER <i>0/534</i>	2	115.1000	230.20
6	REAR BUMPER SIDE HOLDER <i>n1</i>	2	22.3000	44.60
7	O/S REAR LAMP <i>n1</i>	1	375.8000	375.80
8	BOOTLID VIOS BADGE <i>nee</i>	1	44.1000	44.10
9	BOOTLID E BADGE <i>nee</i>	1	34.4000	34.40
10	BOOTLID CENTRE LOGO BADGE <i>nee</i>	1	59.8000	59.80
11	LESS 20% <i>25%</i>	1	-392.0800	-392.08
	REAR BUMPER PARKING SENSOR <i>1 set</i>	<i>shuttl</i>	450.0000	<i>200 S.N</i>
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.0000	<i>50</i>
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		120.0000	<i>60</i>
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		40.0000	<i>20</i>
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS. ADJUST AND REALIGN THE SAME.		550.0000	<i>220</i>
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		600.0000	<i>400</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's price is subject to final approval from Insurance Company

Sub Total
GST(7.00%)
Total (SGD)

1,568.32
109.78
1,678.10
3448.32

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Acknowledged by Repairer
Signature:
Date:

784.1
588.07
1538.07



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005613/Uqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2166G	Veh. Inspected	SLM 486X	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002423MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	26/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MHFB29F3702008128	Colour	SILVER	
Odometer	51358	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2018	Inspection Date	27/03/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 486X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	504.90	504.90
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	379.20	-
6	REAR BUMPER CLIP @\$4.30	NECESSARY	25.80	25.80
2	REAR BUMPER REFLECTOR @\$130.80	NOT NECESSARY	261.60	-
2	REAR BUMPER SIDE RETAINER @\$115.10	O/S BENT	230.20	115.10
2	REAR BUMPER SIDE HOLDER @\$22.30	NOT NECESSARY	44.60	-
1	O/S REAR LAMP	NOT NECESSARY	375.80	-
1	BOOTLID VIOS BADGE	NECESSARY	44.10	44.10
1	BOOTLID E BADGE	NECESSARY	34.40	34.40
1	BOOTLID CENTRE LOGO BADGE	NECESSARY	59.80	59.80
	LESS 20% DISCOUNT		-392.08	-
	LESS 25% DISCOUNT		-	-196.03
			1,568.32	588.07
SPECIAL NETT ITEMS				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	450.00	200.00
			450.00	200.00
LABOUR				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		120.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		40.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION. REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		550.00	220.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		600.00	400.00
			1,430.00	750.00
GRAND TOTAL			3,448.32	1,538.07



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00
---	--	--	----------

Report Ref No. CS/FCI18005613/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.