

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 198301460Z
INDEPENDENT MOVER PTE LTD
NO

SINGAPORE
TEL : FAX :
PH :
ATTN :

ESTIMATE BILL

Number : EB00004782
Date : 26/03/2018
Case No : AD00009633
Vehicle No : SJW3123U
Chassis : MR053BK4007003722
Year of Mfr 2006
Policy No 17-MU011725-R00
Model : TOYOTA CAMRY

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR FENDER RH	1.0	1,078.85	20	863.08
2	REAR BUMPER	1.0	927.40	20	741.92
3	REAR BUMPER RETAINER RH	1.0	75.48	20	60.38
4	REAR SHOCK ABSORBER RH	1.0	698.50	20	558.80
5	REAR KNUCKLE ARM RH	1.0	527.50	20	422.00
6	REAR LOWER ARM RH	1.0	495.31	20	396.25
7	REAR FENDER INNER SHIELD RH	1.0	188.60	20	150.88
8	REAR WINDSCREEN GLASS MOULDING	1.0	97.80	20	78.24
List Price - Parts Sub Total					3,271.55
9	REAR TYRE RH	1.0	380.00	0	380.00
10	WINDSCREEN SEALANT	2.0	24.00	0	48.00
Special Nett Price - Parts Sub Total					428.00
Parts Total					3,699.55
11	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
12	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
13	ANTI-RUST COATING	1.0	150.00	0	150.00
14	TO REMOVE & REFIT UNDERCARRIAGE	1.0	350.00	0	350.00
15	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
16	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
17	FOUR WHEEL ALIGNMENT	1.0	180.00	0	180.00
18	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	250.00	0	250.00
Labour 1 Sub Total					3,160.00
SINGAPORE DOLLARS : SEVEN THOUSAND THREE HUNDRED THIRTY-NINE AND CENTS SEVENTY-TWO ONLY			Less Excess		0.00
			SUBTOTAL		6,859.55
			GST 7.00%		480.17
			TOTAL		7,339.72

Date of accident : 23/03/2018 06:15 PM. Place : GEYLANG ROAD > LORONG 25 GEYLANG

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE