

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Joanne Yang

of

FCI

Date/Time:

26/3/18 @ 2:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 2489J

Insured:

SHD 4587G

at Workshop m/s:

Cheng Hoe Motor

Tel:

6755 6142

of

81k 1019 Yishun Ind Park A # 01-374

Policy No:

Claim No:

D18002396MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/3/2018

CA / REV / REP. / REV 24 HRS

lwp

27/3/18

H.O.D. Endorsement:

Date/Time:

4:16pm @ 26/3/18

Person Contacted:

wendy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SKW 2489J - X
	SHD 4587G - CS/FCI16001349/Kqb3c2
	D.O.A: 18/1/16
31/3/18	Email preli revised to FCI
10/5	83882.79 Confirm Ehd, (Recd 166197, 309)

ASS. REC. BY:

REF:

17021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

27/3

File pass to Catherine.

RECEIVED 10 MAY 2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 10/5- typist

Report Format:

CWS

Lump Sum / I.B.I. (\$

3882.79

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Veh No:

SKW 2489J

Yr Regn:

10.15

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Vios E

c.c.

1497

Colour

N. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

97148

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

M14F BT 9F3508036676

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

P2144

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

23/3/18

D.O.I.

26/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

140

50

50 + 50

23

313



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005617/Kvd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4587G	Veh. Inspected	SKW 2489J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002396MFSH	Excess (\$)	0.00	
Assign From	CWS (JOANNE YONG)	Assign Date	26/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/03/2018	Inspection Date		
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002396MFSH

Our ref: CS/FCI18005617/Kvd3

Date : 31/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKW 2489J


We thank for your instruction on 26/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/3/2018 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,544.76
Revised Estimate Amount	: S\$3,315.16
"Check" Items Amount	: S\$1,570.59
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	23-03-2018	Our Ref No. D18002396MFSH
Accident Date	23-03-2018	Claim Type. Third Party
Insured Vehicle	SHD4587G	Third Party Vehicle. SKW2489J
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	664812001/0	Fax No. 64821296
Survey Type	WITHOUT PREJUDICE; ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rate) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc: TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236301)



PRI Documents



Close



PRI Header Details

Claim No	D18002396MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHENG H
Workshop Name	CHENG HOE MOTOR PTE LTD (Contact Person : JUNE)	Survey Location & Contact Details	BLK 1019 YISHUN IND. PARK A #01-374 Mobile: 0 , Phone: 664812001 , Fax: 64821296 EmailId: CHMOTOR@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4587G	TP Vehicle No	SKW2489J
PRI Recieved Date	23-03-2018 09:58:00 PM	Surveyor Appointed Date	26-03-2018 02:11:38 PM	Surveyor Accept Date	26-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-03-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

[Upload Multiple Documents](#)

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Saturday, 31 March 2018 11:31 AM
To: 'Claim Workflow System'
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002396MFSH/1, SKW 2489J
Attachments: SKW 2489J PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKW 2489J
Date of survey: 26/3/2018

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 26 March 2018 4:19 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002396MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 26 March 2018 2:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002396MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0743E
Vehicle Details	
Vehicle No.:	SKW2489J
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E GRADE 1.5 A/T
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	1NZZ149344
Chassis No.:	MHFBT9F3506036676
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,410.00
Original Registration Date:	23 Oct 2015
First Registration Date:	23 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$15,410.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2025
PARF Rebate Amount:	\$11,557.00
Intended COE Rebate Details	
COE Expiry Date:	22 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,001.00
COE Rebate Amount:	\$42,440.00
Total Rebate Amount:	\$53,997.00

The information contained herein is correct as at 23 Mar 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKW 2489J

TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 23/03/2018

TP Veh Reg No: SHD4587G

Estimate No: ES1890300/YISHUN

Date: 26 Mar 2018

Policy No: 5075100485-02

Veh Reg No: SKW2489J

Make/Model: TOYOTA VIOS GRADE 1.5A/T

Chassis No: MHFBT9F3506036676

Engine No: 1NZZ149344

Reg. Date: 23/10/2015

Not Authorised

Running Repair

Estimate Repair Cost to Vehicle No :SKW2489J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	427.90	1 PC	Bu 427.90	—
2 FRONT BUMPER RH SIDE RETAINER	54.74	1 PC	Diy 54.74	—
3 FRONT BUMPER RH FOG LAMP	248.20	1 PC	myer 248.20	—
4 FRONT BUMPER RH FOG LAMP GARNISH	58.53	1 PC	Bu 58.53	X
5 FRONT BUMPER REINFORCEMENT	372.00	1 PC	R 372.00	X
6 FRT BUMPER LOGO	60.70	1 PC	me 60.70	—
7 FRONT BUMPER MOULDINGS	75.50	2 PCS	me 151.00	—
8 FRONT BUMPER CLIPS	3.89	8 PCS	me 31.12	—
9 FRONT GRILLE CLIPS	3.89	2 PCS	me 7.78	—
10 RH HEADLAMP	398.80	1 PC	me 398.80	—
11 FRONT RH FENDER	612.50	1 PC	cm 612.50	—
12 FRONT RH FENDER INNER SHIELD	275.40	1 PC	Bu 275.40	—
13 FRONT RH FENDER INNER SHIELD CLIPS	3.50	6 PCS	me 21.00	—
14 FRONT BUMPER CENTRE LOWER GRILLE	282.50	1 PC	Diy 282.50	—
15 FRONT BUMPER RH UNDER COVER	139.20	1 PC	me 139.20	X
16 FRONT BUMPER TOW COVER	40.10	1 PC	my 40.10	—
17 FRT BUMPER RH UNDER COVER CLIPS	3.89	6 PCS	me 23.34	—
18 FRONT RH SHOCK ABSORBER	375.30	1 PC	Bu 375.30	X
19 FRONT RH KNUCKLE ARM	544.70	1 PC	me 544.70	X
20 FRONT RH WHEEL BEARING	488.20	1 PC	me 488.20	X
			4,613.01	
		Less 25%	1,153.25	3,459.76
Special Net				
21 FRONT NUMBER PLATE	35.00	1 PC	Bu 35.00	—
22 FRT RH SPORT RIM	380.00	1 PC	me 380.00	300.00
			415.00	415.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 23/03/2018

TP Veh Reg No: SHD4587G

Estimate No: ES1890300/YISHUN

Date: 26 Mar 2018

Policy No: 5075100485-02

Veh Reg No: SKW2489J

Make/Model: TOYOTA VIOS GRADE 1.5A/T

Chassis No: MHFBT9F3506036676

Engine No: 1NZZ149344

Reg. Date: 23/10/2015

Estimate Repair Cost to Vehicle No :SKW2489J

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
23 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT RH FENDER INNER SHIELD,FOG LAMPS,TO KNOCK & REPAIR FRT SUPPORT PANEL,FRT RH FENDER INNER PANEL & REALIGN THE SAME	600.00	1 LA	600.00	500
24 REMOVE & REFIX FRT RH UNDER CARRIAGE	180.00	1 LA	180.00	100
25 PUTTY & RESPRAY ON FRT SUPPORT PANEL,BONNET FRT RH FENDER & INNER PANEL,FRT BUMPER,GRILLE & ALL AFFECTED AREAS	800.00	1 LA	800.00	600
26 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	-
27 RUSTPROOFING	30.00	1 LA	30.00	-
			1,670.00	1,670.00

Total S\$ 5,544.76

Add GST @ 7% 388.13

Total Amount Payable S\$ 5,932.89

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005617/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4587G	Veh. Inspected	SKW 2489J	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002396MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	26/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS E (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MHFBT9F3506036676	Colour	METALLIC RED	
Odometer	97148	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	FALKEN	7 mm	
L/H Front Tyre	185/60 R15	FALKEN	7 mm	
R/H Rear Tyre	185/60 R15	FALKEN	7 mm	
L/H Rear Tyre	185/60 R15	FALKEN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/03/2018	Inspection Date	26/03/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 2489J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	427.90	427.90
1	FRONT BUMPER RH SIDE RETAINER	DISTORTED	54.74	54.74
1	FRONT BUMPER RH FOG LAMP	MTG CRACKED	248.20	248.20
1	FRONT BUMPER RH FOG LAMP GARNISH	SERVICEABLE	58.53	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	372.00	-
1	FRT BUMPER LOGO	NECESSARY	60.70	60.70
2	FRONT BUMPER MOULDINGS @\$75.50	NECESSARY	151.00	151.00
8	FRONT BUMPER CLIPS @\$3.89	NECESSARY	31.12	31.12
2	FRONT GRILLE CLIPS @\$3.89	NECESSARY	7.78	7.78
1	RH HEADLAMP	CUT	398.80	398.80
1	FRONT RH FENDER	CRACKED	612.50	612.50
1	FRONT RH FENDER INNER SHIELD	BUCKLED	275.40	275.40
6	FRONT RH FENDER INNER SHIELD CLIPS @\$3.50	NECESSARY	21.00	21.00
1	FRONT BUMPER CENTRE LOWER GRILLE	DISTORTED	282.50	282.50
1	FRONT BUMPER RH UNDER COVER	SERVICEABLE	139.20	-
1	FRONT BUMPER TOW COVER	MISSING	40.10	40.10
6	FRONT BUMPER RH UNDER COVER CLIPS @\$3.89	NECESSARY	23.34	23.34
1	FRONT RH SHOCK ABSORBER	BENT	375.30	375.30
1	FRONT RH KNUCKLE ARM	SERVICEABLE	544.70	-
1	FRONT RH WHEEL BEARING	NOT NECESSARY	488.20	-
	LESS 25% DISCOUNT		-1,153.25	-752.59
			3,459.76	2,257.79
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
1	FRT RH SPORT RIM (SN)	DENTED	380.00	300.00
			415.00	335.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT RH FENDER INNER SHIELD,FOG LAMPS,TO KNOCK & REPAIR FRT SUPPORT PANEL,FRT RH FENDER INNER PANEL & REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		600.00	500.00
	REMOVE & REFIX FRT RH UNDER CARRIAGE.		180.00	100.00
	PUTTY & RESPRAY ON FRT SUPPORT PANEL,BONNET,FRT RH FENDER & INNER PANEL,FRT BUMPER,GRILLE & ALL AFFECTED AREAS.		800.00	600.00
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		60.00	60.00
	RUSTPROOFING.		30.00	30.00
			1,670.00	1,290.00
	GRAND TOTAL		5,544.76	3,882.79
RECOMMENDED COST OF REPAIRS				3,882.79

Report Ref No. CS/FCI18005617/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.