

FORMING

ASS. REG. NY

REF: CS/FCI/800 5620/ 4/13/18

SURVEY

Marcus

ASSIGNMENT (Office)

From (Person):

Serene Ter

FCI

Date/Time 26/03/18 @ 3:11pm

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SFV 34704

Insured:

SHC1499C

at Workshop no:

Torque 5

Tel:

91478841

of

No. 8 Koki Bk + Ave 4 premier @ 01-50

Policy No:

Claim No:

D18002387 MFSH

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A

22/3/18

27/3/18

CA / REV / REP. / REV 24 HRS ^{1 up}

H.O.D. Endorsement

Date/Time:

4:14pm @ 26/3/18

Person Contacted:

Stephanie

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFV 34704 - NA/11/18/05482/13

D.O.A 22/3/18

SHC1499C - NA/11/18/05482/13

D.O.A 22/3/18

243-

Report via email pred.

REF: FCI

ASSIGNMENT

From: Date: 27/3/18

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFV 34704

at Workshop m/s

of No. 8 kaki Bkt Ave 4 Premier # 01-50

Insured:

Policy No.

Claims No.

Sum Insured:

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}30/4/2020
Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFV 34704

Yr Regn:

6 05

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M /

Make:

Toyota v.05

C.C.

1497

Colour:

blue

A/C

Insured / Std / NI / NA

Sp. Reading

513958

T/Radio: Insured / Std / NI / NA

Eng. No:

C. No:

MR053HY4204134588

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

22/3/18

D.O.I.

27/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date: Time:

Action / Instruction

LTA 13/19

2 yrs. Int.

29/3/18 contact d/s & 4000 w/c stephane. (Red 14140.70 77%)

RECEIVED 10 APR 2018

RECEIVED 03 APR 2018

Date/Time: File Pass to?



Preli. Report

3/4 Typist



Final Report

Date/Time: File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

-

Survey Fee:

Transporter:

J...S + PC...S

Press:

Other:

TOTAL

Add Fee:



Site Insp: \$



Interview: \$



Tech. Insp: \$



Refresh: \$

Report Format:

TP

Lump Sum / I.B.I. \$

4000

8x15

170 + 120

50

52

282

ACCIDENT STATEMENT

ACCIDENT DATE: 22/03/2018 (DD/MM/YYYY), TIME: 19:54 (HH:MM)

LOCATION: TPE towards PIE before KPE/ECF Exit

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SFV 34704
b) INSURANCE COMPANY: AG
c) POLICY NUMBER: 0100531357
d) POLICY TYPE: COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT
e) MAKE & MODEL: Toyota Vios
f) TYPE: (SALOON) / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS
g) VEHICLE CATEGORY: (PRIVATE) / COMMERCIAL / MOTORCYCLE
h) PURPOSE OF USING AT ACCIDENT TIME: for use
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM) REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: Chang Lam Chiang (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: S01853936 CONTACT: 98635196
c) ADDRESS: Not Bk 712 Bedok Reservoir Road
#02-3928 Singapore 4720 470712

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: _____ (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: _____ CONTACT: _____
c) ADDRESS: _____

*d) DATE OF BIRTH: 17/05/1947 (DD/MM/YYYY)

e) OCCUPATION: (INDOOR OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: 48 years

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: _____

5. a) WEATHER CONDITION: (CLEAR) RAINING / OTHERS _____
b) ROAD SURFACE: (DRY) WET / OTHERS _____

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: SHC 1499 C MODEL: Hyundai
b) DRIVER'S NAME: Muhammad Firdaus
c) NRIC/FIN/PASSPORT: _____ CONTACT: 93384394

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: SLZ 9969 S MODEL: Hyundai Elantra
e) DRIVER'S NAME: Lee Teck Boon
f) NRIC/FIN/PASSPORT: _____ CONTACT: 98297271

LKK

Ubi Industrial Park 2


Unit 25, 51 Ubi Ave

S(408933)

Email = REPORTINS@
TOPQUE5.com
Fax = 6452 4584

SKETCH PLAN

TPE towards PIE before KPE/ECF Exit



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, at the stated venue,

I vehicle 'A' SFV 34704 was driving straight on my lane. The vehicle in front of me slow down, so I followed suit at one car length distance. Suddenly I felt an impact on my rear portion. Vehicle 'B' SHC 1499C collided onto my rear portion. I got down to check, I was involved in a 3 'cars' collusion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

[Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 5393G

Vehicle Details

Vehicle No.: SFV3470U

Vehicle to be Exported: No

Intended De-registration Date: 27 Mar 2018

Vehicle Make: TOYOTA

Vehicle Model: VIOS 1.5E M

Primary Colour: Blue

Manufacturing Year: 2005

Engine No.: 1NZX251420

Chassis No.: MR053HY4204134588

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$11,559.00

Original Registration Date: 01 Jun 2005

First Registration Date: 01 Jun 2005

Transfer Count: 0

Actual ARF Paid: \$12,715.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$31,361.00

COE Rebate Amount: \$13,119.00

Total Rebate Amount: \$13,119.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 Mar 2018

OK

- Anonymous Dislike function - Time for review?
- Uber/Grab issues and charges
- Liverpool 2017/18: YNWA with Klopp

toyota vios Price Range Depreciation > 10 year(s) Vehicle Type Submit

Advanced Search

Home > Used Cars > Dickson Automobile > Toyota Vios 1.5A E (COE till 08/2020)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Leasing

CL LEASING
YOUR FAVORITE CAR LEASING
OPTION IN SINGAPORE
6768 7117 8728 5000 8728 8000

OCBC CYCLE
JOIN IN
ON THE FUN
TODAY!
Sign up now

Toyota Vios 1.5A E (COE till 08/2020)

Overview Financial Accessories Similar Research Photos Map



DICKSON AUTOMOBILE PTE LTD
A member of DICKSON AUTO GROUP

Established since 1988



Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$19,800	2
Depreciation	\$8,210 /yr	2
Reg Date	24-Aug-2005 (2yrs 4mths 27days COE left)	2
Manufactured	2005	2
Mileage	-	2
Transmission	Auto	2
Engine Cap	1,497 cc	2
Road Tax	\$889 /yr	2
Power	80.0 kW (107 bhp) View specs of the Toyota Vios (2003-2007)	2
Features	1.5L DOHC VVT-i Engine, Auto Transmission, SRS Airbags, ABS, EBD.	2
Accessories	Sport Rims, Bodykit, Factory Fitted Audio System, Electrical Adjustable Side Mirrors, Upholstery 2 Tone Leather Seats.	2
Description	Low Monthly At \$400 Plus Only! 2 Careful Owner! Very Low Mileage! Extremely Reliable And Fuel Efficient Yet Affordable! Well Kept By Previous Owner In Superb Condition, For You To View And Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Come To Our Aircon Showroom To Appreciate It In Pristine Condition Today!	2
COE	\$31,398	2
OMV	\$12,343	2
ARF	\$13,578	2
Dereg Value	\$15,140 as of today (change)	2
No. of Owners	2	2
Type of Veh	Mid-Size Sedan	2
Category	COE Car	2
Availability	Available	2



Seller Information

Company	Dickson Automobile • dealer's pricelist • 129 vech sold 191 vech available
Address	31 Kaki Bukit Road 3 #01-01 Search cars nearby this location
Location	Techlink
Website	dicksonauto.com.sg
Office No	68447667
Contact Person(s)	Frankie Tan 96213635 Ricky Eng 91853390 Eric Lee 91827304

Add to Shortlist Add to Compare Add a Note



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



toyota vios

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Direct Owners » Toyota Vios 1.5A E (COE till 10/2020)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing



Earn more
Healthpoints
when you
sign up
as a new

HealthHub
member



Toyota Vios 1.5A E (COE till 10/2020)

Overview Financial Accessories Similar Research Photos Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

CAR DETAILS

Price **\$18,500**

Depreciation **\$7,160 /yr**

Reg Date **26-Oct-2005**
(2yrs 6mths 28days COE left)

Manufactured **2005**

Mileage **-**

Transmission **Auto**

Engine Cap **1,497 cc**

Road Tax **\$889 /yr**

Power **80.0 kW (107 bhp)**
[View specs of the Toyota Vios \(2003-2007\)](#)

Curb Weight **1,020 kg**

Features **1.5L VVT-I DOHC Engine. Fuel Consumption 15 To 16Km/L. Genuine Mileage**

Accessories **Dvd Player Install With Camera. Leather Seats. Wear And Tear Replaced**

Description **Genuine Mileage. Family Is Welcoming A New Member, Require A Bigger Car. Car Is In Good Condition. Drive Till Coe Ends.**

COE **\$28,399**

OMV **\$12,343**

ARF **\$13,578**

Dereg Value **\$14,674 as of today (change)**

No. of Owners **3**

Type of Veh **Mid-Size Sedan**

Category **COE Car, Direct Owner Sale**

Availability **Available**

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 07-Feb-2018 | Last Updated on: 22-Mar-2018

Tags: Toyota Vios, 2005 Toyota Vios, Toyota Vios, Used Toyota



100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Preferred Viewing Area

Seller Information

Contact Person(s) **Serene**

Contact No. **92988747**

Enquiry [Contact Seller](#)

USEFUL FORMS

- Indemnity form
- Sales agreement
- Receipt
- Hand-over form
- M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Make sure of this car condition with STA Evaluation.
Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.
Free Valuation



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

NOT Authorized
name
2/5 #4000/1
6 day. Limited Repair

Torque 5 Pte Ltd

27/3/18

Take the After Repair

ESTIMATION REPORT

Vehicle No : SFV3470U
Make & Model : TOYOTA, VIOS 1.5E M, MR053HY4204134588
Year of : 2005
Manufacture

Estimation No. : E18030066
DOA : 22/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bootlid <i>but/suc</i>	1.00	680.80	680.80 ✓
2	Rear bootlid hinge (LH) <i>n</i>	1.00	97.40	97.40 X
3	Rear bootlid hinge (RH) <i>n</i>	1.00	97.40	97.40 X
4	Rear bootlid support garnish (LH) <i>11</i>	1.00	305.40	305.40 X
5	Rear bootlid support garnish (RH) <i>11</i>	1.00	305.40	305.40 X
6	Rear bootlid lock <i>7m1</i>	1.00	82.10	82.10 ✓
7	Rear bootlid weather strip <i>7m1</i>	1.00	86.10 0.00	0.00 ✓
8	Rear bootlid logo <i>me</i> <i>38.50</i>	1.00	69.90	69.90 ✓
9	Rear bootlid emblem - Vios <i>me</i> <i>30.50</i>	1.00	62.30	<u>62.30</u> ✓
10	Rear bootlid emblem - 1.5E <i>me</i> <i>31.20</i>	1.00	69.90	<u>69.90</u> ✓
11	Rear bootlid emblem - VVT-i <i>me</i> <i>36.50</i>	1.00	72.30	<u>72.30</u> ✓
12	Rear bootlid outer handle <i>11</i>	1.00	192.70	192.70 X
13	Rear bootlid key lock <i>11</i>	1.00	68.10	68.10 4
14	Rear number plate lamp (LH) <i>11</i>	1.00	136.00	136.00 X
15	Rear number plate lamp (RH) <i>11</i>	1.00	136.00	136.00 X
16	Rear bumper <i>D.S</i> <i>329.10</i>	1.00	684.20	<u>684.20</u> ✓
17	Rear bumper clip <i>me</i>	10.00	5.00	50.00 ✓
18	Rear bumper retainer (LH) <i>34</i>	1.00	69.20	69.20 ✓
19	Rear bumper retainer (RH) <i>34</i>	1.00	69.20	69.20 ✓
20	Rear bumper bracket (LH) <i>ns</i>	1.00	89.90	89.90 X
21	Rear bumper bracket (RH) <i>ns</i>	1.00	89.90	89.90 X
22	Rear bumper reinforcement <i>ns</i>	1.00	0.00	0.00 X
23	Rear bumper sponge <i>ns</i>	1.00	0.00	0.00 X
24	Tail lamp (LH) <i>me</i> <i>320.50</i>	1.00	382.70	382.70 ✓
25	Tail lamp (RH) <i>me</i> <i>320.50</i>	1.00	382.70	382.70 ✓

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFV3470U
Make & Model : TOYOTA, VIOS 1.5E M, MR053HY4204134588
Year of Manufacture : 2005

Estimation No. : E18030066
DOA : 22/03/2018

No	Description	Qty	U/P	Amt	
26	Tail lamp clip (LH) 11	2.00	5.00	10.00	X
27	Tail lamp clip (RH) 11	2.00	5.00	10.00	X
28	Tail lamp bracket (LH) 11	1.00	138.00	138.00	X
29	Tail lamp bracket (RH) 11	1.00	138.00	138.00	X
30	Tail lamp panel (LH) 12	1.00	286.10	286.10	X
31	Tail lamp panel (RH) 34	1.00	286.10	286.10	/
32	Rear fender (LH) - repair 12	1.00	1,247.50	1,247.50	X
33	Rear fender (RH) - repair 12	1.00	1,247.50	1,247.50	X
34	Rear fender cowling (LH) 11	1.00	86.20	86.20	X
35	Rear fender cowling (RH) 11	1.00	86.20	86.20	X
36	Rear fender cowling clip (LH) 11	10.00	5.00	50.00	X
37	Rear fender cowling clip (RH) 11	10.00	5.00	50.00	X
38	Rear fender inner trim (LH) 11	1.00	724.10	724.10	X
39	Rear fender inner trim (RH) 11	1.00	724.10	724.10	X
40	Rear fender inner trim clip (LH) 11	10.00	5.00	50.00	X
41	Rear fender inner trim clip (RH) 11	10.00	5.00	50.00	X
42	Rear end panel 306.00	1.00	731.00	731.00	/
43	Rear end panel top garnish 721	1.00	192.50	192.50	/
44	Rear end panel top garnish clip 11	10.00	5.00	50.00	X
45	Spare wheel panel 12	1.00	899.60	899.60	X
46	Spare wheel panel top board 10.1 126.10	1.00	311.50	311.50	/
47	Spare wheel panel sponge 11	1.00	0.00	0.00	X
48	Exhaust pipe 12	1.00	481.20	481.20	X
49	Exhaust pipe mounting 11	2.00	89.20	178.40	X
50	Exhaust pipe gasket 11	1.00	49.20	49.20	X

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SFV3470U
Make & Model : TOYOTA, VIOS 1.5E M, MR053HY4204134588
Year of Manufacture : 2005

Estimation No. : E18030066
DOA : 22/03/2018

No	Description	Qty	U/P	Amt
			Amt	S\$
				12,270.70
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$
				12,270.70

Section: Special Nett Items

51	Rear bootlid spoiler	1	1,000.00	1,000.00	X
52	Rear number plate	50	50.00	50.00	20
53	Rear bumper reverse sensor	300	300.00	300.00	200
54	Rear bumper mudflap (LH)	1	300.00	300.00	X
55	Rear bumper mudflap (RH)	1	300.00	300.00	X
56	Rear fender sealant	1	80.00	80.00	X
57	Rear end panel sealant	1	80.00	80.00	50
			Amt	S\$ 2,110.00	
			Discount (0.00%)	S\$ 0.00	
			Subtotal	S\$ 2,110.00	

Section: Labour Items

58	To R&R accident affected areas	1.00	1,500.00	1,500.00	800
59	To putty & respray accident affected areas	1.00	1,300.00	1,300.00	1000
60	To rust proof accident affected areas	1.00	60.00	60.00	50
61	To R&R rear boot mechanism	1.00	80.00	80.00	60
62	To R&R rear luggage compartment	1.00	200.00	200.00	80
63	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00	50
64	To R&R exhaust pipe assy	1.00	180.00	180.00	60
65	To check wiring layout of tail lamp	1.00	80.00	80.00	20
66	To check for water seepage	1.00	100.00	100.00	X
67	To do wheel alignment	1.00	180.00	180.00	X

Continue on next page...

2390



Vehicle No : SFV3470U
Make & Model : TOYOTA,VIOS 1.5E M,MR053HY4204134588
Year of Manufacture : 2005

Estimation No. : E18030066
DOA : 22/03/2018

No	Description	Qty	U/P	Amt
			Amt	S\$ 3,760.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 3,760.00

[illegible]

List Items Subtotal	S\$ 12,270.70
Special Nett Items Subtotal	S\$ 2,110.00
Labour Items Subtotal	S\$ 3,760.00
Total	S\$ 18,140.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FC118005620/Utd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 1499C	Veh. Inspected	SFV 3470U	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002387MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	26/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTAVIOS (M)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	MR053HY4204134588	Colour	BLUE	
Odometer	513958	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	YOKOHAMA	6 mm	
L/H Front Tyre	175/70 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	175/70 R14	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2018	Inspection Date	27/03/2018	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 3470U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOTLID	BENT / BUCKLED	680.80	680.80
1	REAR BOOTLID HINGE (LH)	TO REPAIR SEE LABOUR	97.40	-
1	REAR BOOTLID HINGE (RH)	TO REPAIR SEE LABOUR	97.40	-
1	REAR BOOTLID SUPPORT GARNISH (LH)	NOT NECESSARY	305.40	-
1	REAR BOOTLID SUPPORT GARNISH (RH)	NOT NECESSARY	305.40	-
1	REAR BOOTLID LOCK	TWISTED	82.10	82.10
1	REAR BOOTLID WEATHERSTRIP	TWISTED	86.10	86.10
1	REAR BOOTLID LOGO	NECESSARY	69.90	38.50
1	REAR BOOTLID EMBLEM -VIOS	NECESSARY	62.30	30.90
1	REAR BOOTLID EMBLEM -1.5E	NECESSARY	69.90	31.20
1	REAR BOOTLID EMBLEM -VVT-I	NECESSARY	72.30	38.50
1	REAR BOOTLID OUTER HANDLE	NOT NECESSARY	192.70	-
1	REAR BOOTLID KEY LOCK	NOT NECESSARY	68.10	-
1	REAR NUMBER PLATE LAMP (LH)	NOT NECESSARY	136.00	-
1	REAR NUMBER PLATE LAMP (RH)	NOT NECESSARY	136.00	-
1	REAR BUMPER	DISTORTED	684.20	329.10
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER (LH)	BENT	69.20	69.20
1	REAR BUMPER RETAINER (RH)	BENT	69.20	69.20
1	REAR BUMPER BRACKET (LH)	NO SUCH PARTS	89.90	-
1	REAR BUMPER BRACKET (RH)	NO SUCH PARTS	89.90	-
1	REAR BUMPER REINFORCEMENT (NPA)	NO SUCH PARTS	-	-
1	REAR BUMPER SPONGE (NPA)	NO SUCH PARTS	-	-
1	TAIL LAMP (LH)	NECESSARY	382.70	320.50
1	TAIL LAMP (RH)	CRACKED	382.70	320.50
2	TAIL LAMP CLIP (LH) @\$5.00	NOT NECESSARY	10.00	-
2	TAIL LAMP CLIP (RH) @\$5.00	NOT NECESSARY	10.00	-
1	TAIL LAMP BRACKET (LH)	NOT NECESSARY	138.00	-
1	TAIL LAMP BRACKET (RH)	NOT NECESSARY	138.00	-

Report Ref No. CS/FCI18005620/Utd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL LAMP PANEL (LH)	TO REPAIR SEE LABOUR	286.10	-
1	TAIL LAMP PANEL (RH)	BENT	286.10	286.10
1	REAR FENDER (LH)	TO REPAIR SEE LABOUR	1,247.50	-
1	REAR FENDER (RH)	TO REPAIR SEE LABOUR	1,247.50	-
1	REAR FENDER COWLING (LH)	NOT NECESSARY	86.20	-
1	REAR FENDER COWLING (RH)	NOT NECESSARY	86.20	-
10	REAR FENDER COWLING CLIP (LH) @\$5.00	NOT NECESSARY	50.00	-
10	REAR FENDER COWLING CLIP (RH) @\$5.00	NOT NECESSARY	50.00	-
1	REAR FENDER INNER TRIM (LH)	NOT NECESSARY	724.10	-
1	REAR FENDER INNER TRIM (RH)	NOT NECESSARY	724.10	-
10	REAR FENDER INNER TRIM CLIP (LH) @\$5.00	NOT NECESSARY	50.00	-
10	REAR FENDER INNER TRIM CLIP (RH) @\$5.00	NOT NECESSARY	50.00	-
1	REAR END PANEL	BADLY DENTED	731.00	731.00
1	REAR END PANEL TOP GARNISH	TWISTED	192.50	192.50
10	REAR END PANEL TOP GARNISH CLIP @\$5.00	NOT NECESSARY	50.00	-
1	SPARE WHEEL PANEL	TO REPAIR SEE LABOUR	899.60	-
1	SPARE WHEEL PANEL TOP BOARD	TORN	311.50	126.10
1	SPARE WHEEL PANEL SPONGE (NPA)	NOT NECESSARY	-	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	481.20	-
2	EXHAUST PIPE MOUNTING @\$89.20	NOT NECESSARY	178.40	-
1	EXHAUST PIPE GASKET	NOT NECESSARY	49.20	-
	LESS 25% DISCOUNT		-	-870.08
			12,356.80	2,610.22
	SPECIAL NETT ITEMS			
1	REAR BOOTLID SPOILER (SN)	TO REPAIR SEE LABOUR	1,000.00	-
1	REAR NUMBER PLATE (SN)	SCRATCHED	50.00	20.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR BUMPER MUDFLAP (LH) (SN)	NOT FITTED	300.00	-
1	REAR BUMPER MUDFLAP (RH) (SN)	NOT FITTED	300.00	-

Report Ref No. CS/FCI18005620/Utd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
			2,110.00	270.00
	LABOUR			
	TO R&R ACCIDENT AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR BOOTLID HINGE (LH),REAR BOOTLID HINGE (RH),TAIL LAMP PANEL (LH),REAR FENDER (LH) ,REAR FENDER (RH), SPARE WHEEL PANEL ,EXHAUST PIPE AND REAR BOOTLID SPOILER.		1,500.00	800.00
	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS.		1,300.00	1,000.00
	TO RUST PROOF ACCIDENT AFFECTED AREAS.		60.00	50.00
	TO R&R REAR BOOT MECHANISM .		80.00	60.00
	TO R&R REAR LUGGAGE COMPARTMENT .		200.00	80.00
	TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION.		80.00	50.00
	TO R&R EXHAUST PIPE ASSY.		180.00	60.00
	TO CHECK WIRING LAYOUT OF TAIL LAMP .		80.00	20.00
	TO CHECK FOR WATER SEEPAGE .	NOT NECESSARY	100.00	-
	TO DO WHEEL ALIGNMENT .	NOT NECESSARY	180.00	-
			3,760.00	2,120.00
GRAND TOTAL			18,226.80	5,000.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/FCI18005620/Utd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.