

RETAIL PRICE LIST
Effective as of 19 July 2016



MODEL	ENGINE	POWER (bhp)	TORQUE (Nm)	Fuel Consumption (combined) litres/100 km	CO2 Emission (combined) g/km	RRP	CEVS (rebate) or surcharge from July '15 onwards	Nett Price after CEVS (rebate) / surcharge
AUDI A1 Sportback								
A1	1.0 TFSI S tronic	95	100	4.4	102	S\$ 132,850	(15,000)	S\$ 117,850
AUDI S3 / RS3 Sportback								
A3	1.4 TFSI S tronic (Attraction)	125	200	5.1	118	S\$ 144,800	(10,000)	S\$ 134,800
RS3	2.5 TFSI qu S tronic	367	460	8.2	182	S\$* 282,800	S\$* 8,000	S\$* 287,800
AUDI A3 / S3 Sedan								
A3	1.4 TFSI S tronic (Attraction)	125	200	5.0	116	S\$ 147,800	(10,000)	S\$ 137,800
A3	1.4 TFSI S tronic (Ambiente Plus)	125	200	4.9	114	S\$* 169,750	(10,000)	S\$ 159,750
AUDI A3 Cabriolet								
A3	1.4 TFSI S tronic (Attraction)	125	200	5.3	121	S\$ 184,500	(8,000)	S\$ 176,500
AUDI A4 (NEW)								
A4	1.4 TFSI S tronic	150	250	5.2	118	S\$ 178,000	(10,000)	S\$ 168,000
A4	1.4 TFSI S tronic (Design)	150	250	5.3	122	S\$ 183,280	(5,000)	S\$ 178,280
A4	2.0 TFSI qu S tronic (Design)	252	370	6.2	141	S\$ 236,200	-	S\$ 236,200
AUDI A4 / RS4 Avant								
A4	1.4 TFSI S tronic (New)	150	250	5.6	128	S\$ 187,400	(5,000)	S\$ 182,400
A4	2.0 TFSI qu S tronic (Design) (New)	252	370	6.5	148	S\$ 245,600	-	S\$ 245,600
A4	2.0 TFSI mu (VVT)	225	350	6.0	148	S\$* 217,750	-	S\$* 217,750
AUDI A5 / S5 Cabriolet								
A5	2.0 TFSI qu S tronic (NAV) (MY'15)	225	350	6.9	158	S\$* 294,450	-	S\$* 294,450
AUDI A6								
A6	1.8 TFSI S tronic (NAV)	190	320	5.7	133	S\$* 225,538	(8,000)	S\$* 220,538
A6	2.0 TFSI S tronic (NAV)	252	375	5.9	137	S\$ 243,488	-	S\$ 243,488
A6	3.0 TFSI qu S tronic	333	440	7.6	177	S\$ 352,900	-	S\$ 352,900
AUDI A6 / RS6 Avant								
A6	1.8 TFSI S tronic (NO NAV)	190	320	5.9	137	S\$* 238,600	-	S\$* 238,600
A6	3.0 TFSI qu S tronic	333	440	7.8	182	S\$ 364,400	-	S\$ 364,400
RS6	4.0 TFSI qu tp	560	700	9.8	223	S\$ 524,230	15,000	S\$ 539,230
AUDI A7 Sportback								
A7 (P)	2.0 TFSI S tronic	252	370	5.8	137	S\$ 302,350	-	S\$ 302,350
A7 (P)	3.0 TFSI qu S tronic	333	440	7.6	176	S\$ 373,150	-	S\$ 373,150
AUDI A8								
A8L (P)	3.0 TFSI qu tp	318	440	7.3	184	S\$* 412,800	-	S\$* 412,800
A8L (P)	4.0 TFSI qu tp	435	600	8.2	218	S\$* 512,650	15,000	S\$* 527,650
S8 (P)	4.0 TFSI qu tp	520	680	8.8	225	S\$* 652,900	15,000	S\$* 667,900
AUDI Q3								
Q3	1.4 TFSI S tronic	150	250	6.0	139	S\$ 186,250	-	S\$ 186,250
Q3	2.0 TFSI qu S tronic (Design)	180	320	6.7	165	S\$ 195,700	-	S\$ 195,700
AUDI Q5 / SQ5								
Q5	2.0 TFSI qu tp	180	320	7.5	175	S\$* 203,350	-	S\$* 203,350
Q5	2.0 TFSI qu tp	230	350	7.4	172	S\$* 238,800	-	S\$* 238,800
SQ5	3.0 TFSI qu tp	354	475	8.7	202	S\$* 297,950	10,000	S\$* 307,950
AUDI Q7								
Q7	2.0 TFSI qu tp (NEW)	252	370	7.4	172	S\$ 296,000	-	S\$ 296,000
Q7	3.0 TFSI qu tp (NEW)	333	440	7.9	183	S\$ 353,400	-	S\$ 353,400
AUDI TT Coupe								
TT	2.0 TFSI qu S tronic	230	370	6.4	149	S\$ 252,450	-	S\$ 252,450
AUDI TT Roadster								
TT	2.0 TFSI qu S tronic	230	370	6.7	154	S\$ 257,600	-	S\$ 257,600
AUDI R8 Coupe (NEW)								
R8	5.2 FSI qu S tronic	540	540	11.4	272	S\$ 769,888	30,000	S\$ 799,888

*Terms & Conditions. Please turn over

Terms and Conditions :

- Package price includes 12-months road tax, registration fee and GST but without insurance
- COE is not guaranteed and subject to 6 bids (within 3 months) only, taking which new terms and conditions shall apply.
- Booking deposit for all models is S\$20,000/-
- Minimum booking deposit for special intent models is S\$25,000/-, with the exception of RS/R8 is S\$75,000/-
- An administrative fee of S\$1,000/- will be levied for any changes to models, colors and options for all intent orders.
- All deposits are non-refundable upon cancellation.
- In-house utilization of PARF/COE Rebates for new car registration is within Premium Automobile's discretion.
- Subject to in-house Financier and Insurance.

All prices and promotions are subject to change without any prior notice.

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 2100481195-01
Period of Insurance : 31 Aug 2017 to 30 Aug 2018

Issued Date : 31 Jul 2017

ABOUT THE POLICYHOLDER

Name of Policyholder : BERNARD CHIN KIM FOOK
Address : 68 CHESTNUT AVE
#16-15 TREE HOUSE
SINGAPORE 679521
Occupation/Nature of Business : Executives

ABOUT THE VEHICLE

Registration No. : SLF6174T
Chassis No. : WAUZZZF42GA111565
Seating Capacity : 5
First Year of Registration : 2015
Make/Model : AUDI A4 1.4 TFSI S tronic
Hire Purchase Company/Employer's Loan : United Overseas Bank Limited
Engine Capacity/Tonnage : 1,395.00 CC
Engine No. : CVN014485
Body Type : Sedan

ABOUT THE COVER

Sum Insured : Market Value
Driver Restriction : NA
Off Peak Car : No
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive

- a) The Policyholder
b) Any other person who is driving at the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorized Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, prearranging, reliability trial or speedrunning, the damage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits

Key or Lost, Stolen, Picked and Civil Commission: Pk to Authorized Driver / Unnamed Passenger: \$1000; Dealer + AIG Authorized Workshops: Pk Insured: \$10000; Finance and Accessories (Cessure): \$6000; ~~Excess~~ For Old (36 months): In-Car Camera Excess Waiver

EXCESS

Section 1
Fire - \$0; Own Damage - \$600; Theft - \$0; Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen - \$100

Named Driver
BERNARD CHIN KIM FOOK - \$600 (Own Damage)

PREMIUM

Premium : \$ 1,300.26
GST (7%) : \$ 91.02

Total : \$ 1,391.28

Your Premium includes the following discount(s):

Safe Driver Discount - 5.00%; Group Discount - 10.00%; No Claim Discount - 50%

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0359/2018/GW
Date : 22-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SLF 6174 T**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Bernard Chin Kim Fook
Address : Tree House, 68 Chestnut Avenue
#16-15
Singapore 679521
Telephone : (HP) 67093406
Type of Claim : Own Damage Claims
Policy No. : 2100481196-01
Vehicle No : **SLF 6174 T**
Model Code : Audi A4 Sedan 1.41 TFSI S
Model / Year : Aug-16
Engine No : CVN 014489
Chassis No : WAUZZZF42GA111565
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Mar-18
Place of Accident : Elite Highway KM 9.2 Selangor

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian *hij*
Surveyed Date : 26/03/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 32 Days. (Inclusive of front and rear undercarriage)
(Not inclusive of internal structural damages)

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 6174 T.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature and headlights washer assy.	S/N \$ 360.00 ✓	360
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N \$ 280.00 ✓	280
3	To dismantle and renew front bumper, rhs front fender, headlight, rhs front door and wing mirror assy. Re-organise front management components. Reinstall all parts removed.	\$ 3,000.00	2000 2000
4	To suspend engine, dismantle front suspension assy. Inspect for damages and renew accordingly.	S/N \$ 2,800.00 ✓	2800
5	To respray front bumper, rhs front fender, rhs front door and rhs wing mirror cover.	\$ 2,500.00	1800 1800
6	To renew lhs front rim. Carry out wheel alignment.	S/N \$ 280.00 ✓	280
TOTAL LABOUR CHARGES - FRONT		: \$ <u>9,220.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6174T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repaired</i>	\$ 1,849.00	X 1479.20
2	FRONT BUMPER AIR GUIDE-RH <i>Not New</i>	\$ 73.00	X 57.84
3	FRONT BUMPER GUIDE SECTION-RH <i>Dented</i>	\$ 32.00	✓ 25.36
4	FRONT FENDER-RH <i>Dented</i>	\$ 665.00	✓ 532.00
5	FRONT FENDER ATTACHMENT PARTS-RH <i>Not New</i>	\$ 45.00	? X
6	FRONT FENDER CLOSING ELEMENT-RH <i>Dented</i>	\$ 44.00	? 34.56
7	FRONT FENDER BRACKET <i>Bent</i>	\$ 31.00	✓ 24.16
8	FRONT FENDER DEFORMATION ELEMENT BRACKET-LH <i>Not New</i>	\$ 43.00	✓ X
9	FRONT FENDER TOP COVER <i>Not New</i>	\$ 27.00	✓ 21.04
10	FRONT FENDER BRACE-RH <i>Bent</i>	\$ 103.00	✓ 82.40
11	FRONT FENDER FILLER PANEL-RH <i>Not New</i>	\$ 29.00	? X
12	FRONT WHEEL HOUSING LINER-RH <i>Dented</i>	\$ 209.00	✓ 167.20
13	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not New</i>	\$ 78.00	? X
14	FRONT WHEEL SPOILER-RH <i>Dented</i>	\$ 63.00	✓ 50.16
15	FRONT FENDER LINER EXTENSION BRACKET-RH <i>Not New</i>	\$ 31.00	? X
16	STONE CHIP GUARD <i>Not New</i>	\$ 44.00	✓ 34.56
17	LED HEADLIGHT-RH <i>Not New</i>	\$ 6,973.00	✓ 5578.40
18	FRONT DOOR-RH <i>Dented</i>	\$ 1,860.00	✓ 1638.40
19	FRONT OUTER DOOR SEAL-RH <i>Not New</i>	\$ 176.00	✓ 140.40
20	BONDING AGENT <i>Not New</i>	\$ 43.00	? X
SUB- SPARE PARTS CHARGES - FRONT		\$ 12,418.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6174 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	CLEANING SOLUTION <i>Not nec</i>	\$ 64.00	+
22	FRONT DOOR CATCH-RH <i>Not nec</i>	\$ 92.00	+
23	FRONT EXTERIOR MIRROR MOUNTING-RH <i>Not nec</i>	\$ 959.00	✓ 632.60
24	ASSEMBLY CARRIER <i>Not nec</i>	\$ 1,657.00	?
25	FRONT WISHBONE LINK <i>Best</i>	\$ 476.00	?
26	FRONT SUSPENSION GUIDE-RH <i>Best</i>	\$ 834.00	?
27	FRONT UPPER CONTROL ARM-RH <i>Best</i>	\$ 452.00	?
28	FRONT UPPER REARWARD CONTROL ARM-RH <i>Best</i>	\$ 452.00	?
29	FRONT WHEEL BEARING HOUSING-RH <i>Best</i>	\$ 848.00	?
30	SWIVEL JOINT <i>Best</i>	\$ 165.00	?
31	WHEEL HUB WITH BEARING <i>Best</i>	\$ 651.00	?
32	ELECTRIC STERRING RACK <i>Best</i>	\$ 5,922.00	?
33	TIE ROD END <i>Best</i>	\$ 169.00	?
TOTAL SPARE PARTS CHARGES - FRONT		\$ 25,159.00	
TOTAL LABOUR CHARGES - FRONT		\$ 9,220.00	
GRAND TOTAL - FRONT		\$ 34,379.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 6174 T

S/N	Nature of Jobs			Estimated Charges	
1	To carry out first measurement on car-o-liner.	S/N	\$	800.00	? x
2	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function and renew according to damage.	S/N	\$	360.00	✓ 360
3	To renew 1/4 glass and rear windscreen to facillitate fender renewal.	S/N	\$	600.00	✓ 600
4	To remove and reinstall rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N	\$	480.00	✓ 480
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipmenmt. Inspect for damage and renew where necessary.	S/N	\$	1,800.00	✓ 1800
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain air bag etc.	S/N	\$	1,400.00	✓ 1400
SUB-TOTAL LABOUR CHARGES - (REAR)			:	\$	5,440.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 6174 T

S/N	Nature of Jobs	Estimated Charges
7	To remove rear exhaust silencer assy. Dismantle rear suspension assy. Inspect for damages and renew accordingly.	S/N \$ 2,800.00 ✓ 2800
8	To remove and reinstall fuel tank assy. Inspect for damages.	S/N \$ 480.00 ✓ 480
9	To set up and place vehicle on car-o-liner.	S/N \$ 1,200.00 ? 1200
10	To dismantle rear bumper and rear lid. Repair and straighten both rear chassis frames to specification of origin. Cut out and weld rear end panels, spare wheel well, rhs rear fender, connecting plates, outer wheel house, inner wheel house. Renew rear bumper and rear lid. reinstall all parts removed.	\$ 13,200.00 6000 (Not withstanding any internal structural damages) 8000
11	To respray rear bumper, rear lid, both rear fenders, connecting plates, rhs sill panel, door entrance, drain panel, roof channel, spare wheel well and end panelling. To carry out stone chip treatment and joint sealer works. Rear door	\$ 7,200.00 4400 4400
12	To carry out wheel alignment.	S/N \$ 240.00 X X
13	To carry out diagnostic check.	S/N \$ 768.00 ? 384.00
TOTAL LABOUR CHARGES - (REAR)		: \$ 31,328.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLF 6174 T.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR BUMPER Distorted	\$ 1,907.00	✓ 1525.60
2	REAR BUMPER FIXING PARTS Dmgd	\$ 63.00	? 50.00
3	REAR BUMPER SECURING PLATE Dmgd	4 \$ 56.00	? 44.80
4	REAR BUMPER SECURING STRIP Dmgd	\$ 191.00	✓ 152.80
5	REAR BUMPER SPOILER Bashed	\$ 216.00	✓ 172.80
6	REAR LIGHT REFLECTOR-LH/RH Rtl cracked	2 \$ 70.00	35 27.76
7	REAR BUMPER SENSOR 2 pieces dngd	4 \$ 842.00	421 336.80
8	REAR BUMPER WIRING Snapped	\$ 598.00	? 478.00
9	REAR BUMPER CARRIER Bent	\$ 786.00	✓ 628.40
10	REAR BUMPER SENOR SEAL new	2 \$ 24.00	✓ 18.56
11	REAR BUMPER GUIDE SECTION-LH/RH } Rtl Dngd	2 \$ 75.00	37.50 60.00
11	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 38.00	19. 29.76
12	REAR LID Dented	\$ 2,362.00	✓ 1889.60
13	REAR LID ATTACHMENT PART new	\$ 125.00	✓ 99.60
14	REAR LID HINGE-LH/RH RH BENT	2 \$ 400.00	? 160.00
15	REAR LID LOCK Not New	\$ 202.00	? X
16	REAR LID PUSH BUTTON ELECTRIC new	\$ 475.00	X
17	REAR LOCK STRIKER New	\$ 29.00	X
18	LED LICENCE PLATE new	2 \$ 100.00	+ X
19	ANTI-THEFT GUARD COVER } new	\$ 55.00	X
20	STOP BUFFER	2 \$ 28.00	X
SUB-TOTAL SPARE PARTS - frt/rear		\$ 8,642.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLF 6174 T.

		<u>Damage Parts & Prices</u>	
S/N	Parts Description	S/NETT	REMARKS
21	DAMPER <i>{ new</i>	\$ 105.00 *	} X
22	SPRING	\$ 50.00	
23	REAR LID GASKET FOR FLAP <i>new</i>	\$ 176.00*	140.40
24	REAR LID STOP <i>new</i>	4 \$ 39.00*	} X
25	REAR LID STOP CAP	2 \$ 8.00 *	
27	ADHESIVE PACKING <i>new</i>	\$ 15.00 ✓	11.60
28	AUDI EMBLEM <i>{ new</i>	\$ 108.00 ✓	83.00
29	INSCRIPTION " A4 "	\$ 83.00 ✓	66.16
30	INSCRIPTION " TFSI "	\$ 83.00 ✓	66.16
31	REAR CROSS PANEL <i>Distorted.</i>	\$ 230.00 ✓	183.60
32	REAR CROSS PANEL REINFORCEMENT <i>Distorted</i>	\$ 445.00 ✓	356.00
33	REAR SIDE PANEL <i>Distorted Repair</i>	\$ 783.00 but ? X	
34	REAR CONNECTING PLATE-RH <i>Distorted</i>	\$ 71.00 ✓	56.40
35	REAR WHEEL HOUSING-RH <i>Distorted.</i>	\$ 545.00 ?	436.00
36	REAR VENT TRIM <i>Smashed RH</i>	2 \$ 119.00 59.50 94.88	
37	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 78.00 ✓	62.00
38	D-PILLARS PARTITION <i>Repair</i>	\$ 21.00 ?	} X
39	REAR WHEEL HOUSING INNER PART-RH <i>Repair</i>	\$ 1,064.00 ?	
40	SPARE WHEEL WELL <i>Repair</i>	\$ 1,938.00 ?	
SUB-TOTAL SPARE PARTS - frt/rear		\$ 5,961.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLF 6174 T.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
41	SPARE WHEEL MOUNTING <i>Not nec</i>	\$ 117.00 ?	} x
42	CLAMPING STRIP FOR BATTERY <i>Not nec</i>	\$ 11.00 ?	
43	STRIKER PLATE <i>Not nec</i>	\$ 113.00 ?	
44	BOTTOM PLATE <i>Distorted</i>	\$ 428.00 ?	342.60
45	VENT TRIM <i>Not nec</i>	\$ 60.00 ?	} x
46	SIDE MEMBER-RH <i>Distorted Repair</i>	\$ 1,483.00	
47	UNDERBODY TRIM <i>torn</i>	\$ 97.00	77.60
48	REAR WINDOW <i>nec</i>	\$ 1,014.00 ?	811.20
49	SIDE WINDOW <i>nec</i>	\$ 541.00 ?	432.40
50	PRIMER <i>nec</i>	2 \$ 37.00 ?	29.12
51	REAR CROSS PANEL TRIM <i>Not nec</i>	\$ 146.00 ?	} x
52	INSERT PART <i>Not nec</i>	\$ 237.00 ?	
53	LUGGAGE COMPARTMENT FLOOR <i>Repair</i>	\$ 621.00 ?	} x
54	LUGGAGE COMPARTMENT TRIM <i>Not nec</i>	\$ 689.00 ?	
55	BRACKET <i>Not nec</i>	2 \$ 61.00 ?	} x
56	TRUNK TIE DOWN HOOK <i>Not nec</i>	4 \$ 208.00 ?	
57	REAR LID TRIM PANEL <i>Del'd</i>	\$ 290.00	231.60
58	REAR NO. PLATE <i>nec</i>	S/N \$ 25.00	X
59	ACRYLIC SEALER <i>nec</i>	S/N \$ 360.00	360.00
60	CAVITY WAX <i>nec</i>	S/N \$ 280.00	280.00
SUB-TOTAL SPARE PARTS - frt/rear		: \$ 6,818.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLF 6174 T.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
61	STONE CHIP	S/N \$ 360.00 ✓	360.00
62	1/4 GLASS SEALANT	S/N \$ 100.00 ✓	100.00
63	REAR WINDSCREEN SEALANT	S/N \$ 200.00 ✓	200.00
64	METAL FILLER POWDER	S/N \$ 560.00 ✓	560.00
65	SUPPORT FRAME	\$ 2,804.00 ?	2243.20
66	REAR WISHBONE	\$ 762.00 ?	609.20
67	REAR UPPER WISH BONE-RH	\$ 492.00 ?	393.20
68	REAR FRONT WISH BONE-RH	\$ 109.00 ?	87.20
69	REAR LATERAL ARM	\$ 395.00 ?	316.00
70	TRACK ROD	\$ 149.00 ?	119.20
71	REAR WHEEL BEARING HOUSING-RH	\$ 868.00 ?	694.40
72	WHEEL BEARING WITH ASSEMBLY PARTS	\$ 394.00 ?	314.80
73	STONE CHIP GUARD	\$ 38.00 ✓	30.00
74	GAS SHOCK ABSORBER	\$ 260.00 ?	208.00
75	SHOCK ABSORBER BEARING	\$ 94.00 ?	
76	ANTI ROLL BAR	\$ 358.00 ?	x
77	COUPLING ROD	2 \$ 153.00 ?	
78	REAR FENDER - RH	\$ 2,347.00 ✓	1877.60
79	SUNDIRES	\$ 2,000.00 ?	555.41
REAR SPARE PARTS		\$ 33,864.00	
REAR LABOUR		\$ 31,328.00	
TOTAL SPARE PARTS - frt/rear		\$ 59,023.00	
TOTAL LABOUR CHARGES - frt/rear		\$ 40,548.00	
GRAND TOTAL -		\$ 99,571.00	110,664.10

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

102956.41

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1163

Email: Nora.khar@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9002271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0359/2018/GW

28-May-18

Tony

1 of 1

SLF 6174 T

Audi A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR WINDSCREEN AND REAR RH 1/4 GLASS SOLAR FILM	\$ 299.60	299.60
2	TYRE RIM - REAR RH	\$ 802.50	802.50
TOTAL PARTS :		\$ 1,102.10	
GRAND TOTAL :		\$ 1,102.10	

For Premium Automobiles Pte Ltd



Authorised Signature

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0359/2018/GW

28-May-18

Tony

1 of 1

SLF 6174 T

Audi A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Front brake host <i>Damaged</i>	\$ 67.00	\$ 53.36
2	Rear C link <i>2nd</i>	\$ 77.00	\$ 60.96
3	Underbody lining <i>2x2m</i>	\$ 116.00	\$ 92.80
4	label <i>new</i>	\$ 33.00	\$ 26.24
5	Rear wheel liner RHS <i>2x2m</i>	\$ 215.00	\$ 171.60
		\$ 508.00	\$ 404.96
LABOUR			
1	To respray bonnet, rhs rear door	\$ 1,400.00	\$ 1,100.00
TOTAL PARTS :		\$ 1,908.00	\$ 1,504.96

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0359/2018/GW 14-May-18 CHANG 1 of 1 SLF 6174 T Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	FUEL TANK <i>To/r</i>	\$ 5,049.00	\$ 4,039.20
2	FUEL TANK SCREW SET <i>new</i>	\$ 33.00	\$ 26.40
3	CHARCOAL CONTAINER <i>Cracked</i>	\$ 360.00	\$ 288.00
4	BREATHER LINE <i>Set</i>	\$ 92.00	\$ 78.00
5	AIR LINE <i>Set</i>	\$ 33.00	\$ 25.84
6	CHARCOAL CONTAINER BRACKET <i>Set</i>	\$ 97.00	\$ 77.36
7	WHEEL HOUSING SUPPORT - RH <i>3 pnd</i>	\$ 86.00	\$ 68.16
8	REAR LID TENSION SPRING CONSOLE	\$ 24.00	\$ 18.99
9	FUEL TANK INSERT <i>2 pnd</i>	\$ 78.00	\$ 62.00
10	SECURING PLATE <i>not new</i>	\$ 56.00	\$ 44.80
11	REAR LID HINGE COVER - RH <i>3 pnd</i>	\$ 15.00	\$ 12.00
12	REAR LID HINGE COVER CLIP <i>3 pnd</i>	\$ 17.00	\$ 13.44
13	REAR FENDER REINFORCEMENT - RH REAR <i>3 pnd</i>	\$ 180.00	\$ 143.60
14	D-PILLAR PANEL SUPPORT - RH <i>Set</i>	\$ 86.00	\$ 68.16
15	LED TAIL LIGHT - RH INNER <i>3 pnd</i>	\$ 816.00	\$ 652.40
16	LED TAIL LIGHT - RH OUTER <i>3 pnd</i>	\$ 915.00	\$ 732.00
17	REAR END PANEL TOP COVER <i>3 pnd</i>	\$ 146.00	\$ 116.80
TOTAL PARTS :		\$ 8,083.00	\$ 6,422.35
GRAND TOTAL :		\$ 8,083.00	\$ 6,422.35

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0359/2018/GW
Date : 22-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. **SLF 6174 T**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

You recommended 32 days

We took 54 days exclude 9 Sundays

and 2 Public Holiday - JB - 16 Jul 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Bernard Chin Kim Fook
Address : Tree House, 68 Chestnut Avenue
#16-15
Singapore 679521
Telephone : (HP) 67093406
Type of Claim : Own Damage Claims
Policy No. : 2100481196-01
Vehicle No : **SLF 6174 T**
Model Code : Audi A4 Sedan 1.41 TFSI S
Model / Year : Aug-16
Engine No : CVN 014489
Chassis No : WAUZZZF42GA111565
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Mar-18
Place of Accident : Elite Highway KM 9.2 Selangor

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 6174 T.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature and headlights washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N	\$ 280.00	\$ 280.00
3	To dismantle and renew front bumper, rhs front fender, headlight, rhs front door and wing mirror assy. Re-organise front management components. Reinstall all parts removed.		\$ 3,000.00	\$ 2,000.00
4	To suspend engine, dismantle front suspension assy. Inspect for damages and renew accordingly.	S/N	\$ 2,800.00	\$ 2,800.00
5	To respray front bumper, rhs front fender, rhs front door and rhs wing mirror cover.		\$ 2,500.00	\$ 1,800.00
6	To renew lhs front rim. Carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 9,220.00	\$ 7,520.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6174T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	\$ 57.84
3	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	\$ 25.36
4	FRONT FENDER-RH	\$ 665.00	\$ 532.00
5	FRONT FENDER ATTACHMENT PARTS-RH	\$ 45.00	
6	FRONT FENDER CLOSING ELEMENT-RH	\$ 44.00	\$ 34.56
7	FRONT FENDER BRACKET	\$ 31.00	\$ 24.16
8	FRONT FENDER DEFORMATION ELEMENT BRACKET-LH	\$ 43.00	
9	FRONT FENDER TOP COVER	\$ 27.00	\$ 21.04
10	FRONT FENDER BRACE-RH	\$ 103.00	\$ 82.40
11	FRONT FENDER FILLER PANEL-RH	\$ 29.00	
12	FRONT WHEEL HOUSING LINER-RH	\$ 209.00	\$ 167.20
13	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 78.00	
14	FRONT WHEEL SPOILER-RH	\$ 63.00	\$ 50.16
15	FRONT FENDER LINER EXTENSION BRACKET-RH	\$ 31.00	
16	STONE CHIP GUARD	\$ 44.00	\$ 34.56
17	LED HEADLIGHT-RH	\$ 6,973.00	\$ 5,578.40
18	FRONT DOOR -RH	\$ 1,860.00	\$ 1,638.40
19	FRONT OUTER DOOR SEAL-RH	\$ 176.00	\$ 140.40
20	BONDING AGENT	\$ 43.00	
SUB- SPARE PARTS CHARGES - FRONT		\$ 12,418.00	\$ 9,865.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 6174 T.

		<u>Damage Parts & Prices</u>		
S/N	Parts Description	S/NETT	REMARKS	
		c/f	\$	9,865.68
21	CLEANING SOLUTION	\$	64.00	
22	FRONT DOOR CATCH-RH	\$	92.00	
23	FRONT EXTERIOR MIRROR MOUNTING-RH	\$	959.00	\$ 632.00
24	ASSEMBLY CARRIER	\$	1,657.00	
25	FRONT WISHBONE LINK	\$	476.00	\$ 380.40
26	FRONT SUSPENSION GUIDE-RH	\$	834.00	\$ 667.20
27	FRONT UPPER CONTROL ARM-RH	\$	452.00	\$ 361.20
28	FRONT UPPER REARWARD CONTROL ARM-RH	\$	452.00	\$ 361.20
29	FRONT WHEEL BEARING HOUSING-RH	\$	848.00	\$ 678.40
30	SWIVEL JOINT	\$	165.00	\$ 132.00
31	WHEEL HUB WITH BEARING	\$	651.00	\$ 520.80
32	ELECTRIC STERRING RACK	\$	5,922.00	\$ 4,737.60
33	TIE ROD END	\$	169.00	\$ 135.20
	TOTAL SPARE PARTS CHARGES - FRONT	\$	25,159.00	\$ 18,471.68
	TOTAL LABOUR CHARGES - FRONT	\$	9,220.00	\$ 7,520.00
	GRAND TOTAL - FRONT	\$	34,379.00	\$ 25,991.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 6174 T

S/N	Nature of Jobs	Estimated Charges	
	<i>LABOUR FRONT C/F</i>	\$	7,520.00
1	To carry out first measurement on car-o-liner.	S/N \$ 800.00	FOC
2	To remove and transfer rear parking aid and rear lid kick sensor assy. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
3	To renew 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$ 600.00	\$ 600.00
4	To remove and reinstall rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	\$ 480.00
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipmenmt. Inspect for damage and renew where necessary.	S/N \$ 1,800.00	\$ 1,800.00
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain air bag etc.	S/N \$ 1,400.00	\$ 1,400.00
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 5,440.00	\$ 12,160.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 6174 T

S/N	Nature of Jobs	Estimated Charges		
			\$	12,160.00
7	To remove rear exhaust silencer assy. Dismantle rear suspension assy. Inspect for damages and renew accordingly.	S/N \$ 2,800.00	\$	2,800.00
8	To remove and reinstall fuel tank assy. Inspect for damages.	S/N \$ 480.00	\$	480.00
9	To set up and place vehicle on car-o-liner.	S/N \$ 1,200.00	\$	1,200.00
10	To dismantle rear bumper and rear lid. Repair and straighten both rear chassis frames to specification of origin. Cut out and weld rear end panels, spare wheel well, rhs rear fender, connecting plates, outer wheel house, inner wheel house. Renew rear bumper and rear lid. reinstall all parts removed.	\$ 13,200.00	\$	8,000.00
	<i>Added 4 days for replacement, RHS outer wheelhouse, Bottom plate, repair RHS substructure etc etc Added \$2000.00</i>			
11	To respray rear bumper, rear lid, both rear fenders, connecting plates, rhs sill panel, door entrance, drain panel, roof channel, spare wheel well and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 7,200.00	\$	4,400.00
12	To carry out wheel alignment.	S/N \$ 240.00	nil	
12a	Added labour charges - see attached	\$ 1,400.00	\$	1,100.00
13	To carry out diagnostic check.	S/N \$ 768.00	\$	384.00
	TOTAL LABOUR CHARGES - (REAR)	: \$ 32,728.00	\$	30,524.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLF 6174 T.

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
	FRONT MATERIAL C/F	\$	18,471.68
1	REAR BUMPER	\$ 1,907.00	\$ 1,525.60
2	REAR BUMPER FIXING PARTS	\$ 63.00	\$ 50.00
3	REAR BUMPER SECURING PLATE	4 \$ 56.00	\$ 44.80
4	REAR BUMPER SECURING STRIP	\$ 191.00	\$ 152.80
5	REAR BUMPER SPOILER	\$ 216.00	\$ 172.80
6	REAR LIGHT REFLECTOR-LH/RH	2 \$ 70.00	\$ 27.76
7	REAR BUMPER SENSOR	4 \$ 842.00	\$ 336.80
8	REAR BUMPER WIRING	\$ 598.00	\$ 478.00
9	REAR BUMPER CARRIER	\$ 786.00	\$ 628.40
10	REAR BUMPER SENOR SEAL	2 \$ 24.00	\$ 18.56
11	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 75.00	\$ 60.00
11	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 38.00	\$ 29.76
12	REAR LID	\$ 2,362.00	\$ 1,889.60
13	REAR LID ATTACHMENT PART	\$ 125.00	\$ 99.60
14	REAR LID HINGE-LH/RH	2 \$ 400.00	\$ 160.00
15	REAR LID LOCK	\$ 202.00	
16	REAR LID PUSH BUTTON ELECTRIC	\$ 475.00	
17	REAR LOCK STRIKER	\$ 29.00	
18	LED LICENCE PLATE	2 \$ 100.00	
19	ANTI-THEFT GUARD COVER	\$ 55.00	
20	STOP BUFFER	2 \$ 28.00	
SUB-TOTAL SPARE PARTS - frt/rear		\$ 8,642.00	\$ 24,146.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

\$

Material List for Accident Vehicle Regn No.SLF 6174 T.

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT	\$	
					24,146.16
21	DAMPER		\$	105.00	
22	SPRING		\$	50.00	
23	REAR LID GASKET FOR FLAP		\$	176.00	\$ 140.40
24	REAR LID STOP	4	\$	39.00	
25	REAR LID STOP CAP	2	\$	8.00	
27	ADHESIVE PACKING		\$	15.00	\$ 11.60
28	AUDI EMBLEM		\$	108.00	\$ 86.00
29	INSCRIPTION " A4 "		\$	83.00	\$ 66.16
30	INSCRIPTION " TFSI "		\$	83.00	\$ 66.16
31	REAR CROSS PANEL		\$	230.00	\$ 183.60
32	REAR CROSS PANEL REINFORCEMENT		\$	445.00	\$ 356.00
33	REAR SIDE PANEL		\$	783.00	
34	REAR CONNECTING PLATE-RH		\$	71.00	\$ 56.40
35	REAR WHEEL HOUSING-RH		\$	545.00	\$ 436.00
36	REAR VENT TRIM	2	\$	119.00	\$ 94.88
37	WHEEL HOUSING LINER ATTACHMENT PARTS		\$	78.00	\$ 62.00
38	D-PILLARS PARTITION		\$	21.00	
39	REAR WHEEL HOUSING INNER PART-RH		\$	1,064.00	
40	SPARE WHEEL WELL		\$	1,938.00	
SUB-TOTAL SPARE PARTS - frt/rear			\$	5,961.00	\$ 25,705.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLF 6174 T.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
				25,705.36
41	SPARE WHEEL MOUNTING	\$ 117.00		
42	CLAMPING STRIP FOR BATTERY	\$ 11.00		
43	STRIKER PLATE	\$ 113.00		
44	BOTTOM PLATE	\$ 428.00	\$	342.00
45	VENT TRIM	\$ 60.00		
46	SIDE MEMBER-RH	\$ 1,483.00		
47	UNDERBODY TRIM	\$ 97.00	\$	77.60
48	REAR WINDOW	\$ 1,014.00	\$	811.20
49	SIDE WINDOW	\$ 541.00	\$	432.40
50	PRIMER	2 \$ 37.00	\$	29.12
51	REAR CROSS PANEL TRIM	\$ 146.00		
52	INSERT PART	\$ 237.00		
53	LUGGAGE COMPARTMENT FLOOR	\$ 621.00		
54	LUGGAGE COMPARTMENT TRIM	\$ 689.00	\$	551.20
55	BRACKET	2 \$ 61.00		
56	TRUNK TIE DOWN HOOK	4 \$ 208.00		
57	REAR LID TRIM PANEL	\$ 290.00	\$	231.60
58	REAR NO. PLATE	S/N \$ 25.00		
59	ACRYLIC SEALER	S/N \$ 360.00	\$	360.00
60	CAVITY WAX	S/N \$ 280.00	\$	280.00
SUB-TOTAL SPARE PARTS - frt/rear		\$ 6,818.00	\$	28,820.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No.SLF 6174 T.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0359/2018/GW 28-May-18 Tony 1 of 1 SLF 6174 T Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	REAR WINDSCREEN AND REAR RH 1/4 GLASS SOLAR FILM <i>new</i>	\$ 299.60	\$ 299.60
2	TYRE RIM - REAR RH <i>cut</i>	\$ 802.50	\$ 802.50
3	Front brake host <i>only</i>	\$ 67.00	\$ 53.36
4	Rear C link <i>both</i>	\$ 77.00	\$ 60.96
5	Underbody lining <i>both</i>	\$ 116.00	\$ 92.80
6	label <i>new</i>	\$ 33.00	\$ 26.24
7	Rear wheel liner RHS <i>both</i>	\$ 215.00	\$ 171.60
		\$ 1,610.10	\$ 1,507.06
LABOUR			
1	To respray bonnet, rhs rear door	\$ 1,400.00	\$ 1,100.00
	TOTAL PARTS :	\$ 3,010.10	\$ 2,607.06

* both by owner

For Premium Automobiles Pte Ltd

Authorised Signature

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, July 16, 2018 3:27 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; jlayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SLF6174T - OD AIG - SURVEYED 26 MAR 18
Attachments: PA03592018 - SLF 6174 T - A4 SEDAN 1.4 TFSI - FRONT + REAR (AIG) + SUPP.xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$78,942.10 @ 54 days of repairs exclude 9 Sundays and 2 Public Holidays. Please discuss with Tony on acceptance for days of repairs.

Photographs can be obtained from our share folders. (Resurvey SLF6174T)

Your early closure is well appreciated.

Best
regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLF 6174 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0359/2018/MAS

14 Aug 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SLF 6174 T, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above mentioned vehicle, no. **SLF 6174 T**, claimant, **Mr. Bernard Chin Kim Fook**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012826 - \$80,616.05
2. A copy of letter of Discharge duly signed by client

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG Insurance – SLF 6174 T

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 684 11183