

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2897/03/18 Your Ref: _____ Date: 26th March 2018

M/S DL Repair & Aircon Services
Blk 111, #07-76,
Woodlands Street 13,
Singapore 730111

not done
the whole
repair
1/5 \$3000
4dy
27/3/18

Estimate cost of repair to NISSAN NV350 Van - GBE 3678 A

1 pc front panel	<i>body</i>	\$ 1,096.90	Nett
1 pc front windscreen glass moulding	<i>new</i>	63.20	"
1 pc front windscreen glass inner seal	<i>new</i>	60.20	"
1 pc front windscreen glass sealant	<i>new</i>	226.10	" <i>405.2</i>
1 pc front grille & chrome frame comp	<i>one</i>	485.00	"
1 pc front number plate & frame	<i>new</i>	50.00	" <i>405.2</i>
1 pc front grille 'NISSAN' logo emblem	<i>new</i>	73.60	"
6 pcs front grille clips	<i>new</i>	33.00	"
1 pc front bumper	<i>new</i>	514.70	"
8 pcs front bumper clips	<i>new</i>	40.00	"
1 pc front bumper centre air scoop	<i>17</i>	106.90	" <i>X</i>
2 pcs front bumper o/s & n/s side retainer	<i>11</i>	29.40	" <i>X</i>
		\$ 2,779.00	Nett
	Less 10%	\$ 277.90	
		\$ 2,501.10	<i>2366.6</i> <i>2121.94</i>

To wiring check up for affected wiring system.

120.00 *20*

To remove & refix front windscreen glass & necessary parts.

150.00 *100*

To remove & refix dash board, wiper motor, air cond blower motor, cooling box & necessary parts, to enable repair front panel & necessary parts,

380.00 *160*

To refill Ra 134 air cond gas for enable repair front panel.

120.00 *100*

To respray Tuff-Kote on all affected accident parts.

90.00 *30*

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out necessary parts, to weld, renew & align above parts.

750.00 *600*

To putty & respray painting on all affected accident parts.

800.00 *580*

\$ 4,911.10

Dollars : Four Thousand Nine Hundred Eleven Dollars And Cents Ten Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify
the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: