



FALCON-AIR

MASS TECHNOLOGIES PTE LTD
7 BUKIT BATOK STREET 22
SINGAPORE 659584

Attention : Motor Claim Department
Contact : 90906494 676346002 97821392

Estimate : ES003147

Date : 26/03/2018
Vehicle Num. : GZ6038H
Make/Model : TOYOTA HIACE
Chassis/Eng# : JTFHS02P500050049
Accident Date : 24/03/2018
Claim No. :
Reference : TP TMIS VS EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE	1,765.10	BT ✓
2.	1	TAILGATE GLASS	1,227.10	Bro ✓
3.	1	TAILGATE LOGO	75.80	me ✓
4.	1	TAILGATE OUTER HANDLE	155.60	CRA ✓
5.	1	TAILGATE REAR VIEW MIRROR	465.20	Bro ✓
6.	1	TAILGATE LOCK	275.03	BT ✓
7.	1	TAILGATE WEATHERSTRIP	288.40	me ✓
8.	1	LH TAILLAMP	398.50	CRA ✓
9.	1	TAILLAMP LOWER PANEL	145.00	DE ✓
10.	1	REAR BUMPER	415.80	DE ✓
11.	1	REAR END PANEL INNER	331.70	X ✓
12.	1	REAR END PANEL OUTER	445.00	BT ✓
13.	1	REAR END PANEL SCUFF PLATE	175.00	BT ✓
List TotalS\$:			6,163.23	
25.00% Discount S\$:			1,540.81	
			4,622.42	
SPECIAL NETT ITEMS :				
1.	1	TAILGATE GLASS SEALANT	40.00	me ✓
2.	1	TAILGATE STICKER '70KM/HR'	10.00	me ✓

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR

MASS TECHNOLOGIES PTE LTD
7 BUKIT BATOK STREET 22
SINGAPORE 659584

Attention : Motor Claim Department

Contact : 90906494 676346002 97821392

Estimate : ES003147

Date : 26/03/2018
Vehicle Num. : GZ6038H
Make/Model : TOYOTA HIACE
Chassis/Eng# : JTFHS02P500050049
Accident Date : 24/03/2018
Claim No. :
Reference : TP TMIS VS EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
3.	1	TAILGATE STICKER '7PAX'		10.00
		Special Nett Total S\$:		60.00
		LABOUR :		
		TO TRANSFER TAILGATE PARTS/MECHANISM	40	50.00
		TO REMOVE/REPLACE REAR WINDSCREEN GLASS	100	120.00
		TO RUST PROOF ON ACCIDENT DAMAGED PARTS	80	150.00
		TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING	40	100.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS	800	1,000.00
		TO CUT OUT/ REWELD REAR END PANEL, INNER/OUTER		
		REPAIR REAR CHASSIS, REAR FLOORBOARD, LH TAIL LAMP PANE		
		LH REAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS	600	850.00
		Labour Total S\$:		2,270.00

for FALCON AIR AUTO SERVICES PTE LTD

E. & O.E.

Total S\$: 6,952.42

LKR Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg