



FALCON-AIR

MASS TECHNOLOGIES PTE LTD
7 BUKIT BATOK STREET 22
SINGAPORE 659584

Attention : Motor Claim Department

Contact : 90906494 676346002 97821392

FALCON-AIR AUTO SERVICES PTE LTD

Page 1 / 2
CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003147

Date : 26/03/2018
Vehicle Num. : GZ6038H
Make/Model : TOYOTA HIACE
Chassis/Eng# : JTFHS02P500050049
Accident Date : 24/03/2018
Claim No. :
Reference : TP TMIS VS EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE		1,765.10
2.	1	TAILGATE GLASS		1,227.10
3.	1	TAILGATE LOGO		75.80
4.	1	TAILGATE OUTER HANDLE		155.60
5.	1	TAILGATE REAR VIEW MIRROR		465.20
6.	1	TAILGATE LOCK		275.03
7.	1	TAILGATE WEATHERSTRIP		288.40
8.	1	LH TAILLAMP		398.50
9.	1	TAILLAMP LOWER PANEL		145.00
10.	1	REAR BUMPER		415.80
11.	1	REAR END PANEL INNER		331.70
12.	1	REAR END PANEL OUTER		445.00
13.	1	REAR END PANEL SCUFF PLATE		175.00
List TotalS\$:				6,163.23
25.00% Discount S\$:				1,540.81
				4,622.42
SPECIAL NETT ITEMS :				
1.	1	TAILGATE GLASS SEALANT		40.00
2.	1	TAILGATE STICKER '70KM/HR'		10.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

MASS TECHNOLOGIES PTE LTD
7 BUKIT BATOK STREET 22
SINGAPORE 659584

Attention : Motor Claim Department

Contact : 90906494 676346002 97821392

Page 2 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003147

Date : 26/03/2018
Vehicle Num. : GZ6038H
Make/Model : TOYOTA HIACE
Chassis/Eng# : JTFHS02P500050049
Accident Date : 24/03/2018
Claim No. :
Reference : TP TMIS VS EQ
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
3.	1	TAILGATE STICKER '7PAX'		10.00
		Special Nett Total S\$:		60.00
		LABOUR :		
		TO TRANSFER TAILGATE PARTS/MECHANISM		50.00
		TO REMOVE/REPLACE REAR WINDSCREEN GLASS		120.00
		TO RUST PROOF ON ACCIDENT DAMAGED PARTS		150.00
		TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING		100.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS		1,000.00
		TO CUT OUT/ REWELD REAR END PANEL, INNER/OUTER		
		REPAIR REAR CHASSIS, REAR FLOORBOARD, LH TAIL LAMP PANE		
		LH REAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS		850.00
		Labour Total S\$:		2,270.00



E. & O.E.

Total S\$: 6,952.42

for FALCON-AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg