



HUA HONG PRIVATE LIMITED

25D Sungei Kadul Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

29 March 2018

HHTPClaims18-25

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

ACCIDENT INVOLVING SJA 7008 J & GBF 4567 A ON 23/03/2018 AT JUNCTION OF CHOA CHU KANG ROAD & BUKIT BATOK ROAD AT ABOUT 1535 HOURS

Insured : AZAHARI BIN LEBU
Vehicle Registration No : SJA 7008 J
Vehicle Make : MITSUBISHI
Vehicle Model : LANCER 1.6 M
Vehicle Chassis No : JMYSNCS3A8U002367
Policy No : GA077144/1
Date of Accident : 23/3/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper / DO		\$ 678.00
2	10	Rear Bumper Clip / N/C	\$ 3.00	\$ 30.00
3	2	Rear Bumper Bracket (LH/RH) / BR	\$ 45.00	\$ 90.00
4	15	Rear Bumper Bracket Rivet (x15) / N/C	\$ 2.00	\$ 30.00 20
5	1	Rear Bumper Lower Lip X N/A		\$ 670.00
6	8	Rear Tail Lamp Bracket Clip (x4) X N/A	\$ 3.00	\$ 24.00
7	2	Rear Tail Lamp (LH/RH) X N/A	\$ 420.00	\$ 840.00
8	1	Rear Reinforcement / DO		\$ 195.00
9	1	Rear Boot / DO		\$ 580.00
10	1	Rear Boot Lock / BT		\$ 75.00
11	1	Rear Boot Weather Strip / CR4		\$ 175.00
12	1	Rear Emblem / N/C		\$ 48.00
13	1	Rear Logo (LANCER) / N/C		\$ 28.00
14	1	Rear Logo (GLX) / N/C		\$ 27.00
15	1	Rear End Panel X R		\$ 430.00
16	1	Rear Fender (RH) X R		\$ 380.00
17	1	Rear Bumper Centre Bracket / DO		\$ 128.00
18	1	End Panel Top Garnish / CR4		\$ 95.00
19	1	Rear Boot Hinge X N/A		\$ 95.00
				\$ 4,618.00
Less 20%				\$ (923.60)
				\$ 3,694.40

11	1	Rear Number Plate	NN	NETT	\$ 35.00 X
12	1	Rear Reverse Sensor	900	NETT	\$ 200.00 / Shd
					\$ 3,929.40



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

**ACCIDENT INVOLVING SJA 7008 J & GBF 4567 A ON 23/03/2018 AT JUNCTION OF
CHOA CHU KANG ROAD & BUKIT BATOK ROAD AT ABOUT 1535 HOURS**
Estimate Repair List for vehicle SJA 7008 J - Mitsubishi Lancer

	Balance B/F	\$	3,929.40
To dismantle, cut & weld rear end panel, change rear bumper, lower lip, rear bumper, rear LH/RH tail lamp, rear boot, knocking & pull straight rear LH/RH tail lamp panel, rear LH/RH fender, rear tyre floor panel and all area affected by accident.	\$	1,200.00	800 /
To perform wire checking.	\$	20.00	/
To dismantle rear cushion seat and change rear boot hinge (LH/RH)	\$	100.00	30 /
To dismantle & refit rear reverse sensor.	\$	60.00	20 /
To dismantle, repair and spray rear boot spoiler	\$	200.00	100 /
To spray rear bumper, rear bumper lip, rear boot, rear panel, rear LH/RH tail lamp panel, rear tyre floor panel and touch up rear LH/RH fender.	\$	1,000.00	800 /

1779

7% GST
Total

\$	6,509.40
\$	455.66
\$	6,965.06

P-1735.20
A1-200
L-1770
3705.20
L/S-2964.16
= 2950



[Signature]

Authorised by Claims Dept
Mrs Tan @ 9639 9195

5 repair days

kindly offer workshop

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Co. Reg. No. 200900309M

huahong.com.sg

GST Reg. No. 200900309M