

ASS. REC. BY:

REF: CS/TCU0005661/Ugbn2 Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): CWS Karen Tan

of FCL

Date/Time: 28/03/2018 3.28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GLT 3892A

Insured:

SHA 7916L

at Workshop m/s

Pegasus

Tel:

6858 1846

of

51 Defu Lane 10

Policy No:

D-18088936 MFH

Claim No:

D18002488MFSH

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 26/03/2018

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 28/03/2018 4:14pm

Person Contacted:

Avin

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 3892A - x
	SHA 7916L - CCL/AYA151103008/Hly0362 OIA: 120519
24/3/18 @ 2.50pm	revised to Karen Tan by email.

(08/11/13) wef

ASS..REC. BY: Marcus

REF:

Fc. /

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL73892A

at Workshop m/s: P 99543

of \_\_\_\_\_

Insured: SIA 7916L

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SL73892A Yr Regn: 10/17

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: merda 3 c.c. 1496

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: 28768 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6BN22A8H0158119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 2 mm

R/Bal. 2 mm

L/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 26/3/18

D.O.I. 27/3/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/3/18	confid. f. rel. by \$2449.20 with San. (add \$2449.20, 48%)

RECEIVED 29 MAR 2018

Date/Time, File Pass to?

: Preli. Report

1/19/13 hunan

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

135
50
50
44
279

Report Format: TP

Lump Sum / I.B.I.: (\$ 2449.20)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005661/Uqb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-03-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7916L	Veh. Inspected	SLT 3892A
Policy No.		Coverage (\$)	0.00
Claim No.	D18002488MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	27/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	26/03/2018	Inspection Date	27/03/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002488MFSH

Date: 29 March 2018

Our Ref: CS/FCI18005661/Uqb

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 3892A .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/03/2018 at the premises of M/s PEGASUS, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 4,742.40</u> .
Revised Estimate Amount	: <u>S\$ 2,449.20</u> .
"Check" Items Amount	: <u>S\$ -</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:  
The vehicle sustained damages  
at the rear portion.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	27-03-2018	<b>Our Ref No.</b> D18002488MFSH
<b>Accident Date</b>	26-03-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA7916L	<b>Third Party Vehicle.</b> SLT3892A
<b>Survey Location</b>	51 DEFU LANE 10	
<b>Contact Person.</b>	ALVIN LOW	
<b>Contact No.</b>	68581846/ 0	<b>Fax No.</b> 64876070
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PEGASUS ENGINEERING & TRADING PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	KARENT	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236415)  PRI Documents  Close 

**PRI Header Details**

<b>Claim No</b>	D18002488MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & PE TRADIN
<b>Workshop Name</b>	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	<b>Survey Location &amp; Contact Details</b>	51 DEFU LANE 10 <b>Mobile:</b> 0 , <b>Phone:</b> 68581846 , <b>Fax:</b> 6487607 <b>EmailId:</b> CLAIMS@PEGASUSENGR.G.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	DIRECT SETTLEMENT:		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHA7916L	<b>TP Vehicle No</b>	SLT389
<b>PRI Recieved Date</b>	27-03-2018 09:26:22 PM	<b>Surveyor Appointed Date</b>	28-03-2018 03:27:55 PM	<b>Surveyor Accept Date</b>	28-03-

**Survey Report Upload**

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	28-03-2018	<b>Upload Survey Report *:</b>	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

**Vehicle Particulars**

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

**Multiple Documents Upload**

File Name	Action

**Surveyor Job Remarks**

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 29 March 2018 2:50 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18002488MFSH/1  
**Attachments:** CSFC18005661Uqb.pdf

Dear Karen,

Enclosed herewith preliminary advise of SLT 3892A.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 28 March 2018 3:45 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002488MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 28 March, 2018 3:27 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [KARENTAN@MSFIRSTCAPITAL.COM.SG](mailto:KARENTAN@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18002488MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 7200G

### Vehicle Details

Vehicle No.: SLT3892A  
Vehicle to be Exported: No  
Intended De-registration Date: 27 Mar 2018  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA3 SEDAN 1.5 AT EU6  
Primary Colour: Blue  
Manufacturing Year: 2017  
Engine No.: P520451202  
Chassis No.: JM6BN22A8H0158559  
Maximum Power Output: 88.0 kW (118 bhp)  
Open Market Value: \$15,108.00  
Original Registration Date: 27 Oct 2017  
First Registration Date: 27 Oct 2017  
Transfer Count: 0  
Actual ARF Paid: \$10,108.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 26 Oct 2027  
PARF Rebate Amount: \$7,581.00

### Intended COE Rebate Details

COE Expiry Date: 26 Oct 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$51,600.00  
COE Rebate Amount: \$49,423.00  
**Total Rebate Amount: \$57,004.00**

The information contained herein is correct as at 27 Mar 2018

OK

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

*Not Actual*

**From :**  
**PEGASUS ENGINEERING & TRADING PTE LTD**  
 C/O 51 DEFU LANE 10  
 539216  
 Officer in Charge : WEE TZE FAH  
 Tel :  
 Email :

**Customer :**  
**GRAB RENTALS PTE LTD**  
 18 SIN MING LANE  
 #01-08 MIDVIEW CITY  
 SINGAPORE 573960  
 Attn :  
 Tel :  
 Fax :

*27/03 - confirmed w/ Marcus*  
*27/3/18*  
*3 dr.*  
*27/3 2449.20*

Quotation No : QO18/03-1241	Quotation Date : 27/03/2018	Terms : 30 DAYS
Vehicle No : SLT3892A	Chassis No : JM6BN22A8H0158559	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHA7916L, DATE OF ACCIDENT: 26.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
1	REAR BUMPER <i>Dis</i>	1	1,075.0000	1,075.00	✓
2	REAR BUMPER REINFORCEMENT <i>1</i>	1	538.0000	538.00	X
3	REAR BUMPER SIDE RETAINER <i>but</i>	2	37.0000	74.00	✓
4	REAR BUMPER SIDE HOLDER <i>11</i>	2	46.0000	92.00	X
5	REAR BUMPER SIDE HOLDER RIVETS <i>11</i>	4	5.0000	20.00	X
6	REAR BUMPER CLIPS <i>11</i>	8	5.0000	40.00	✓
7	REAR BUMPER TOW COVER <i>11</i>	1	17.0000	17.00	✓
8	REAR BUMPER CENTRE BRACKET <i>11</i>	1	10.0000	10.00	X
9	REAR BUMPER REFLECTOR <i>11</i>	2	51.0000	102.00	X
10	BOOTLID CENTRE LOGO BADGE <i>11</i>	1	75.0000	75.00	✓
11	BOOTLID CENTRE MAZDA 3 BADGE <i>11</i>	1	54.0000	54.00	✓
12	BOOTLID SKYACTIV BADGE <i>11</i>	1	64.0000	64.00	✓
13	REAR END PANEL <i>11</i>	1	506.0000	506.00	X
14	REAR END PANEL INNER TRIM <i>11</i>	1	86.0000	86.00	X
15	LESS 20% (ITEM 1 - 14)	1	-550.6000	-550.60	
16	REAR BUMPER PARKING SENSOR <i>1 set</i>	1	500.0000	500.00	200
17	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00	50
18	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	120.0000	120.00	60
19	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	50.0000	50.00	20
20	TO RUST PROOFING OF THE AFFECTED AREAS	1	100.0000	100.00	X
21	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. REPAIR BOOTLID	1	850.0000	850.00	400

*7-1399*  
*1119.2*

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216
Officer in Charge : WEE TZE FAH
Tel :
Email :

<b>Customer :</b>
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn :
Tel :
Fax :

Quotation No : QO18/03-1241	Quotation Date : 27/03/2018	Terms : 30 DAYS
Vehicle No : SLT3892A	Chassis No : JM6BN22A8H0158559	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: FIRST CAPITAL, INSURED'S VEH NO: SHA7916L, DATE OF ACCIDENT: 26.03.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
22	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	800.0000	B/F 0.00 <i>600</i> 800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

<b>Sub Total</b>	4,742.40
<b>GST(7.00%)</b>	331.97
<b>Total (SGD)</b>	5,074.37

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005661/Uqbn2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-04-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHA 7916L	<b>Veh. Inspected</b>	SLT 3892A
<b>Policy No.</b>	D-18088936MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D18002488MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KARENT	<b>Assign Date</b>	27/03/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 3 (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JM6BN22A8H0158559	<b>Colour</b>	BLUE
<b>Odometer</b>	28768	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	BRIDGESTONE	8 mm
<b>L/H Front Tyre</b>	205/60 R16	BRIDGESTONE	8 mm
<b>R/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	8 mm
<b>L/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	8 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	26/03/2018	<b>Inspection Date</b>	27/03/2018
<b>Survey held at</b>	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 3892A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	DISTORTED	1,075.00	1,075.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	538.00	-
2	REAR BUMPER SIDE RETAINER @\$37.00	BENT	74.00	74.00
2	REAR BUMPER SIDE HOLDER @\$46.00	NOT NECESSARY	92.00	-
4	REAR BUMPER SIDE HOLDER RIVETS @\$5.00	NOT NECESSARY	20.00	-
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
1	REAR BUMPER TOW COVER	TORN	17.00	17.00
1	REAR BUMPER CENTRE BRACKET	NOT NECESSARY	10.00	-
2	REAR BUMPER REFLECTOR @\$51.00	NOT NECESSARY	102.00	-
1	BOOTLID CENTRE LOGO BADGE	NECESSARY	75.00	75.00
1	BOOTLID CENTRE MAZDA 3 BADGE	NECESSARY	54.00	54.00
1	BOOTLID SKYACTIV BADGE	NECESSARY	64.00	64.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	506.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	86.00	-
	LESS 20% DISCOUNT		-550.60	-279.80
			2,202.40	1,119.20
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	500.00	200.00
			500.00	200.00
<b>LABOUR</b>				
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		120.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		50.00	20.00
	TO RUST PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	100.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION. REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. REPAIR BOOTLID. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR ED PANEL.		850.00	400.00

Report Ref No. CS/FCI18005661/Uqbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		800.00	600.00
			2,040.00	1,130.00
	<b>GRAND TOTAL</b>		<b>4,742.40</b>	<b>2,449.20</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,449.20</b>

Report Ref No. CS/FCI18005661/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.