



樹發汽車修理廠 SHU FATT AUTO WORKS

8-11P

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
27th March 2018
TP

SLD 283 L TOYOTA HARRIER

		S\$
Spare Parts	1 Frt bumper.	1570.92 <i>scr</i>
	1 Set frt bumper clips.	58.80 <i>na</i>
	2 Frt bumper side retainers. @\$92.71	185.42 <i>X</i>
	1 Rt frt fog light garnish.	184.31 <i>X</i>
	1 Frt bumper lower garnish.	377.80 <i>X</i>
		2377.25
		Less 20% <i>25%</i>
		475.45
		1401.80
Labour	To knock frt support panel, left frt fender, renew frt bumper and assembly.	550.00 <i>200</i>
	To respray damaged parts.	720.00 <i>250</i>
		2671.80

Bridgestone 235/55R18
ZSU60- 0073470
22898

Rasul
Hp 90010068
2 days
4/3 or 7/10
27/03/18 @ 1345

Reg by or after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: