



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFM 6444Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	28.00	-
1	REAR BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-5.60	-
			22.40	-
	LABOUR			
	TO KNOCK AND STRAIGHTEN ON REAR BUMPER, REAR FENDER LH. TO ALIGN CONNECTION. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER.		350.00	200.00
	TO SPRAY PAINT ON REAR BUMPER & REAR FENDER LH.		500.00	400.00
			850.00	600.00
	GRAND TOTAL		872.40	600.00
	RECOMMENDED COST OF REPAIRS			600.00

Report Ref No. CS/FC118005679/R1rd3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.