

22/03/2018

ASS. REC. BY:

REF:

es/FCI18005683/mlgd3/n2

Special Instruction:

Survivor:

CWS

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

27/3/18 @ 3:33pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S12 4282X

Insured:

SHD 3898R

at Workshop m/s

CarCrafters

Tel:

62679916

of

48 Toh Guan Rd East # 05-155

Policy No:

D18088936MFSH

Claim No:

D18002433MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/3/2018

03/04/18 @ Before 12pm

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

lop

Date/Time:

4:01pm @ 27/3/18

Person Contacted:

Fais

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

S12 4282X - X

SHD 3898R - es/FCI17013870/Tlgbn2

D.O.A: 14/07/2017

04/4/18 @ 7:21pm advised to Eileen Lee by email.

26/4/18 @ 4:04pm confirmed with Faisai is \$3750, 4 days.

(Red \$9986, 73%)

REF: FCI

ASSIGNMENT

From:

Date:

3/4/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJZ 4282X

at Workshop m/s

Car Crafters

of

48 Toh Guan Rd East #05-155

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Before 12pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS / wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJZ 4282X

Yr Regn:

FEB 2012

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN TIGUAN c.c. 1924

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

87534

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVG 2225 N2 CWB 12381

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/40/19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CON

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

22/03/2018

D.O.I.

3/4/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 27 APR 2018

Date/Time: File Pass to?



Preli. Report

1/2/4 m/s



Final Report

Date/Time: File Return to?

2)

Report Format:

TP

Lump Sum / I.B.A. (\$)

3750

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation

\$ + PS \$

Photos

Others

TOTAL

3x15 = 45

170 + 45

50

50

30

345



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005683/M1qd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3898R	Veh. Inspected	SJZ 4282X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002433MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/03/2018	Inspection Date		
Survey held at	CARCRAFTERS SINGAPORE PTE LTD 48 TOH GUAN ROAD EAST #05-155 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	26-03-2018	Our Ref No. D18002433MFSH
Accident Date	22-03-2018	Claim Type. Third Party
Insured Vehicle	SHD3898R	Third Party Vehicle. SJZ4282X
Survey Location	48 Toh Guan Road East #05-155 Enterprise Hub	
Contact Person.	MD FAISAL BIN MASRIF	
Contact No.	62679916/ 86831844	Fax No. 62679313
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CARCRAFTERS SINGAPORE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236348)



PRI Documents



Close



PRI Header Details

Claim No	D18002433MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CARCRAF
Workshop Name	CARCRAFTERS SINGAPORE PTE LTD (Contact Person : MD FAISAL BIN MASRIF)	Survey Location & Contact Details	48 Toh Guan Road East #05-155 Enterprise Hub Mobile: 86831844 , Phone: 62679916 , Fax: 6267931: EmailId: FAISAL@CARCRAFTERS.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3898R	TP Vehicle No	SJZ4282X
PRI Recieved Date	26-03-2018 07:52:20 PM	Surveyor Appointed Date	27-03-2018 03:31:53 PM	Surveyor Accept Date	27-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Faisal - CarCrafters Singapore <faisal@carcrafters.sg>
Sent: Thursday, 26 April 2018 4:04 PM
To: Shiau Chan (LKKAUTO)
Cc: Admin A; Ma C.F (LKKAUTO); SUR; EILEENLEE@msfirstcapital.com.sg; Tony - CarCrafters Singapore; Farez - CarCrafters Singapore
Subject: Re: FINALISE REPAIR ESTIMATE & PHOTO AFTER PAINT SJZ4282X


Hi Shiau,

We confirmed to accept your offer of \$3,750.00 before GST with 4 working days repaired.

Thanks.

Best Regards,

Md Faisal Bin Masrif



CarCrafters Singapore Pte Ltd
48 Toh Guan Road East, #05-155 Enterprise Hub
Singapore 608586

Tel: (65) 6267 9916
Fax: (65) 6267 9313
Towing: (65) 6795 5005
Spray Paint & Bodywork Specialist
www.carcrafters.sg

On Mon, Apr 23, 2018 at 11:08 AM, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Faisal,

Offer Lump Sum \$3,750.00 before GST and 4 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 April 2018 2:21 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002433MFSH/1
Attachments: CSFCI18005683M1qd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SJZ 4282X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 27 March 2018 4:04 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002433MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 March 2018 3:31 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002433MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002433MFSH

Date: 04 April 2018

Our Ref: CS/FCI18005683/M1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJZ 4282X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/04/2018 at the premises of M/s CARCRAFTERS, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,697.52</u>
Revised Estimate Amount	: S\$ <u>4,720.00</u>
"Check" Items Amount	: S\$ <u>2,798.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

Ma C.F.
Automotive Assessor

Sketch Plan Pg. 1

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel: (65) 63387288 Fax: (65) 63382522
Website: www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



Private Cars COMP
POLICY SCHEDULE
RENEWAL
Original

POLICY INFORMATION		Policy No. : VPA/P1884507	
Source	:	(01) 13950 META (PA/HOME X SELL 20110901)	
Insured	:	WONG PAK KIONG	
Address	:	39 BANGKIT ROAD #06-04 SINGAPORE 679977	
Business/Profession	:	MANAGEMENT / DIRECTOR / CEO Carrying on or engaged in the business or profession last declared and no other for the purpose of this insurance.	
Period of Insurance : From 20/02/2018 To 19/02/2019 (Both Dates Inclusive)			
Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.			
PREMIUM			
Premium After 50.00% : SGD 672.82			
NCD			
Safe Driver	Disc :	SGD 67.28	
10.00%			
GST	7.00%	:	SGD 42.39
Annual Premium	:	SGD 647.93	
Total Payable	:	SGD 647.93	
RISK DETAILS THE MOTOR VEHICLE			
Type Of Cover	:	Comprehensive	
Regn No.	:	SJZ4282X	
Type Of Use	:	Private Car	
Make/Model	:	VOLKSWAGEN TIGUAN 2.0 TSI AT 5N22N9	
Year of Manufacture	:	2011	Seating Capacity (excl. Driver) : 04
Body Type	:	SPORTS UTILITY VEHICLE	Engine C.C. : 1984
Engine No.	:	CC2179263	
Chassis No.	:	WVGZZZ5NZCW012381	
Insured's Estimated Market Value	:	Market Value At The Time Of Loss (including Accessories and Spare Parts)	
Limitations as to Use : As specified in Certificate of Insurance			
<u>Extra Coverage(Premium Breakdown)</u>		<u>Limits (SGD)</u>	<u>Premium (SGD)</u>
NCD Protector			
Basic Own Damage Excess		:	SGD 400.00
<u>Named Drivers</u>			
1 WONG PAK KIONG			
2 TENG SHUN LI			

Page 1

Owner & driver



Hp: 81127939

email: jackboss2416@yahoo.com.sg

Pax: 1

Condition: Dry

Weather: Clear



First Capital Insurance Ltd

Our Client,

WONG PAK KIONG

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East

#05-155, Enterprise Hub

Singapore 608586

Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

Date : 3/4/2018

Vehicle Num SJZ4282X

Make/Model : VOLKSWAGEN TIGUAN 2.0

Chassis No : WVGZZZ5NZCW012381

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR BUMPER	1 pc	\$ 950.00	\$ 950.00
2	LOWER SPOILER	1 pc	\$ 320.00	\$ 320.00
3	REINFORCEMENT	1 pc	\$ 600.00	\$ 600.00
4	REAR BUMPER GUIDE PIECE LH	1 pc	\$ 48.00	\$ 48.00
5	REAR BUMPER GUIDE PIECE RH	1 pc	\$ 48.00	\$ 48.00
6	REAR APRON	1 pc	\$ 380.00	\$ 380.00
7	END PANEL	1 pc	\$ 625.00	\$ 625.00
8	REAR HOOD LATCH	1 pc	\$ 180.00	\$ 180.00
9	LICENSE PLATE BRACKET	1 pc	\$ 110.00	\$ 110.00
10	REAR TRUNK LID	1 pc	\$ 1,670.00	\$ 1,670.00
11	STRIKER	1 pc	\$ 48.00	\$ 48.00
12	REAR WEATHERSTRIP	1 pc	\$ 295.00	\$ 295.00
13	TAILLIGHT INNER LH	1 pc	\$ 230.00	\$ 230.00
14	TAILLIGHT INNER RH	1 pc	\$ 230.00	\$ 230.00
15	TAILLIGHT OUTER LH	1 pc	\$ 285.00	\$ 285.00
16	TAILLIGHT OUTER RH	1 pc	\$ 285.00	\$ 285.00
17	LICENSE PLATE LIGHT	2 pcs	\$ 38.00	\$ 76.00
18	TOWING EYE COVER	1 pc	\$ 28.00	\$ 28.00
19	SUPPORT LIGHT BULB LH	1 pc	\$ 67.00	\$ 67.00
20	SUPPORT LIGHT BULB RH	1 pc	\$ 67.00	\$ 67.00
21	REFLECTOR LH	1 pc	\$ 47.00	\$ 47.00
22	REFLECTOR RH	1 pc	\$ 47.00	\$ 47.00
23	FLOOR PAN	1 pc	\$ 1,385.00	\$ 1,385.00
24	REAR SENSOR	2 pcs	\$ 162.00	\$ 324.00
25	REAR EXHAUST SILENCER	1 pc	\$ 990.00	\$ 990.00
26	DUAL CLAMP	1 pc	\$ 66.00	\$ 66.00
TOTAL AMOUNT				\$ 9,401.00
MISCELLANEOUS ITEM				
	CARPLATE NUMBER WITH CASING	1 pc	\$ 35.00	\$ 35.00
LABOUR				
1	To remove/ replace/ refit of rear portion of realigned rear bumper, reinforcement, trunk lid & other affected area.		check	\$ 1,500.00
2	To putty & respray trunk lid, rear bumper, end panel, luggage compartment, rear both fenders & other affected area.			\$ 2,000.00
3	To remove/replace/refit of end panel & luggage compartment & taillight panel.			\$ 400.00

4	To check accident affected wiring system & recover.		\$ 20	20
5	To recode & decode engine management system & fault code clearing after repair works.		\$ 100.00	80
6	To remove & replace of rear windscreen.		\$ 150.00	X
7	To remove & replace of rear exhaust silencer.		\$ 100.00	50
	TOTAL		\$ 13,736.00	
	GST 7%		\$ 961.52	
	GRAND TOTAL		\$ 14,697.52	

Not Authorised
 R/S Repair
 After paint Pk
 LKK Auto
 4 wks days
 3/4/2018


 4/4/18

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



First Capital Insurance Ltd

Our Client,
WONG PAK KIONG

Finalise Repair Estimate

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East

#05-155, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

Date : 11/4/2018

Vehicle Num SJZ4282X

Make/Model : VOLKSWAGEN TIGUAN 2.0

Chassis No : WYGZZZ5NZCW012381

S/N	PARTS	QTY	PRICE	TOTAL
1	REAR BUMPER	1 pc	\$ 950.00	\$ 950.00
2	LOWER SPOILER	1 pc	\$ 320.00	\$ 320.00
3	REINFORCEMENT	1 pc	\$ 600.00	\$ 600.00
4	REAR BUMPER GUIDE PIECE LH	1 pc	\$ 48.00	\$ 48.00
5	REAR BUMPER GUIDE PIECE RH	1 pc	\$ 48.00	\$ 48.00
6	REAR APRON	1 pc	\$ -	\$ -
7	END PANEL	1 pc	\$ -	\$ -
8	REAR HOOD LATCH	1 pc	\$ -	\$ -
9	LICENSE PLATE BRACKET	1 pc	\$ -	\$ -
10	REAR TRUNK LID	1 pc	\$ -	\$ -
11	STRIKER	1 pc	\$ -	\$ -
12	REAR WEATHERSTRIP	1 pc	\$ -	\$ -
13	TAILLIGHT INNER LH	1 pc	\$ -	\$ -
14	TAILLIGHT INNER RH	1 pc	\$ -	\$ -
15	TAILLIGHT OUTER LH	1 pc	\$ -	\$ -
16	TAILLIGHT OUTER RH	1 pc	\$ -	\$ -
17	LICENSE PLATE LIGHT	2 pcs	\$ -	\$ -
18	TOWING EYE COVER	1 pc	\$ 28.00	\$ 28.00
19	SUPPORT LIGHT BULB LH	1 pc	\$ -	\$ -
20	SUPPORT LIGHT BULB RH	1 pc	\$ 67.00	\$ 67.00
21	REFLECTOR LH	1 pc	\$ -	\$ -
22	REFLECTOR RH	1 pc	\$ -	\$ -
23	FLOOR PAN	1 pc	\$ -	\$ -
24	REAR SENSOR	2 pcs	\$ 162.00	\$ 324.00
25	REAR EXHAUST SILENCER	1 pc	\$ 990.00	\$ 990.00
26	DUAL CLAMP	1 pc	\$ -	\$ -
	TOTAL AMOUNT			\$ 3,375.00
	MISCELLANEOUS ITEM			
	CARPLATE NUMBER WITH CASING	1 pc	\$ 35.00	\$ 35.00
	LABOUR			
1	To remove/ replace/ refit of rear portion of realigned rear bumper, reinforcement, trunk lid & other affected area.		\$ 1,500.00	\$ 500.00
2	To putty & respray trunk lid, rear bumper, end panel, luggage compartment, rear both fenders & other affected area.		\$ 2,000.00	\$ 500.00
3	To remove/replace/refit of end panel & luggage compartment & taillight panel.		\$ 400.00	\$ 150.00

4	To check accident affected wiring system & recover.	\$	50.00	\$	20.00
5	To recode & decode engine management system & fault code clearing after repair works.	\$	100.00	\$	80.00
6	To remove & replace of rear windscreen.	\$	150.00	\$	-
7	To remove & replace of rear exhaust silencer.	\$	100.00	\$	50.00
	TOTAL			\$	4,710.00
	GST 7%			\$	329.70
	GRAND TOTAL			\$	5,039.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005683/M1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3898R	Veh. Inspected	SJZ 4282X	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002433MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TIGUAN	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WVGZZZ5NZCW012381	Colour	BLACK	
Odometer	87534	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/40 R19	CONTINENTAL	8 mm	
L/H Front Tyre	255/40 R19	CONTINENTAL	8 mm	
R/H Rear Tyre	255/40 R19	CONTINENTAL	8 mm	
L/H Rear Tyre	255/40 R19	CONTINENTAL	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/03/2018	Inspection Date	03/04/2018	
Survey held at	CARCRAFTERS SINGAPORE PTE LTD 48 TOH GUAN ROAD EAST #05-155 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 4282X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	950.00	950.00
1	LOWER SPOILER	DEFORMED	320.00	320.00
1	REINFORCEMENT	BENT	600.00	600.00
1	REAR BUMPER GUIDE PIECE LH	DISTORTED	48.00	48.00
1	REAR BUMPER GUIDE PIECE RH	DISTORTED	48.00	48.00
1	REAR APRON	NOT NECESSARY	380.00	-
1	END PANEL	NOT NECESSARY	625.00	-
1	REAR HOOD LATCH	SERVICEABLE	180.00	-
1	LICENSE PLATE BRACKET	TO REPAIR SEE LABOUR	110.00	-
1	REAR TRUNK LID	TO REPAIR SEE LABOUR	1,670.00	-
1	STRIKER	SERVICEABLE	48.00	-
1	REAR WEATHERSTRIP	NOT NECESSARY	295.00	-
1	TAILLIGHT INNER LH	SERVICEABLE	230.00	-
1	TAILLIGHT INNER RH	SERVICEABLE	230.00	-
1	TAILLIGHT OUTER LH	NOT NECESSARY	285.00	-
1	TAILLIGHT OUTER RH	NOT NECESSARY	285.00	-
2	LICENSE PLATE LIGHT @\$38.00	NOT NECESSARY	76.00	-
1	TOWING EYE COVER	DISTORTED	28.00	28.00
1	SUPPORT LIGHT BULB LH	NOT NECESSARY	67.00	-
1	SUPPORT LIGHT BULB RH	CRACKED	67.00	67.00
1	REFLECTOR LH	NOT NECESSARY	47.00	-
1	REFLECTOR RH	NOT NECESSARY	47.00	-
1	FLOOR PAN	NOT NECESSARY	1,385.00	-
2	REAR SENSOR @\$162.00	SHORTED	324.00	324.00
1	REAR EXHAUST SILENCER	BENT	990.00	990.00
1	DUAL CLAMP	NOT NECESSARY	66.00	-
			9,401.00	3,375.00
SPECIAL NETT ITEMS				
1	CARPLATE NUMBER WITH CASING (SN)	CUT	35.00	35.00

Report Ref No. CS/FCI18005683/M1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			35.00	35.00
	LABOUR			
	TO REMOVE/REPLACE/REFIT OF REAR PORTION OF REALIGNED REAR BUMPER,REINFORCEMENT,TRUNK LID & OTHER AFFECTED AREA.INCLUSIVE OF THE REPAIR OF LICENSE PLATE BRACKET AND REAR TRUNK LID.		1,500.00	500.00
	TO PUTTY & RESPRAY TRUNK LID,REAR BUMPER,END PANEL,LUGGAGE COMPARTMENT,REAR BOTH FENDERS & OTHER AFFECTED AREA.		2,000.00	500.00
	TO REMOVE/REPLACE/REFIT OF END PANEL & LUGGAGE COMPARTMENT & TAILLIGHT PANEL.		400.00	150.00
	TO CHECK ACCIDENT AFFECTED WIRING SYSTEM & RECOVER.		50.00	20.00
	TO RECODE & DECODE ENGINE MANAGEMENT SYSTEM & FAULT CODE CLEARING AFTER REPAIR WORKS.		100.00	80.00
	TO REMOVE & REPLACE OF REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE & REPLACE OF REAR EXHAUST SILENCER.		100.00	50.00
			4,300.00	1,300.00
	GRAND TOTAL		13,736.00	4,710.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CS/FCI18005683/M1qd3n2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.