



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singapore.sg
Bus. Reg. No. 251513/00M

DA/AIG(SLJ1296L)
DOA: 23/03/2018@2120

AIG ASIA PACIFIC INSURANCE PTE LTD
ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SJH 747 T - SUBARU IMPREZA 5D 1.5R AWD 5MT
CHASSIS NO: JF1GH3KW48G015116 (2008)

1 pc	Rear door LH	\$ 655.80	74
1 pc	Rear door frame sticker LH	\$ 78.50	new
1 pc	Front door LH	\$ 685.30	R
1 pc	Front door frame sticker LH	\$ 85.70	X
1 pc	LH rocker panel LH	\$ 528.60	74
1 pc	Rear fender LH	\$ 1,247.20	74
1 pc	Rear mudflag LH	\$ 175.80	cut / price?
		\$ 3,456.90	
	LESS 25%	\$ 864.23	
		\$ 2,592.67	
1 pc	Sealant	\$ 35.00	
	Remove and reinstall rear windscreen LH	\$ 120.00	80
	Repair and respray rear rim LH	\$ 100.00	50
	Remove and install all cushions, seats, back rest, inner trim garnish, roof lining and upholstery to facilitate repairs.	\$ 180.00	80
	Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear fender LH, LH rocker panel, rear LH door and front door LH.	\$ 1,200.00	800
	Putty and respray rear fender LH, LH rocker panel, rear door LH and front door LH.	\$ 900.00	700
		\$ 5,127.67	
	ADD 7% GST	\$ 358.94	
		\$ 5,486.61	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

[Signature]

the Repairer of the following:
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rahul
Ap 90010068
8 days
4/8
04/04/18 @ 1155
Resurvey after repair