

REF: NTUC

NS/INC18005692 / Sgpn2

ASSIGNMENT

From:

Date: 26/3/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SG1713H

at Workshop m/s

SMRT

of

Insured:

SKQ 9751L

Policy No.

5069514535-03 090118-080199

Claims No.

MT/0986581-002

Sum Insured:


Excess

(Client's Record)

Make of Veh:

Sunny

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SG1713H

Yr Regn:

4/5/2016

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAN NL320F

C.C. 10518

Colour:

Green

A/C:

Insured / Std / NI / NA

Sp. Reading:

123707

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WMH4226281-7007884

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F: 275/70R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Finn 79

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

17/3/18

D.O.I.

26/3/18

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / NI / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18005692/Sqb			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 27-03-2018	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKQ 9751L	Veh. Inspected	SG 1713H
Policy No.	5069514535-03	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/03/2018	Inspection Date	26/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident
1	MT/0989874-002	SMRT TAXIS PTE LTD	SHB 5952P	FM 6777M	06/04/2018
2	MT/0988647-002	SMRT TAXIS PTE LTD	SHB 1892E	SKE 5210X	30/03/2018
3	MT/0986581-002	SMRT BUSES LTD	SG 1713H	SKQ 9751L	17/03/2018

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	SD69514535-03	KOH LIN HOE	S0131097F	GPC	drive CLASSIC	SKQ9751L	SKQ9751L	09/01/2018	08/01/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/03/2018 14:52
Date Of Accident	17/03/2018 15:05
Exact Location Of Accident	UPPER THOMSON RD BEFORE BS 56021
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SG1713H
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	MAN
Model	MAN A22

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-17087563MFBP
Cover Note Number	

Driver

Name of Driver	MAH TEOW YANG
NRIC No	S1194028E
Date Of Birth	12/01/1956
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1978
Driving Experience	39 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NOADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 30

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

At the stated date and time, I was traveling along Upper Thomson Rd (before BS: 56021 - opposite Sembawang Hill FC) when one private car that was coming out from the side road (Old Upper Thomson Rd) collided into the left centre portion of the bus. From my left view mirror I can see that the private car did not stop even when my bus passed by. No injuries reported

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKQ9751L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver XU REN HAO

NRIC/Passport Number S0131097F

Contact Number 96801437

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver) 1

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

2292D

Vehicle Details

Vehicle No.:

SG1713H

Vehicle to be Exported:

No

Intended De-registration Date:

27 Mar 2018

Vehicle Make:

MAN

Vehicle Model:

NL 320F (A22) 11L AUTO ABS TURBO

Primary Colour:

Multi-Colour

Manufacturing Year:

2015

Engine No.:

50340681654077

Chassis No.:

WMAA22ZZ8F7002884

Maximum Power Output:

\$238,661.00

Open Market Value:

04 May 2016

Original Registration Date:

04 May 2016

First Registration Date:

0

Transfer Count:

\$0.00

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Rebate Amount:

\$0.00

Total Rebate Amount:

\$0.00


The information contained herein is correct as at 27 Mar 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre


Reg. No : SG1713H
Ref. No : BUS/03/18/7026
Reg. Date : 19/03/2018
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Mah Teow Yang
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 17/03/2018 03:03:00 PM
Accident Reported Date / Time : 19/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC,if any :
SG1713H - LEFT CENTRE TO RIGHT PORTION
SKQ9751L (TP) - INSURED WITH NTUC.
Prepared Date : 19/03/2018 10:12:28 AM



SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1713H
 Ref. No : BUS/03/18/7026
 Reg. Date : 19/03/2018
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : Mah Teow Yang
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 17/03/2018 03:03:00 PM
 Accident Reported Date / Time : 19/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : IDAC
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 SG1713H - LEFT CENTRE TO RIGHT PORTION
 SKQ9751L (TP) - INSURED WITH NTUC.
 Prepared Date : 19/03/2018 10:12:28 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian
27/3/18

- Part by part repair.
- Photo Before & After Paint

[Signature]
28/3/18

Chassis No :

Work Shop :

Mileage

0

Repair Completed Date / Time :

Summary of Repair Estimates

Adjusted by Surveyor, if applicable

Total Labour Charges : 2,120.00

Total Spray Painting Charges : 1,112.00

Total Material Charges : 652.32

Other Charges : 0.00

TOTAL : 3,884.32

Lum Sum Total : 0.00

No. of Repair Days : 5.00

Prepared / Adjusted By : Sunny Tan Ah Leong

Arc / Surveyor Sing Off Date : 26/03/2018 10:47:52 AM

01/01/1900 12:00:00 AM

4 days



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/03/2018 10:47:45 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	2,120.00	0.00 1800
Total Labour	2,120.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,112.00	0.00 900
Total Spray Painting & Panel Beating	1,112.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
4000F06-HING733		6010318	HINGE RH SIDE FLAP	2	181.20	10.00	326.16	Replace	Replace	No ✓
4000F06-HING732		6010317	HINGE LH SIDE FLAP	2	181.20	10.00	326.16	Replace	Replace	No ✓
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)										
652.32 652.32										


Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG1713H
Ref. No : BUS/03/18/7026
Reg. Date : 04/05/2016
Vehicle Type : BUS -12M
Make : MAN
Model : MAN
Name of Driver : Mah Teow Yang
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 17/03/2018 03:03:00 PM
Accident Reported Date / Time : 19/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : IDAC
Vehicle is Towed Back? : No
Towed Back Date/Time : 01/01/2000
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095246
Special Instruction to ARC, if any :
SG1713H - LEFT CENTRE TO RIGHT PORTION
SKQ9751L (TP) - INSURED WITH NTUC.
Prepared Date : 19/03/2018 10:12:28 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WMAA22ZZ8F7002884 Mileage : 0
Work Shop : Repair Completed Date / Time : 01/01/2000

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,120.00	1,800.00
Total Spray Painting Charges	: 1,112.00	900.00
Total Material Charges	: 652.32	652.32
Other Charges	: 0.00	0.00
TOTAL	: 3,884.32	3,352.32
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	4.00
Prepared / Adjusted By	: Sunny Tan Ah Leong	SEBASTIAN-LKK
Arc / Surveyor Sign Off Date	: 26/03/2018 10:47:52 AM	27/03/2018 10:43:05 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/03/2018 10:47:45 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	2,120.00	1,800.00
Total Labour	2,120.00	1,800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,112.00	900.00
Total Spray Painting & Panel Beating	1,112.00	900.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
4000F06-HING733		6010318	HINGE RH SIDE FLAP	2	181.20	10.00	326.16	Replace	Replace	No /
4000F06-HING732		6010317	HINGE LH SIDE FLAP	2	181.20	10.00	326.16	Replace	Replace	No /
TOTAL MATERIALS							652.32	652.32		
TOTAL MATERIALS(Discounted)							652.32	652.32		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

652.32
 1800.00
 + 900.00

 3352.32

Sebastian
 23/4/18

3856.80



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18005692/Sqbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 02-05-2018
189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKQ 9751L	Veh. Inspected	SG 1713H
Policy No.	5069514535-03	Coverage (\$)	0.00
Claim No.	MT/0986581-002	Excess (\$)	0.00
Assign From		Assign Date	26/03/2018

2. Vehicle Particulars & Condition

Make & Model	MAN NL 320F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WMAA22ZZ8F7002884	Colour	GREEN
Odometer	123909	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm
L/H Rear Tyre	275/70 R22.5 (D)	FIRENZA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/03/2018	Inspection Date	26/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 1713H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	HINGE RH SIDE FLAP @\$181.20	BENT	362.40	362.40
2	HINGE LH SIDE FLAP @\$181.20	BENT	362.40	362.40
	LESS 10% DISCOUNT		-	-72.48
			724.80	652.32
LABOUR				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		2,120.00	1,800.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		1,112.00	900.00
			3,232.00	2,700.00
GRAND TOTAL			3,956.80	3,352.32
RECOMMENDED COST OF REPAIRS (CONFIRMED)				3,352.32

Report Ref No. NS/INC18005692/Sqbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.