



NAI SOO TONG
SINGAPORE

File No :
Date : 26-March-2018

Estimated cost of repair for vehicle no: **SGS91D TOYOTA LEXUS**
Accident involving vehicle no: **SGS91D & SFJ6556A on 16-February-2018**

Description	Quantity	List Price
LH front fender	1	\$ 821.70
Front bumper	1	\$ 721.50
LH head lamp	1	\$ 2,783.65
LH front bumper retainer	1	\$ 72.50
LH front fender wheel cowling	1	\$ 324.50
LH front fender wheel cowling clips @ 1 set	1	\$ 45.00
		\$ 4,768.85
	Less 25%	\$ 1,192.21
		\$ 3,576.66
Labour to remove front bumper , LH front fender, panel beating, repair LH front door, LH head lamp inner panel, LH bumper brecket, renew , install and adjust LH front door, front bumper alignment.	1	\$ 480.00
To spray paint LH front door, front fender, front bumper and accident repair areas.	1	\$ 750.00
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ 30.00
		\$ 4,836.66

T/Party: AXA INSURANCE PTE LTD