

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0375/2018/JT
Date : 27-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Soo Man Kuen Catherine
Address : 65 Jalan Lanjut

Singapore 577708

Telephone : HP 65 9012 0935
Type of Claim : Third party claims
Policy No. : 10676521
Vehicle No : **SLE 112 S**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Oct-15
Engine No : CNC 138395
Chassis No : WAUZZZ8R9GA041264
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Mar-18
Place of Accident : Holland Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLE 112 S.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00 ✓	
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00 ✓	
3	To dismantle and renew rear bumper and rear lid. Inspect rear end panels for damage. Re-organize rear crash management components. Reinstall all parts removed.		\$ 2,100.00	1250 (2.5 Days inclusive of repairs to end panel)
4	To respray rear bumper, lower spoiler and rear lid.		\$ 2,200.00	137.5 (2.5 pieces)
5	To renew rear windscreen.	S/N	\$ 480.00 ✓	
6	To renew centre and LHS rear exhaust silencer.	S/N	\$ 480.00 ?	
7	To carry out diagnostic checks.	S/N	\$ 192.00 ✓	
TOTAL LABOUR CHARGES		:	<u>\$ 6,012.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 112 S.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>deformed</i>	\$ 1,430.00	✓
2	REAR BUMPER SPOILER <i>deformed</i>	\$ 749.00	✓
3	GROMMET ?	\$ 20.00	?
4	REAR BUMPER GUIDE - LHS/RHS <i>new</i>	\$ 92.00	X.
5	REAR PARKING AID - INNER ?	2 \$ 421.00	?
6	REAR PARKING AID - OUTER <i>new</i>	2 \$ 392.00	X.
7	REAR PARKING AID WIRING SET <i>new</i>	\$ 515.00	X
8	REAR REINFORCEMENT BEAM ?	\$ 571.00	?
9	REAR BUMPER FIXING PARTS <i>new</i>	\$ 143.00	X
10	REINFORCEMENT BEAM BOLTS ?	4 \$ 29.00	?
11	REAR BUMPER HOLDER - LHS/RHS <i>new</i>	\$ 368.00	X.
12	REAR LID <i>deformed</i>	\$ 3,844.00	✓
13	REAR LID ATTACHMENT PARTS <i>new</i>	\$ 106.00	✓
14	BALL STUD <i>new</i>	\$ 36.00	+
15	LID LOCK <i>new</i>	\$ 157.00	+
16	REAR LID CHROME TRIM <i>at</i>	\$ 377.00	✓
17	ADHESIVE <i>2</i>	\$ 15.00	✓
18	AUDI EMBLEM <i>new</i>	\$ 108.00	✓
19	"Q5" EMBLEM	\$ 83.00	✓
20	"TFSI" EMBLEM	\$ 83.00	✓
SUB-TOTAL SPARE PARTS		\$ 9,539.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLE 112 S.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
21	"quattro" EMBLEM <i>new</i>	\$ 83.00	✓
22	PRIMER <i>new</i>	\$ 19.00	✓
23	REAR LID SPOILER ATTACHMENT ?	\$ 147.00	?
24	CENTRE SILENCER ?	\$ 875.00	?
25	REAR SILENCER ?	\$ 883.00	?
26	DUAL CLIP ?	2 \$ 93.00	?
27	EXHAUST BRACKET ?	\$ 50.00	?
28	REAR WINDSCREEN ?	TBC	?
29	REAR WINDSCREEN SEALENT <i>new</i>	S/N \$ 200.00	✓
30	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 12,189.00	
TOTAL LABOUR CHARGES		\$ 6,012.00	
GRAND TOTAL		\$ 18,201.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim.
Surveyed Date : 27/03/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised , 06 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant