



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
QUOTATION



EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lim Wei Sheng, Damien ADDRESS : 33 Punggol Field #17-14 Singapore 828817 TEL : 98463900		WIP : 14960 EXCESS : DATE: 24-Mar-18	
VEH NO :	SLN902G	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6CW1071H0125329	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIMS
MODEL :	MAZDA5	DATE REG.:	21-Apr-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FASTENER, REAR BUMPER	2	MGD7A-50-EA1		\$ 6.00
2	GROMMET, REAR BUMPER	2	MC235-50-ES1		\$ 8.80
3	REAR BUMPER	1	MC513-50-221EBB		\$ 915.40
4	RETAINER RH, REAR BUMPER	1	MC513-50-2H1B		\$ 45.30
5	RETAINER LH, REAR BUMPER	1	MC513-50-2J1C		\$ 45.30
6	RIVET, REAR BUMPER	4	MBN8F-50-355		\$ 21.60
7	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A		\$ 10.00
8	REFLECTOR LH, REAR BUMPER	1	MD350-51-5M0E		\$ 50.40
9	REFLECTOR RH, REAR BUMPER	1	MD350-51-5L0E		\$ 50.40
10	BRACKET RH, REAR BUMPER	1	MC513-51-067A		\$ 5.40
11	BRACKET LH, REAR BUMPER	1	MC513-51-077A		\$ 5.40
12	FASTENER, REAR BUMPER	2	MB45A-56-146A		\$ 5.60
13	REINFORCEMENT	1	MC235-56-B9XC		\$ 148.00
14	TAPE PROTECTOR	2	MG043-62-864A		\$ 6.60
15	GROMMET, TAIL GATE	1	M9991-00-501		\$ 2.80
16	TAIL GATE	1	MCGY3-62-02XF		\$ 1,559.00
17	VALVE ONEWAY	2	MGHP9-58-867		\$ 22.80
18	WEATHERSTRIP, TAIL GATE	1	MC513-62-761C		\$ 169.00
19	RUBBER STOPPER, TAIL GATE (TOP)	2	MEG21-62-877		\$ 22.40
20	RUBBER STOPPER, TAIL GATE (BOTTOM)	2	MB25S-62-877A		\$ 34.60
21	TAPE PROTECTOR	2	MTK48-62-864		\$ 14.00
22	RUBBER STOPPER, TAIL GATE (OUTER BOTTOM)	2	MBR5S-56-994		\$ 14.40
TOTAL PARTS					\$ 3,163.20
LESS 10%					\$ 316.32
TOTAL PARTS COST					\$ 2,846.88
Labour Description					

1	MZ-BR-REAR04	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,800.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND TAILGATE.	630	\$ 2,520.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330	\$ 660.00
4	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.	NETT	\$ 560.00
5	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NETT	\$ 120.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00

3 Days.
before paint photos.
Gmo Qiang.
09/4/18.

TOTAL LABOUR	\$ -	\$ 6,360.00
TOTAL PARTS	\$ -	\$ 2,846.88
TOTAL	\$ -	\$ 9,206.88
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: