



Vfix Auto Service Pte Ltd
 60 Kaki Bukit Ave 6
 Ark@KB Singapore 417892
 Email: vfixauto@gmail.com
 Tel: 64489268 Fax: 64452368

M/S AIG ASIA PACIFIC INS PTE LTD
 CHARTIS BUILDING
 78 SHENTON WAY #08-16
 SINGAPORE 079120

*not about
 also
 1/5
 4dy
 28/3/18
 The Rep. Attorney*

ESTIMATE
 DATE : 27/03/2018
 ACC DATE : 26/03/2018
 REF NO. : VFIX-TP20180447
 POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO. SGS8681Z RENAULT KOLEOS

DESCRIPTION	AMOUNT S\$
1 1 TAIL GATE <i>lower body</i>	2,850.00 ✓
2 1 TAIL GATE GARNISH <i>11</i>	652.00 X
3 1 TAIL GATE EMBLEM (RENAULT) <i>rec</i>	240.00 ✓
4 2 TAIL GATE DAMPER R+L <i>11</i>	320.00 640.00 X
5 1 TAIL GATE WEATHERSTRIP <i>7m</i>	398.00 ✓
6 1 TAIL LAMP LH <i>11</i>	450.00 X
7 1 REAR BUMPER TOP <i>D.S</i>	1,855.00 ✓
8 1 REAR BUMPER LOWER <i>D.S</i>	850.00 ✓
9 2 REAR BUMPER LOWER BRACKET R+L	65.00 130.00 ?
10 2 REAR BUMPER SIDE RETAINER R+L <i>21</i>	85.00 170.00 ✓
11 2 REAR BUMPER SIDE BRACKET R+L	105.00 210.00 ?
12 1 REAR BUMPER CENTER REFLECTOR	295.00 ?
13 1 REAR BUMPER REFLECTOR LH	385.00 ?
14 1 REAR BUMPER REINFORCEMENT	450.00 ?
15 1 REAR END PANEL <i>2</i>	988.00 X
16 1 REAR END PANEL GARNISH <i>11</i>	455.00 X
17 1 REAR EXHUAUST MUFFLER <i>2</i>	1,450.00 2
18 2 REAR EXHUAUST MUFFLER HANGER <i>11</i>	75.00 150.00
	\$ 12,618.00

107

DESCRIPTIONS	UNIT PRICE	AMOUNT S\$
1 2 REVERSE SENSOR	180.00	360.00 <i>200</i>
2 2 REVERSE SENSOR HOLDER	45.00	90.00 ?
3 1 REAR NUMBER PLATE		40.00 ✓
		\$ 490.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LABOUR & MISCELLANEOUS:		AMOUNT S\$	
1	To remove damaged parts with all necessary components/attachments apply hot work where necessary straighten repair dented panel	600	1,400.00
2	To spray paint replaced/repaired parts inclusive of preparatory works and painting materials	800	1,400.00
3	To install reverse sensor, control box check function	50	100.00
4	To remove, refit rear windscreen glass and water test	400	200.00
5	To transfer tail gate components with all necessary attachments	60	200.00
6	To remove, replace rear exhaust with all necessary components	60	120.00
		\$	3,420.00
GRAND TOTAL		:	\$ 16,528.00

SINGAPORE DOLLARS : SIXTEEN THOUSAND FIVE HUNDRED & TWENTY EIGHT ONLY

Vfix Auto Service Pte Ltd

