

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-		Ref : CS/TP18005717/R1tbe2		
ONG POH GUAN DICKY 73, JALAN JARAKSINGAPORE 809237		Date : 05-04-2018		
		Code : TP2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SJW 4711R	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR S-TYPE2.5SE	c.c	2497	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	SAJAC01A65JN24470	Colour	BLACK	
Odometer	233592	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R17	CONTINENTAL	6 mm	
L/H Front Tyre	235/50 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	235/50 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	235/50 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/02/2018	Inspection Date	27/03/2018	
Survey held at	2 JALAN PESAWAT			
Repairer	WEARNES AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Amend modification to NIK.
10/4