

ASS. REC. BY:

REF: CS/FCI18005722/Kvd3n2 Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Aung Yin Min

of FCI

Date/Time: 28/3/18 @ 12:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG15855

Insured:

SHC0715K

at Workshop m/s:

T & T Auto Services

Tel:

6266 6876

of

Blk 19, Sin Ming Ind. Est. Sec. A # 01-19

Policy No:

Claim No:

D1800245SMFHH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

25/03/2018

CA / REV / REP. / REV 24 HRS ^{1 up?}

H.O.D. Endorsement:

Date/Time: 12:24pm @ 28/3/18

Person Contacted:

Vincent

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJG15855-X

SHC715K-CS/FCI16014416/M/vbd1

D.O.A: 29/07/2016

2/4/18

@ 240pm LS \$850 confirmed with Vincent (Ref 3643.98, 819)

2/4/18

Email preli revised to FCI

ASS. REC. BY:

REF:

17621

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

T&T

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STG 1585

Yr Regn:

06, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Axi

c.c

1598

Colour:

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

109084

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR053 ZEE106110084

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Yoko 195/65R15

R: Toyo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

25/3/18

D.O.I.

28/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/3

File pass to Cathrine

RECEIVED 03 APR 2018

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 2/4 - typist

Days Of Repair: 2

Resurvey No. of Trlp: -

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

135

Transportation:

50

S + RS. SI

50

Photos

13

Others

TOTAL

248

Report Format:

CWS

Lump Sum / I.B.I. (\$

850/2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005722/Kvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 715K	Veh. Inspected	SJG 1585S
Policy No.		Coverage (\$)	0.00
Claim No.	D18002455MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	28/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/03/2018	Inspection Date	28/03/2018
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	27-03-2018	Our Ref No. D18002455MFSH
Accident Date	25-03-2018	Claim Type. Third Party
Insured Vehicle	SHC0715K	Third Party Vehicle. SJG1585S
Survey Location	BLK 19 SIN MING INDUSTRIAL ESTATE SECTOR A#01-19	
Contact Person.	VINCENT TAN	
Contact No.	62666876/ 91459776	Fax No. 62666861
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	T & T AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236373)



PRI Documents



Close



PRI Header Details

Claim No	D18002455MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & T & T AUT
Workshop Name	T & T AUTO SERVICES PTE LTD (Contact Person : VINCENT TAN)	Survey Location & Contact Details	BLK 19 SIN MING INDUSTRIAL ESTATE SECTOR A#01-1 Mobile: 91459776 , Phone: 62666876 , Fax: 6266686 EmailId: TNTAUTOSERVICES@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0715K	TP Vehicle No	SJG1585S
PRI Recieved Date	27-03-2018 07:09:37 PM	Surveyor Appointed Date	28-03-2018 12:09:47 PM	Surveyor Accept Date	28-03-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	28-03-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 2 April 2018 2:52 PM
To: 'Claim Workflow System'
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002455MFSH/1, SJG 1585S
Attachments: SJG 1585S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJG 1585S
Date of survey: 28/3/2018
Number of days:2 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 28 March 2018 12:25 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002455MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 28 March 2018 12:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002455MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002455MFSH

Our ref: CS/FCI18005722/Kvd3

Date : 2/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJG 1585S


We thank for your instruction on 28/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 28/3/2018 at the premises of M/s T&T AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,493.98
Revised Estimate Amount	: S\$850.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2317L
Vehicle Details	
Vehicle No.:	SJG15855
Vehicle to be Exported:	No
Intended De-registration Date:	02 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	3ZZ4771365
Chassis No.:	MR053ZEE106110084
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	23 Jun 2008
First Registration Date:	23 Jun 2008
Transfer Count:	2
Actual ARF Paid:	\$16,777.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jun 2018
PARF Rebate Amount:	\$8,388.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jun 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,101.00
COE Rebate Amount:	\$313.00
Total Rebate Amount:	\$8,701.00

The information contained herein is correct as at 02 Apr 2018

OK

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING
50 SERANGOON NORTH AVE 4
#02-19 FIRST CENTRE
SINGAPORE 555856

Not Authorised
Call 8850h
Runny After Rain
2 days

ESTIMATE

DATE : 27/03/2018
VEHICLE NO : SJG 1585 S
MAKE/MODEL : Toyota Altis
ACC DATE : 25/03/2018

PARTICULAR AMOUNT S\$

LIST ITEMS:

1	1	REAR BUMPER	<i>Red Way</i>	495.80	✓
2	1	REAR BUMPER SIDE RETAINER (OUTER) - RH	<i>Sm</i>	91.50	X
3	1	REAR BUMPER SIDE RETAINER - (INNER) - RH	<i>Sm</i>	90.90	X
4	1	REAR BUMPER SPONGE	<i>Sm</i>	155.80	X
5	1	REAR BUMPER REFLECTOR - RH	<i>Sm</i>	85.60	X
6	1	REAR BUMPER BRACKET - RH	<i>Sm</i>	89.40	X
7	1	REAR FENDER - RH	<i>Sm</i>	685.50	X
8	1	REAR TAIL LAMP - RH	<i>Sm</i>	381.90	X
9	1	REAR TAIL LAMP LOWER BRACKET - RH	<i>Sm</i>	48.90	X
				2,125.30	
Less Discount:			25%	531.33	
				1,593.98	

SPECIAL NETT ITEMS:

1	10	REAR BUMPER CLIP	<i>Sm</i>	50.00	✓
2	1	REAR REVERSE SENSOR	<i>Sm</i>	250.00	X
				300.00	

LABOUR CHARGES:

1	TO TUFF KOTE	<i>nn</i>	250.00	X
2	TO CHECK WIRING		50.00	<i>1095</i>
3	TO REMOVE/REFIX REVERSE SENSOR		150.00	<i>501</i>
4	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING	<i>nn</i>	150.00	X
5	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS		1,000.00	<i>200</i>
6	TO SPRAY PAINTING ON AFFECTED AREA		1,000.00	<i>400</i>
			2,600.00	

GRAND TOTAL: 4,493.98

Singapore Dollars: Four Thousand Four Hundred And Ninety Three And Cents Ninety Eight Only.


T & T Auto Services Pte Ltd

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after repair
- To display damaged parts
- Parts prices are subject to change
- Third party survey is required with
- No illegal modification
- Supplementary item

is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005722/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 715K	Veh. Inspected	SJG 1585S	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18002455MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	28/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106110084	Colour	METALLIC BLACK	
Odometer	109084	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	3 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	3 mm	
R/H Rear Tyre	195/65 R15	TOYO	2 mm	
L/H Rear Tyre	195/65 R15	TOYO	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/03/2018	Inspection Date	28/03/2018	
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJG 1585S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / WARPED	495.80	495.80
1	REAR BUMPER SIDE RETAINER (OUTER)-RH	SERVICEABLE	91.50	-
1	REAR BUMPER SIDE RETAINER (INNER)-RH	SERVICEABLE	90.90	-
1	REAR BUMPER SPONGE	SERVICEABLE	155.80	-
1	REAR BUMPER REFLECTOR-RH	SERVICEABLE	85.60	-
1	REAR BUMPER BRACKET-RH	TO REPAIR SEE LABOUR	89.40	-
1	REAR FENDER-RH	TO REPAIR SEE LABOUR	685.50	-
1	REAR TAIL LAMP-RH	SERVICEABLE	381.90	-
1	REAR TAIL LAMP LOWER BRACKET-RH	SERVICEABLE	48.90	-
	LESS 25% DISCOUNT		-531.32	-123.95
			1,593.98	371.85
SPECIAL NETT ITEMS				
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	50.00
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
			300.00	50.00
LABOUR				
	TO TUFF KOTE.	NOT NECESSARY	250.00	-
	TO CHECK WIRING.		50.00	15.00
	TO REMOVE/REFIX REVERSE SENSOR.		150.00	50.00
	TO REMOVE/REFIX UPHOLSTERY,CUSHION SEAT & ROOF LINING.	NOT NECESSARY	150.00	-
	TO PANEL BEATING,REMOVING & REPLACING OF NEW PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET-RH AND REAR FENDER-RH.		1,000.00	200.00
	TO SPRAY PAINTING ON AFFECTED AREA.		1,000.00	400.00
			2,600.00	665.00
GRAND TOTAL			4,493.98	1,086.85
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				850.00

Report Ref No. CS/FCI18005722/Kvd3n2



Report Ref No. CS/FCI18005722/Kvd3n2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.