

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 05 Apr 2018

## Preliminary Advice

Insured Vehicle No : SCP820E  
TP Vehicle No : SLQ8340J Accident Date : 23/03/2018  
Make : MAZDA 3 Assignment Date : 28/03/2018  
Date of Inspection : 02/04/2018 Est. Duration of Repair : 3 days  
Inspection At : Pegasus Engineering & Trading Pte Ltd (HQ)  
51 DEFU LANE 10  
Singapore 539216

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,682.00
Revised Amount	:S\$	1,160.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,160.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.