

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Thursday, 7 June, 2018 9:33 AM
To: 'Manivel Priyadarshini'
Cc: Admin A; Vic (LKKAuto)
Subject: Your Ref: MCT18030905_ACCIDENT INVOLVING VEHICLES SHA 3935H AND SKN 7001Y ON 20/03/2018 LKK REF CC4/III18005735/Uha3
Attachments: DAVO4348.JPG; PANC7544.JPG; RHZZ8220.MP4; WBVL1475.JPG; YGXU9030.JPG

Your Ref: MCT18030905

Dear Priya,

ACCIDENT INVOLVING VEHICLES SHA 3935H AND SKN 7001Y ON 20/03/2018

We refer to the above matter.

Insured Driver reported that there was no collision between both vehicles.

As such, TP repairer had furnished us a copy of their client's scene photos and video footage (as attached). Based on the photos and footage, it did not show that the Insured vehicle had reversed and collided to the TP vehicle. It only shows the distance between both vehicles and our Insured vehicle in the car park lot.

We had also observed on Insured's reporting photos that there were damages to the rear bumper.

Please advise further instructions.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.