

Surveyor: **MARCEL** | DOI: **12/01/18** | Date: **28/3/2018** | Registered in Meritum: **12/1/18**

Pre-assign / CCU / FTE: **SHA 3935 H**

Insured Vehicle No.: **CTPL** | Claim No.: **HCT 18030905**

Name of Insured: **CTPL** | Policy No.: **M-LANOT**

Insured Tel No.: \_\_\_\_\_ | HP: \_\_\_\_\_ | Make / Model: **M-BENZ G20**

Excess Sec II :SS: \_\_\_\_\_ | D.O.A: **2/03/18** | Place of Accident: **Neel Rd**

Is driver the owner? ( YES / **NO** ) | Nature of Accident: \_\_\_\_\_

If NO, Driver Name / Age: **Seow Phoi Fah** | OI GIA REPORT: **YES** / NO ; TP GIA REPORT: **YES** / NO

Driver Tel No.: \_\_\_\_\_ | (V/L: **YES** / NO) | Insured Liability: % | Final ? Yes / No

**SKN 7001Y**

 INSRs: _____ WSP: _____ Tel: <b>Chang Mufor.</b> Liability: _____ RMKS: _____	 INSRs: _____ WSP: _____ Tel: _____ Liability: _____ RMKS: _____	 INSRs: _____ WSP: _____ Tel: _____ Liability: _____ RMKS: _____	 INSRs: _____ WSP: _____ Tel: _____ Liability: _____ RMKS: _____
--	---	---	---

Date/Time	STAGE	DATE / PIC
<b>12/1/18</b>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
<b>21/01/18</b>	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
<b>07/01/18</b>	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act	
<b>01/11/18</b>	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
<b>22/03/19</b>	Towing Invoice	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

**PRELIMINARY ADVICE** Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

**FINALIZATION** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: \$S \_\_\_\_\_ ( \_\_\_\_\_ days) Reduction: \_\_\_\_\_ % Email  Call

**FINAL SETTLEMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Final Liability: % \_\_\_\_\_ (Agreed / Assessed) BOLA S/N No. : \_\_\_\_\_ If NO or B 28, Ass. Lia : \_\_\_\_\_

Repair Cost: \$S \_\_\_\_\_

Loss of Rental (LOR): \$S \_\_\_\_\_ ( \_\_\_\_\_ days)

Loss of Use (LOU): \$S \_\_\_\_\_ (5 x days)

Loss of Income (LOI): \$S \_\_\_\_\_ (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search: \$S \_\_\_\_\_

Medical: \$S \_\_\_\_\_

Disbursement: \$S \_\_\_\_\_ (e.g. Tow/ Independent)

Legal Cost: \$S \_\_\_\_\_

**Total:** \$S \_\_\_\_\_ Global Sum \$S: \_\_\_\_\_

**FINAL PAYMENT** Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$S \_\_\_\_\_ Name 1: \_\_\_\_\_

Payee 2: (Strike if N.A.) \$S \_\_\_\_\_ Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$S \_\_\_\_\_ Name 3: \_\_\_\_\_

**WP REPORT NO SETTLEMENT NO PAYMENT TO TP UNION BY REPAYER**

1) Claim status: Normal/Reject/Private Settle

2) Report Format: **WP REPORT**

3) Survey fee: **\$ 250.00**

**28/3/19**

22052002

ASS. REC. BY:

REF:

CS / III 18005735 / b

Special Instruction:

SUBJECT:

ASSIGNMENT (Office)

From (Person): Gabriel Wee of II Date/Time: 28032018 1227pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKN 7001Y Insured: SHN 3935Hat Workshop n/s Cheng Motor Tel: 9671 3335of Blk 1 Paka Bukit Ave 6 # 01-85

Policy No: \_\_\_\_\_ Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 20032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI' H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 28032018 2.14pm Person Contacted: Alan Vehicle: IN / OUTDate/Time Action/Instruction (  ) EstimateSKN 7001Y - XSHN 3935H - CS/III 18005735 / R/A 20032018





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18005735/Uha3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 28-03-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 3935H	Veh. Inspected	SKN 7001Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/03/2018	Inspection Date	12/04/2018
Survey held at	CHENG MOTOR WORK CO. NO.1 KAKI BUKIT AVE 6 #01-83 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83  
 SINGAPORE 417883  
 Tel:65551185/6 Fax:65551184  
 H/P: 96713335  
 E-mail:chengmotor27@yahoo.com

India International Insurance Pte Ltd.  
 64 Cecil Street  
 #04/05 IOB Building  
 Singapore 049711  
 Attn: Motor Claims Dept.

27/3/2018

Estimate cost of repair vehicle no: SKN7001Y

- 2pcs front Headlamp ?
- 2pcs front Headlamp lower bracket 1 u x
- 2pcs front grille n n x
- 2pcs front grille chrome M/S era 1 pc
- Front bumper 70.1
- Front bumper top cover m.s
- 2pcs front bumper side retainer n n x
- 10pcs front bumper clip m
- 2pcs front bumper absorber 7
- Front bumper reinforcement 7
- 2pcs front Fog Lamp 1 1 x
- 2pcs front fog lamp garnish 1 1 x
- 2pcs front bumper lower air duct n n x

*102*

Front number plate	11	40.00	x
Front number plate garnish	11	30.00	x
To spray paint		900.00	300
To remove for checking aircon. condenser and refill aircon gas.	11	120.00	x
To remove and check radiator,refix and coolant.	11	120.00	x
To check wiring		60.00	20
To remove,renew damaged parts,knocking,welding,repaired		800.00	300
And replaced parts.			
Total			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Not Allowed*  
*2/5/18*  
*3 day*  
*12/4/18*  
*The photo After repair*

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC  
 Owner ID: 3055D

**Vehicle Details**

Vehicle No.: SKN7001Y  
 Vehicle to be Exported: No  
 Intended De-registration Date: 12 Apr 2018  
 Vehicle Make: B.M.W.  
 Vehicle Model: 535I AT D/AB 2WD 4DR GAS/D SR HUD  
 Primary Colour: Silver  
 Manufacturing Year: 2012  
 Engine No.: 05988290N55B30A  
 Chassis No.: WBAFR72070C958800  
 Maximum Power Output: 225.0 kW (301 bhp)  
 Open Market Value: \$67,440.00  
 Original Registration Date: 21 Jun 2013  
 First Registration Date: 21 Jun 2013  
 Transfer Count: 2  
 Actual ARF Paid: \$93,392.00 46696

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 20 Jun 2023  
 PARF Rebate Amount: \$70,044.00

**Intended COE Rebate Details**

COE Expiry Date: 20 Jun 2023  
 COE Category: E - Open Category  
 COE Period(Years): 10  
 QP Paid: \$83,001.00  
 COE Rebate Amount: \$42,419.00  
**Total Rebate Amount: \$112,463.00**

The information contained herein is correct as at 12 Apr 2018

OK

## Vic (LKKAuto)

---

**From:** Vic (LKKAuto)  
**Sent:** Wednesday, 27 March, 2019 11:21 AM  
**To:** Manivel Priyadarshini  
**Cc:** Admin A; Vic (LKKAuto); 'Motor Claim - III'  
**Subject:** RE: Your Ref: MCT18030905\_ACCIDENT INVOLVING VEHICLES SHA 3935H AND SKN 7001Y ON 20/03/2018 LKK REF CC4/III18005735/Uha3  
**Attachments:** DAVO4348.jpg; PANC7544.jpg; RHZZ8220.mp4; WBVL1475.jpg; YGXU9030.jpg

Dear Priya,

We refer further to our below email.

Please be informed that TP verbally informed our surveyor to close off the matter since no repair to the TP vehicle has been done to the other repairer and that liability is also unclear.

As such we will proceed to close file in our end and will submit our WP report.

Thank you.


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAuto)  
**Sent:** Thursday, 7 June, 2018 9:33 AM  
**To:** 'Manivel Priyadarshini'  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** Your Ref: MCT18030905\_ACCIDENT INVOLVING VEHICLES SHA 3935H AND SKN 7001Y ON 20/03/2018 LKK REF CC4/III18005735/Uha3

Your Ref: MCT18030905

Dear Priya,

ACCIDENT INVOLVING VEHICLES SHA 3935H AND SKN 7001Y ON 20/03/2018

We refer to the above matter.

Insured Driver reported that there was no collision between both vehicles.

As such, TP repairer had furnished us a copy of their client's scene photos and video footage (as attached). Based on the photos and footage, it did not show that the Insured vehicle had reversed and collided to the TP vehicle. It only shows the distance between both vehicles and our Insured vehicle in the car park lot.

We had also observed on Insured's reporting photos that there were damages to the rear bumper.

Please advise further instructions.

Thank you.


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vic@lkkauto.com](mailto:vic@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

### New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly  
From \$688 Onwards. Lowest  
3.68%P.A@GV Cars Financing,  
GV Credit Pte Ltd [StarAd](#)

**ABWIN**




4 vehicles



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
------	-------	-------	--------------	----------	---------	------

**Search Selection**
**bmw 535**

Any

Any

**2013**

Any


**BMW 5 Series 535i Sunroof**
**\$127,800**

\$18,740 /yr

13-Mar-2013

2,979 cc

65

\$12K Down Payment With The Lowest Installment Of \$1.9k Only! In House Loan/Balloon Scheme Available With 100% F & Powerful Black 535 Selling Cheap Now! Highest Paper \$96k ...

Le Motor Enterprise

Posted: 12-Apr-2018 Tags: 2013 BMW 535i, BMW 535i, BMW, 535i, Used BMW


**BMW 5 Series 535i Sunroof**
**\$144,555**

\$23,990 /yr

10-Jan-2013

2,979 cc

35

Pristine Condition, Low Mileage Of 39000km, 100% Accident Free, Serviced And Maintained By PML, High Spec Model, F1 Auto Blind All Round, Head Up Display, Neat And Clean Ex...

Posted: 09-Apr-2018 Tags: 2013 BMW 535i, BMW 535i, BMW, 535i, Used BMW


**BMW 5 Series 535i Sunroof**
**\$119,800**

\$18,490 /yr

14-Mar-2013

2,979 cc

30

Genuine Low Mileage! Down Payment Merely 10%, \$1756 For 58 Month! Well Taken Care By Careful Owner. Selling Due Spare Car. 100% Mishap Free, No Repairs Required. Accident Free...

Car Buyers Automotive Pte Ltd

Posted: 29-Mar-2018 Tags: 2013 BMW 535i, BMW 535i, BMW, 535i, Used BMW


**BMW 5 Series 535i Gran Turismo**
**\$138,888**

\$19,880 /yr

17-May-2013

2,979 cc

65

Excellent Condition, Very Well Maintained By Owner And Fully Serviced By Reputable Workshop.Call For Viewing Appoint Loan Available.

F1 Autos Pte Ltd

Posted: 25-Mar-2018 Tags: 2013 BMW 535i, BMW 535i, BMW, 535i, Used BMW

Save this search criteria, to get email alerts whenever a match is found.

**Catherine Chong (LKK Auto)**

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Wednesday, 28 March, 2018 12:27 PM  
**To:** tan lay keng; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)  
**Cc:** Manivel Priyadarshini  
**Subject:** RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKN7001Y (Accident involving SKN7001Y and SHA3935H on 20.03.2018)  
**Attachments:** sha3935h\_20180328091922.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKN7001Y and let us have your report urgently.

This claim will be handled by Ms Priya.

\*Kindly upload this survey request email to merimen.

Thank You.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.

**India International Insurance Pte Ltd**

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

**From:** tan lay keng [mailto:tanlaykengandco@gmail.com]  
**Sent:** 28 March, 2018 11:08 AM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>  
**Subject:** Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SKN7001Y (Accident involving SKN7001Y and SHA3935H on 20.03.2018)

Dear Mr Gabriel Wee

We have been instructed by our client that you may appoint LKK Auto Consultants Pte Ltd to conduct the pre-repair inspection.

Rgds  
Raymond Ng  
Tan Lay Keng & Co  
28/3/2018

On Wed, Mar 28, 2018 at 9:26 AM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

*Best Regards,*

**Gabriel Wee**

Motor Claims Dept.  
**India International Insurance Pte Ltd**  
64 Cecil Street | #05 10B Building | Singapore 049711  
Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

# Tan Lay Keng & Co.

Advocates & Solicitors \* Commissioners for Oaths \* Notaries Public \* Trade Mark Agents

Tan Lay Keng LL.B. (Hons), (S'pore)

Raymond Y.E. Ng LL.B. (Hons), LL.M. (S'pore)

Your Ref:

Our Ref: RN.kt.0048.15.V6

27 March 2018



111 North Bridge Road  
#14-03 Peninsula Plaza  
Singapore 179098  
Tel: 6338 2388, 6338 3330  
Fax: 6338 3730  
UEN No. 53131292E

Motor Claims Department  
India International Insurance Pte Ltd  
64 Cecil Street  
#04/05 IOB Building  
Singapore 049711

BY FAX: 6224 4174 & HAND

Dear Sirs

**ACCIDENT ON 20.3.2018 INVOLVING SKN 7001Y AND SHA 3935H  
BESIDE UNIT 75 NEIL ROAD PARKING LOT NO. 10 & 11**

We are instructed by the owner of SKN 7001Y.

You are the insurers of motor taxi No. SHA 3935H.

We are instructed to give you 48 hours' Notice for the pre-repair inspection under NIMA protocol of the damage to our client's car before any repairs are carried out.

Our client's car may be inspected at Cheng Motor Work Company at 1 Kaki Bukit Ave 6 #01-83 Singapore 417883. Contact person: Mr Alan Tan Tel: 6555 1185/9671 3335.

Yours faithfully

A handwritten signature in black ink, appearing to be a stylized 'S' or similar character.

cc client

陳麗卿律師事務所

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2018 <a href="#">Edit Reg</a>		28 Mar 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$620.00</b> <a href="#">Edit Estimates</a>	<b>S\$620.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Main Claimant:	<b>HIMANSHU R L BAKDHA</b> , ID: S7443055D								
Vehicle Reg. No.:	<b>SKN7001Y</b>	Date of Loss:	20/03/2018 12:00 - :59 [56 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MCT18030905</b>	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	<b>SHA3935H</b>	Policy No. (Claimant):	2100489764-01						
		Excess:							
Repairer:	<b>Cheng Motor Work Co. (HQ)</b> 1 KAKI BUKIT AVE 6 #01-83, 417883 Kaki Bukit - Tel: 65551185/6, 67411336, 67472350								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Priya</b> ]								
Claimant's Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 26/04/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• III_SG (01/11/2018): Alert - Adj Mandate Maintained - SKN7001Y - Claim Handler: Priya									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKN7001Y (MCT18030905)  
[SHA3935H]  
TP  
HIMANSHU R L BAKDHA  
Mar 20 2018 12:00PM  
[COMFORT TRANSPORTATION PTE LTD]  
Cheng Motor Work Co.

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
<b>Video</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print					
1	18/06/18 10:36	<b>Video - Accident</b>		 Load MP4	<input checked="" type="checkbox"/>					
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	31/10/18 17:20	<b>Chassis Number</b>		 Load JPG	<input checked="" type="checkbox"/>					
2	31/10/18 17:20	<b>Odometer Reading</b>		 Load JPG	<input checked="" type="checkbox"/>					
3	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
4	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
5	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
6	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
7	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
8	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
9	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
10	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
11	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
12	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
13	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
14	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
15	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
16	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
17	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
18	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
19	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
20	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
21	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
22	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
23	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
24	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
25	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
26	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
27	31/10/18 17:21	<b>General View</b>		 Load JPG	<input checked="" type="checkbox"/>					
<b>Documentation</b>									1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	17/04/18 11:52	<b>ACKNOWLEDGEMENT EMAIL TO III DD 28.03.2018</b>		 Load PDF	<input checked="" type="checkbox"/>					
2	17/04/18 11:52	<b>NOTIFICATION FROM LAWYER</b>		 Load PDF	<input checked="" type="checkbox"/>					
3	18/04/18 00:54	<b>TP ESTIMATE - MARKED</b>		 Load PDF	<input checked="" type="checkbox"/>					
4	18/04/18 00:54	<b>TP GIA REPORT</b>		 Load PDF	<input checked="" type="checkbox"/>					
5	31/10/18 17:22	<b>TP SCENE PHOTOS</b>		 Load PDF	<input checked="" type="checkbox"/>					

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
6	27/03/19 11:22	<b>EMAIL TO III</b>		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	18/04/18 08:49	<b>Singapore Accident Statement</b>		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18005735/UHA3Q2

Date: 29/03/2019

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
 Claimant Vehicle No: SKN7001Y Insured Vehicle No: SHA3935H  
 Date of Loss: 20/03/2018 Nature of Claim: TP Claim No: MCT18030905

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SKN7001Y**  
 Make & Model: BMW 535i, 3.0 (A) Engine No: 05988290N55B30A  
 Reg. Date: 21/06/2013 (Man. Year: 2012) Chassis No: WBAFR72070C958800  
 Colour: Silver Odometer: 98091 km  
 Engine Capacity: 2979 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 275/35 R19  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	70.00	0.00	70.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	620.00	1,380.00	69.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>2,070.00</b>	<b>620.00</b>	<b>1,450.00</b>	<b>70.05</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 28/03/2018  
 Date Inspected: 12/04/2018 Inspected At: Cheng Motor Work Co. (HQ)  
 1 KAKI BUKIT AVE 6 #01-83  
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2019)
<b>Parts:</b> 143	BMW 535I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKN7001Y)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT HEADLAMP (NPA)	*Check	0.00 F	*- FL
2	2		*FRONT HEADLAMP LOWER BRACKET (NPA)	Not Necessary	0.00 F	*- FL
3	2		*FRONT GRILLE (NPA)	Not Necessary	0.00 F	*- FL
4	1		*FRONT GRILLE CHROME (NPA)	N/S Cracked	0.00 F	*- FL
5	1		*FRONT BUMPER (NPA)	Torn	0.00 F	*- FL
6	1		*FRONT BUMPER TOP COVER (NPA)	Missing	0.00 F	*- FL
7	2		*FRONT BUMPER SIDE RETAINER (NPA)	Not Necessary	0.00 F	*- FL
8	10		*FRONT BUMPER CLIP (NPA)	Necessary	0.00 F	*- FL
9	2		*FRONT BUMPER ABSORBER (NPA)	*Check	0.00 F	*- FL
10	1		*FRONT BUMPER REINFORCEMENT (NPA)	*Check	0.00 F	*- FL
11	2		*FRONT FOG LAMP (NPA)	Not Necessary	0.00 F	*- FL
12	2		*FRONT FOG LAMP GARNISH (NPA)	Not Necessary	0.00 F	*- FL
13	2		*FRONT BUMPER LOWER AIR DUCT (NPA)	Not Necessary	0.00 F	*- FL
14	1		*FRONT NUMBER PLATE	Not Necessary	40.00 FS	*- FS
15	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

<b>Sub Total (\$\$)</b>	<b>70.00</b>	<b>0.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>0.00</b>
<b>Total Parts (\$\$)</b>	<b>70.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SPRAY PAINT	New	900.00	300.00
2	TO REMOVE FOR CHECKING AIRCON.CONDENSER AND REFILL AIRCON GAS	New	120.00	0.00
3	TO REMOVE AND CHECK RADIATOR ,REFIX AND COOLANT	New	120.00	0.00
4	TO CHECK WIRING	New	60.00	20.00
5	TO REMOVE,RENEW DAMAGED PARTS, KNOCKING ,WELDING ,REPAIRED AND REPLACED PARTS	New	800.00	300.00
<b>Gross Labour Cost (S\$)</b>			<b>2,000.00</b>	<b>620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >