



GST / ROC Company No : 201101753C

Third Party Insurer : AIG
 Insured's Veh No : SLN2906H
 Date of accident : 16/03/2018

Grab Rentals Pte Ltd
 18 Sin Ming Lane
 #01-08 Midview City
 Singapore 573960

Quotation No : AR/QO18/03-1038
 Quotation Date : 23/03/2018

Not Approved
LKK
to be photo before painting
3 days
28/3/18

Estimate To Repair HONDA VEZEL HYBRID 1.5X AUTO
 Vehicle No : SLU5300Z
 Chassis No : RU3-1265510

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
SPARE PARTS			
1	1PC	REAR GATE <i>body</i>	\$1,010.00
2	1PC	REAR GATE LOCK	\$105.00
3	1PC	REAR GATE "VEZEL" PLATE <i>rec</i>	\$45.00
4	1PC	REAR GATE "HYBRID" PLATE <i>rec</i>	\$60.00
5	1PC	REAR GATE INNER RUBBER <i>17</i>	\$120.00
6	1PC	REAR WINDSCREEN MOULDING <i>rec</i>	\$160.00
7	1PC	REAR BUMPER (CENTRE) <i>pp/rec</i>	\$810.00
8	10PC	REAR BUMPER CLIPS @\$5.50 <i>rec</i>	\$55.00
			\$2,365.00
LESS 20%			\$473.00
			\$1,892.00
MISC ITEMS			
9	1PC	REAR WINDSCREEN GUM <i>seal</i>	\$65.00
10	1PC	REVERSE SENSOR <i>rec</i>	\$250.00
Total			\$315.00
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	\$30.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00
3		TRANSFER REAR DOOR COMPONENT FROM OLD TO NEW	\$120.00
4		LABOUR CHARGE	\$600.00
5		SPRAY PAINTING	\$600.00
Total			\$1,470.00
Sub Total			\$3,677.00
GST (7.00%)			\$257.39
Total			\$3,934.39

✓
?
—
—
X
—
—
—
40
?
20
✓
60
300
400

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please conduct the survey at
 Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883
 GARY 8338 8418

Acknowledged by Repairer
 Signature: