

AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aakls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

China Taiping Insurance (Singapore) Pte. Ltd. - Claims Department

3 Anson Road #15-00

Springleaf Tower

Attn: Sharon

Quotation

DATE: 04-Apr-18

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	UOM	QTY	UNIT PRICE	AMOUNT (\$)
	Accident Repair of YP4523B				
1	Front Right Side Panel		1	\$480.00	\$480.00
2	Spray Paint : Front Bumper Assy, RH Side Panel & Front Panel		1	\$500.00	\$500.00
3	Panel Beat : To renew side panel, to remove and install front bumper & To panel beat side panel bracket		1	\$600.00	\$600.00
4	Replacement 24ft truck with tailgate x 2 days		2	\$180.00	\$360.00
E. & O. E.					
SUB-TOTAL					\$1,940.00
7% GST					\$135.80
TOTAL					\$2,075.80

SGD: TWO THOUSAND SEVENTY-FIVE AND CENTS EIGHTY ONLY.

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

Accepted and Confirmed by

Company Chop & Signature

AAK LOGISTICS SERVICES PTE LTD

Authorised Signature



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

432

850

1282

2020

1025.60

4/5 - 1000

3 days

480

10%

432

Labour

850