

ASS. REC. BY

REF: CS/FCI18005747/Krd3nz Special Instruction

Surveyor
CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Serene Ter

of

FCI

Date/Time:

27/3/18 @ 7:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 7134X

Insured:

SHC 8319.T

at Workshop m/s:

Wei Lee Motor

Tel:

64569830

of

Block 9 Sin Ming Ind. Est #01-32

Policy No:

Claim No:

D18002454MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A

24/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

8:53am @ 28/3/18

Person Contacted:

Karen

Vehicle:

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 7134X-X
	SHC 8319.T-CS/FCI14008733/Rvbu2 D.O.A: 30/4/14
4/4	L1 Rpt & 160ch email & cabinet. Red: 3,393 50,681.

ASS. REC. BY:


REF: P021

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Wai Lu
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLL 7134X Yr Regn: 05, 08
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Zy Atril c.c. 1598
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 16746P T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR0538EE106107835
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modl: Nil / S/Rim / STD/Rim or _____
 Tyre Size: F: Yoko 195/65R15
 R: Mic
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 5 mm R/Bal. 4 mm
 L/Bal. 5 mm L/Bal. 4 mm
 D.O.A. 24/3/18 D.O.I. 28/3/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S & FR
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>29/3</u>	<u>File pass to Catherine</u>

RECEIVED 25 APR 2018

Date/Time, File Pass to? : Prell. Report
 : Final Report
 1) typist
 Date/Time, File Return to?

Days Of Repair: 6
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	<u>135</u>
Transportation:	<u>50</u>
S + RS. \$:	<u>30</u>
Photos:	<u>24</u>
Others:	
TOTAL	<u>259</u>

Report Format: TP
 Lump Sum / LB: (\$ 1600)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005747/Krd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8319T	Veh. Inspected	SLL 7134X
Policy No.		Coverage (\$)	0.00
Claim No.	D18002454MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	28/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/03/2018	Inspection Date	28/03/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	27-03-2018	Our Ref No. D18002454MFSH
Accident Date	24-03-2018	Claim Type. Third Party
Insured Vehicle	SHC8319T	Third Party Vehicle. SLL7134X
Survey Location	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32	
Contact Person.	KAREN SEAH	
Contact No.	64569830/ 0	Fax No. 64580128
Survey Type	WITHOUT PREJUDICE: NO EST PROVIDED (#28 - QUANTUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEI LEE MOTOR WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236371)



PRI Documents



Close



PRI Header Details

Claim No	D18002454MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WEI LEE P LEASING PTE.
Workshop Name	WEI LEE MOTOR WORKS (Contact Person : KAREN SEAH)	Survey Location & Contact Details	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Mobile: 0 , Phone: 64569830 , Fax: 64580128 EmailId: WEILEEMOTORWORKS@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST PROVIDED (#28 - QUAN		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8319T	TP Vehicle No	SLL7134X
PRI Recieved Date	27-03-2018 06:13:07 PM	Surveyor Appointed Date	27-03-2018 07:35:58 PM	Surveyor Accept Date	28-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	28-03-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:
Owner ID:

Company
1813C

Vehicle Details

Vehicle No.:
Vehicle to be Exported:
Intended De-registration Date:
Vehicle Make:
Vehicle Model:
Primary Colour:
Manufacturing Year:
Engine No.:
Chassis No.:
Maximum Power Output:
Open Market Value:
Original Registration Date:
First Registration Date:
Transfer Count:
Actual ARF Paid:

SLL7134X
Yes
30 Mar 2018
TOYOTA
COROLLA ALTIS 1.6 AUTO
Black
2008
3ZZ4762928
MR053ZEE106107835
80.0 kW (107 bhp)
\$16,777.00
20 May 2008
20 May 2008
2
\$16,777.00

Intended PARF Rebate Details

PARF Eligibility:
PARF Eligibility Expiry Date:
PARF Rebate Amount:

Yes
19 May 2018
\$8,388.00

Intended COE Rebate Details

COE Expiry Date:
COE Category:
COE Period(Years):
QP Paid:
COE Rebate Amount:
Total Rebate Amount:

19 May 2018
A - Car (1600cc & below)
10
\$11,009.00
\$147.00
\$8,535.00

The information contained herein is correct as at 27 Mar 2018

OK

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455-3986 *6458 0128*
Business Regn No : 269436/00J

claim no - D18002454 MFSH

27, Mar 2018

First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
S 068877

*Not authorized
U/Sig B?
Resony After Paint
6day*

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No: SHC8319T
Accident involving vehicle No: SLL7134X/SHC8319T/SJY7408L
DOA: 24/03/2018 AT PIE

Dear officer incharge
Re: Estimate cost of repair for vehicle No: SLL7134X
To supply—

Description	Qty		Amount	
Front bumper	1	<i>Bu</i>	423.60	✓
Front bumper enforcement	1	<i>R</i>	339.70	✗
Bumper retainer @51.90	2	<i>D-1</i>	103.80	✓
Bumper lower grille	1	<i>su</i>	93.30	✓
Front grille	1	<i>DisM</i>	305.80	✓
Rear bumper	1	<i>Bu</i>	482.00	✓
Rear bumper enforcement/sponge	1	<i>su</i>	123.50	✗
Rear bumper foglamp	1	<i>scr</i>	37.20	✓
Rear bumper retainer	1	<i>D-1</i>	69.80	✓
Taillamp	1	<i>scr</i>	409.90	✓
Bumper clip		<i>su</i>	42.00	✓
Headlamp	1	<i>su</i>	481.90	✗
End panel	1	<i>R</i>	708.30	✗
End panel top garnish	1	<i>su</i>	36.00	✗
Lid-LH reflector	1	<i>su</i>	159.00	✗
Lid-Altis emblem	1	<i>su</i>	25.70	✓
Lid-1.6 emblem	1	<i>su</i>	32.40	✗
Lid-COROLLA emblem	1	<i>su</i>	24.10	✗
	Parts		3,898.00	
	Parts less 25%		974.50	
			2,923.50	

Reverse sensor

Pr 220.00 x

To remove front and rear damaged parts and attachments.

900.00 6001

Cut n weld damaged panel.

Repair/reshape front bonnet, front support panel, lid and all dented areas.

Replace/realign all parts into position.

To spray paint-

950.00 6001

4493.5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005747/Krd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8319T	Veh. Inspected	SLL 7134X
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002454MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	27/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053ZEE106107835	Colour	METALLIC BLACK
Odometer	167469	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/65 R15	MICHELIN	4 mm
L/H Rear Tyre	195/65 R15	MICHELIN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/03/2018	Inspection Date	28/03/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7134X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	BUCKLED	423.60	423.60
1	FRONT BUMPER ENFORCEMENT	TO REPAIR SEE LABOUR	339.70	-
2	BUMPER RETAINER @\$51.90	DISTORTED	103.80	103.80
1	BUMPER LOWER GRILLE	SERVICEABLE	93.30	-
1	FRONT GRILLE	DISTORTED / DENTED	305.80	305.80
1	REAR BUMPER	BENT	482.00	482.00
1	REAR BUMPER ENFORCEMENT/SPONGE	SERVICEABLE	123.50	-
1	REAR BUMPER FOGLAMP	SCRATCHED	37.20	37.20
1	REAR BUMPER RETAINER	DISTORTED	69.80	69.80
1	TAILLAMP	SCRATCHED	409.90	409.90
1	BUMPER CLIP	NECESSARY	42.00	42.00
1	HEADLAMP	SERVICEABLE	481.90	-
1	END PANEL	TO REPAIR SEE LABOUR	708.30	-
1	END PANEL TOP GARNISH	SERVICEABLE	36.00	-
1	LID-LH REFLECTOR	SERVICEABLE	159.00	-
1	LID-ALTIS EMBLEM	NOT NECESSARY	25.70	-
1	LID-1.6 EMBLEM	NOT NECESSARY	32.40	-
1	LID-SOROLLA EMBLEM	NOT NECESSARY	24.10	-
	LESS 25% DISCOUNT		-974.50	-468.52
			2,923.50	1,405.58
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	220.00	-
			220.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE FRONT AND REAR DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED PANEL.REPAIR/RESHAPE FRONT BONNET,FRONT SUPPORT PANEL,LID AND ALL DENTED AREAS.REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF FRONT BUMPER ENFORCEMENT AND END PANEL. TO SPRAY PAINT.		900.00	600.00
			950.00	600.00
			1,850.00	1,200.00
	GRAND TOTAL		4,993.50	2,605.58
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00

Report Ref No. CS/FC118005747/Krd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.