## **SERVE YOU MOTOR SERVICE**

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265, SINGAPORE 569536 TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: serveyou5033@gmail.com

egist	tration	no. : GJ 87 P / TOYOTA DYNA 150 D	
ate:		26-Mar-18 Quotation No.: 18326-6	
/N	Qty	Item	Amount
		LIST ITEMS	
1	1	LH side gate	<b>1</b> 1388.00
2 3	6 pcs	LH side gate safety hinge \$128 each	768.00
3		LH side mudflat \$145 each	Bu 290.00
4		LH side gate floor panel	N 880.00
			3,326.00
		Less 25%	831.50
			2,494.50
		SPECIAL NETT ITEMS	
1	1	Rear tyre rim	∫ <sub>∽</sub> 444.00
	1	Spare tyre bracket	150.00
2 3 4	1	Company logo body sticker	(Br 11) 450.00 50052 Not 880.00
4	1	LH side gate aluminium	3005N Not 880.00
5	6	LH side hook \$45 each	~ 270.00
			2,194.00
		LABOUR & MISC CHARGES	
			50
1		To dismantle / renew the rear accident damaged	680.00
		portion. To panel beating, reshape, straighten,	
		orientate and align repair / replacement parts.	
2		To reinstall for side gate and floor panel.	vn 250.00
3		To spray undercoating on affected areas.	180.00
			-0
4		To spray painting on rear damaged portion.	3 for 750.00
		TOTAL	2,010.00
Total Parts and Labour Cost of Repair			\$6,698.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurrey Afre Pains (Eday)