

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

<b>TO</b>	: CHINA TAIPING	<b>DATE</b>	: 26/03/2018
<b>ATTENTION</b>	: MOTOR CLAIMS DEPT	<b>JOB TYPE</b>	: T/P CLAIM
<b>ESTIMATE REPORT</b>	:		
<b><u>VEHICLE DETAILS</u></b>			
<b>VEHICLE NO</b>	: SGD1279C	<i>Vivian</i>	
<b>MODEL</b>	: MITSUBISHI LANCER 1.6M		
<b>CHASSIS NO</b>	:		
<b><u>ACCIDENT DETAILS</u></b>		<b>DATE</b>	: 24-Mar-18
		<b>TIME</b>	: 11:40HRS
<b>THIRD PARTY REQUESTOR / CONTACT</b>	: JACK LI		

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Buckled</i>	1	\$ 633.60	\$ 633.60 ✓
2	BOOTLID LOGO <i>new</i>	1	\$ 62.20	\$ 62.20 ✓
3	BOOTLID EMBLEM"LANCER" <i>new</i>	1	\$ 50.00	\$ 50.00 ✓
4	BOOTLID EMBLEM"GLX" <i>new</i>	1	\$ 55.00	\$ 55.00 ✓
5	BOOTLID EMBLEM"C&C" <i>new</i>	1	\$ 60.00	\$ 60.00 ✓
6	BOOTLID TOP LOCK <i>new</i>	1	\$ 168.40	\$ 168.40 ✓
7	BOOTLID LOWER CATCH <i>new</i>	1	\$ 89.60	\$ 89.60 x
8	BOOTLID HINGE <i>new</i>	2	\$ 98.30	\$ 196.60 x
9	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 173.20	\$ 173.20 ✓
10	REAR BUMPER <i>Delivered</i>	1	\$ 753.10	\$ 753.10 ✓
11	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 355.00	\$ 355.00 x
12	REAR BUMPER TOP BEAM <i>Best</i>	1	\$ 233.00	\$ 233.00 ✓
13	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 89.00	\$ <del>178.00</del> 88 ✓
14	REAR NUMBER PLATE GARNISH <i>combined</i>	1	\$ 262.30	\$ 262.30 ✓
15	REAR BUMPER NUMBER PLATE LAMP <i>new</i>	2	\$ 132.90	\$ 265.80 x
16	REAR FENDER INNER TRIM <i>new</i>	2	\$ 327.00	\$ 654.00 x
17	REAR TAILLAMP <i>combined</i>	2	\$ 513.00	\$ <del>1,026.00</del> 688 ✓

18	REAR TAILLAMP INNER PANEL <i>Mem</i>	2	\$ 320.00	\$ 640.00	✓
19	REAR END PANEL <i>Dented</i>	1	\$ 599.30	\$ 599.30	✓
20	REAR END PANEL TOP GARNISH <i>Red</i>	1	\$ 174.00	\$ 174.00	✓

4000.1  
3600.09

TOTAL PRICE \$ 6,629.10  
LESS 10% \$ 662.91  
SUB TOTAL PRICE \$ 5,966.19

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Mem</i>	1	\$ 50.00	\$ 50.00	✓
2	REAR BUMPER CLIP (SET) <i>Mem</i>	1	\$ 30.00	\$ 30.00	✓
3	TAIL LAMP CLIP (SET) <i>Mem</i>	1	\$ 25.00	\$ 25.00	✓
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Mem</i>	1	\$ 30.00	\$ 30.00	10
5	REAR END PANEL INSULATION SEAL <i>Mem</i>	1	\$ 120.00	\$ 120.00	60
6	REVERSE SENSOR <i>Doyle</i>	1	\$ 220.00	\$ 220.00	20

325 TOTAL \$ 475.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING ( REAR)**

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,200.00	90	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	800	
3	TUFF COAT	\$ 180.00	40	
4	WIRING CHECK	\$ 150.00	30	1810
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	40	
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X	

TOTAL \$2,770.00

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 6,441.19  
TOTAL LABOUR COST : \$ 2,770.00  
TOTAL REPAIR COST : \$ 9,211.19

total: 5735.09  
A/S: HSK.

**APPROVED DETAILS**

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

H/S Adrian G  
27/03/18.  
06 Dup.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: