

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 46387**
Date Estimated : **26/03/2018**
Prepared By : **Chua Kee Sin**

Page No. :

REPAIR FOR -
DBS Bank Ltd.
12 MARINA BOULEVARD
LEVEL 15 DBS ASIA CENTRAL@ MARINA BAY FI
Singapore 018982

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SFQ3328A	GL98461	18/11/2016	750LiA	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident			850.00		850.00
To spray paint rear bumper			934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.			150.00		150.00
Sundries.			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER ADAPTER	77.65	1.00		77.65
REAR BUMPER CENTRE GUARD	84.20	1.00		84.20
BUMPER GUARD REAR	102.95	1.00		102.95
RUBBER STRIP LH	85.05	1.00		85.05
RUBBER STRIP RH	85.05	1.00		85.05
REAR BUMPER COVER	107.05	1.00		107.05
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,586.85	1.00		1,586.85
PLUG	1.05	6.00		6.30
# REAR DIFFUSER *	139.75	1.00		139.75
# PLUG BLACK D=5MM *	0.90	6.00		5.40

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,280.25
Total Labour & Parts :	4,294.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,294.25
GST @7%:	300.60
Grand Total :	4,594.85