

ASS. REC. BY:

REF: CS/FCI18005755/Tlv03ⁿ²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

CWS

From (Person): May chua

of FCI

Date/Time: 27/3/18 @ 6:01pm

Estimated Cost:

Bill to:

OD / ~~IP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFQ 3328A

Insured: SH 9910Y

at Workshop m/s

Performance Motor

Tel: 6319 0174

of 303 Alexandra Road

Policy No:

Claim No:

D18002464MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 9:48am @ 28/3/18

Person Contacted: caroline

Vehicle IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	SFQ 3328A - CS / MSG 15001796 / Avbu2 D.O.A. 28/1/15
	SH 9910Y - NS / INC 12003096 / Hlfm D.O.A. 13/2/12
12/4/18	Email preli revised to FCI
22/5/18	Final Rg \$ 4294.25 confirmed by email (Real 3730.05, 467)

ROR xun 22/05/18

Surveyor

Tanflin

REF: FCL


ASSIGNMENT

From: _____ Date: 11-04-2018
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SFD 3328A
 at Workshop m/s: Performance
 of: 303 Alexandra Rd
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

10:30am - 11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SF 23328A Yr Regn: 2016 Nov
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW 250LI A c.c 4395
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 3666 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WR 197 F02W 509 L 98461
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / STD A/Rim or 275/35R20
 Tyre Size: F: _____ R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. _____ D.O.I. 11/4/18
 Survey held at PML
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

RECEIVED 22 MAY 2018

Date/Time, File Pass to? ☐ Preli. Report

1) ☐ Final Report

Date/Time, File Return to?

2) 22/5 - typist

Report Format: CWS

Lump Sum / I.B.I: (\$ 4244.25)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee: _____
 Transportation: _____
) \$ + RS. \$1
) Photos
) Others

160
50
50
45
305

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005755/T1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-03-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9910Y	Veh. Inspected	SFQ 3328A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002464MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	27/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/03/2018	Inspection Date	11/04/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002464MFSH

Our ref: CS/FC118005755/T1vd3

Date: 12/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SFQ 3328A


We thank you for your instruction on 27/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/4/2018 at the premises of M/s PERFORMANCE MOTORS LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,879.15
Revised Estimate Amount	: S\$3,547.35
"Check" Items Amount	: S\$3,110.60
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAL, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	27-03-2018	Our Ref No. D18002464MFSH
Accident Date	24-03-2018	Claim Type. Third Party
Insured Vehicle	SH9910Y	Third Party Vehicle. SFQ3328A
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236384)



PRI Documents



Close



PRI Header Details

Claim No	D18002464MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PERFORM
Workshop Name	PERFORMANCE MOTORS LIMITED (Contact Person : CAROLINE)	Survey Location & Contact Details	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CEI Mobile: 0 , Phone: 63190174 , Fax: 64794601 EmailId: PML-PBSP@SIMEDARBY.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9910Y	TP Vehicle No	SFQ3328A
PRI Recieved Date	27-03-2018 04:48:07 PM	Surveyor Appointed Date	27-03-2018 06:00:44 PM	Surveyor Accept Date	27-03-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-03-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 22 May 2018 9:51 AM
To: 'PBSP'
Cc: Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SFQ3328A

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$4294.25 before GST @ 3 working days.

Final invoice and all supporting documents sent over to First Capital Ins Ltd

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 21 May 2018 3:12 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: FINAL REPORT / SFQ3328A

Dear Sirs

As requested, please see attached photographs.

Thank you.

Regards,
Caroline

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Monday, 21 May 2018 10:36 AM
To: PBSP; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SFQ3328A

Dear Caroline,

Please provides us check items and supplementary photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 17 May 2018 10:22 AM

To: 'PBSP' <pml-pbsp@sime-darby.com.sg>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: FINAL REPORT / SFQ3328A

Dear Caroline,

Please provides us check items and supplementary photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 12 April 2018 2:12 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002464MFSH/1, SFQ 3328A
Attachments: SFQ 3328A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SFQ 3328A
Date of survey: 11/4/2018
Number of days: 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 28 March 2018 2:06 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002464MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 March 2018 6:00 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002464MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

26 MAR 2018

Estimate No. : b1 46387
Date Estimated : 26/03/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

DBS Bank Ltd.
12 MARINA BOULEVARD
LEVEL 15 DBS ASIA CENTRAL@ MARINA BAY F
Singapore 018982

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ3328A	GL98461	18/11/2016	750LiA	0

DESCRIPTION

Replace rear bumper and remove attachment etc include knock on accident dent

Spray painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

✓ 850 1,700.00

✓ 934 1,038.00

✓ 150 177.00

✓ ? 80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER ADAPTER
REAR BUMPER CENTRE GUIDE
REAR LH MOULDING ROCKER PANEL
REAR RH MOULDING ROCKER PANEL
REAR BUMPER CENTRE GUARD
BUMPER GUARD REAR
RUBBER STRIP LH
RUBBER STRIP RH
LH TRIM EXHAUST TAILPIPE
RH TRIM EXHAUST TAILPIPE
REAR BUMPER COVER
REAR BUMPER CARRIER
Protection foil
TRIM REAR PRIMED
REAR BUMPER PANEL PRIMED (PDC/PMA)
REAR BUMPER TOWING EYE COVER PRIMED
LEFT PROTECT foil
RIGHT PROTECT foil
PLUG
ULTRASONIC SENSOR BLACK
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	77.65	? 77.65
1	51.50	? 51.50
1	51.50	? 51.50
1	51.50	? 51.50
1	84.20	? 84.20
1	102.95	? 102.95
1	85.05	? 85.05
1	85.05	? 85.05
1	184.50	? 184.50
1	184.50	x 184.50
1	107.05	107.05
1	898.50	? 898.50
2	8.65	? 17.30
1	216.45	216.45
1	1,586.85	de 1,586.85
1	55.70	R 55.70
1	11.30	? 11.30
1	11.30	? 11.30
6	1.05	nei 6.30
4	248.70	? 994.80
4	5.05	nei 20.20

Total Parts : 4,884.15



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46387
Date Estimated : 26/03/2018
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFQ3328A	GL98461	18/11/2016	750LiA	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time 11/4/18	Excess S\$ _____
Surveyor's Name <i>Teapkin</i>	Sign <i>Teapkin</i>
Surveyor's Tel 97465749	Authorised Yes / No
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail <i>teapkin@lkkauto.com</i>	
No. of Working Days Recommend <i>3 days</i>	

8024.30

Labour 1	:	2,995.00
Parts	:	4,884.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	551.54
Grand Total	:	8,430.69

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46387
Date Estimated : 26/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
DBS Bank Ltd.
12 MARINA BOULEVARD
LEVEL 15 DBS ASIA CENTRAL@ MARINA BAY FI

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 018982

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SFQ3328A	GL98461	18/11/2016	750LiA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR DIFFUSER *	139.75	1.00		139.75 <i>de</i>
# PLUG BLACK D=5MM *	0.90	6.00		5.40 <i>new</i>

Total Labour :	
Total Parts :	145.15
Total Labour & Parts :	145.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46387
Date Estimated : 26/03/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
DBS Bank Ltd.
12 MARINA BOULEVARD
LEVEL 15 DBS ASIA CENTRAL@ MARINA BAY FI

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 018982

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SFQ3328A	GL98461	18/11/2016	750LiA	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident				850.00		850.00
To spray paint rear bumper				934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.				150.00		150.00
Sundries.				80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER ADAPTER	77.65	1.00		77.65
REAR BUMPER CENTRE GUARD	84.20	1.00		84.20
BUMPER GUARD REAR	102.95	1.00		102.95
RUBBER STRIP LH	85.05	1.00		85.05
RUBBER STRIP RH	85.05	1.00		85.05
REAR BUMPER COVER	107.05	1.00		107.05
REAR BUMPER PANEL PRIMED (PDC/PMA)	1,586.85	1.00		1,586.85
PLUG	1.05	6.00		6.30
# REAR DIFFUSER *	139.75	1.00		139.75
# PLUG BLACK D=5MM *	0.90	6.00		5.40

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,280.25
Total Labour & Parts :	4,294.25
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,294.25
GST @7%:	300.60
Grand Total :	4,594.85



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18005755/T1vd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 24-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9910Y	Veh. Inspected	SFQ 3328A
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18002464MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	27/03/2018

2. Vehicle Particulars & Condition

Make & Model	BMW 750LI A	c.c	4395
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA7F02080GL98461	Colour	BLACK
Odometer	36668	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/35 R20	PIRELLI	6 mm
L/H Front Tyre	275/35 R20	PIRELLI	6 mm
R/H Rear Tyre	275/35 R20	PIRELLI	6 mm
L/H Rear Tyre	275/35 R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/03/2018	Inspection Date	11/04/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFQ 3328A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER ADAPTER (SN)	NECESSARY	77.65	77.65
1	REAR BUMPER CENTRE GUIDE (SN)	NOT NECESSARY	51.50	-
1	REAR LH MOULDING ROCKER PANEL (SN)	NOT NECESSARY	51.50	-
1	REAR RH MOULDING ROCKER PANEL (SN)	NOT NECESSARY	51.50	-
1	REAR BUMPER CENTRE GUARD (SN)	DEFORMED	84.20	84.20
1	BUMPER GUARD REAR (SN)	DEFORMED	102.95	102.95
1	RUBBER STRIP LH (SN)	DEFORMED	85.05	85.05
1	RUBBER STRIP RH (SN)	NECESSARY	85.05	85.05
1	LH TRIM EXHAUST TAILPIPE (SN)	NOT NECESSARY	184.50	-
1	RH TRIM EXHAUST TAILPIPE (SN)	NOT NECESSARY	184.50	-
1	REAR BUMPER COVER (SN)	DEFORMED	107.05	107.05
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	898.50	-
2	PROTECTION OIL (SN)	NOT NECESSARY	17.30	-
1	TRIM REAR PRIMED (SN)	NOT NECESSARY	216.45	-
1	REAR BUMPER PANEL PRIMED (PDC/PMA)(SN)	DEFORMED	1,586.85	1,586.85
1	REAR BUMPER TOWING EYE COVER PRIMED (SN)	TO REPAIR SEE LABOUR	55.70	-
1	LEFT PROTECT OIL (SN)	NOT NECESSARY	11.30	-
1	RIGHT PROTECT OIL (SN)	NOT NECESSARY	11.30	-
6	PLUG (SN)	NECESSARY	6.30	6.30
4	ULTRASONIC SENSLR BLACK (SN)	NOT NECESSARY	994.80	-
4	DECOUPING RING PDC TORQUE CONVERTER (SN)	NOT NECESSARY	20.20	-
1	REAR DIFFUSER (ADDITIONAL)(SN)	DEFORMED	139.75	139.75
6	PLUG BLACK D=5MM (ADDITIONAL)(SN)	NECESSARY	5.40	5.40
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
			5,109.30	2,360.25
LABOUR				
REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT.INCLUSIVE OF THE REPAIR OF REAR BUMPER TOWING EYE COVER PRIMED.			1,700.00	850.00
SPRAY PAINTING REAR BUMPER.			1,038.00	934.00

Report Ref No. CS/FCI18005755/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			2,915.00	1,934.00
GRAND TOTAL			8,024.30	4,294.25
RECOMMENDED COST OF REPAIRS				4,294.25

Report Ref No. CS/FCI18005755/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.