

15/5/2010

INS. CASE OWNER:

Jenny
Adnan

CC 6/QBE1800

5757, April 6 3 52

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKU 2764



INSRS:

WSP:

Tel:

Liability:

RMKS:

1st
Auto work

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

5/7/18
MIT
6/7/18

SKU 2764 - 7

GBE 5294K - 7

OI hit TP parked veh.
Sent letter to oi.

27/7/18 - Fire pass to type mandate.

27/10/18 - DV sent.

2/11/18 - Fire pass to Shu per to close

RECEIVED 05 NOV 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(

days)

BOLA S/N No. 1112

If NO or B 28, Ass. Lia:

Repair Cost:

SS

16050.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

600.00

(\$

60 x 10

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

16652.00

Global Sum SS:

16650.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

16650.00

Name 1:

1st Automotives Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Sku2176Y Yr Regn: 2015 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet Sonic C.C. 1398Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 10480 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KLITA69FJFB152037Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55 R16R: 215/55 R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 27/03/18Survey held at 1st AutoworkDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP QBE.

US \$ 15000 (Reel \$ 18264.40 / 55%)MV: 68KPV: 53KNett: 15K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC6/QBE18005757/Amb3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 28-03-2018		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 5294K	Veh. Inspected	SKU 2176Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/03/2018	Inspection Date	27/03/2018	
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

FW 62445785

QBF

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 27/3/2018

Reference: SKU2176Y
CHEVROLET
SONIC NB 1.4
Make: AT 2WD

TP QBE.
Xico Tony.

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SKU2176Y
CHASSIS NO.: KL1TA69FJFB152037
ENGINE NO.: A14XER150470166

Name of insured : Alpine Car Rental Pte Ltd
Date of accident.: 19/03/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1		Front Bumper <i>Rehd</i>	\$ 1,341.00
2		Front Bumper Lower Radiator Grille and Chrome <i>lt</i>	\$ 321.00
3		LHF Foglamp <i>new</i>	\$ 332.00
4		LHF Foglamp Cover <i>new</i>	\$ 50.00
5		Bootlid <i>Distorted</i>	\$ 2,026.00
6		Bootlid Chrome Handle <i>Rehd</i>	\$ 445.00
7		Lettering "CHEVROLET" <i>2mm</i>	\$ 45.00
8		Lettering "SONIC LTZ" <i>2mm</i>	\$ 65.00
9		LTZ Lettering <i>2mm</i>	\$ 30.00
10		Chevrolet Emblem <i>2mm</i>	\$ 96.00
11		Bootlid Inner Trim <i>Rehd</i>	\$ 110.00
12		Bootlid Hinge LH <i>2 Bent</i>	\$ 121.00
13		Bootlid Hinge RH	\$ 121.00
14		Bootlid Striker <i>Bent</i>	\$ 111.00
15		Bootlid Latch <i>Bent</i>	\$ 107.00
16		Bootlid Weatherstrip <i>lt</i>	\$ 135.00
17		LHR Gutter <i>Distorted Rys</i>	\$ 289.00
18		LHR Taillamp <i>Smashed</i>	\$ 491.00
19		LHR Taillamp Panel <i>Distorted</i>	\$ 190.00
20		LHR Fender <i>Distorted Rys</i>	\$ 1,873.00
21		LHR Fender Liner <i>Rehd</i>	\$ 45.00
22		LHR Wheel House <i>Rehd</i>	\$ 990.00
23		LHR Chasis <i>Rys</i>	\$ 1,040.00
24		RHR Gutter <i>Distorted</i>	\$ 289.00
25		RHR Taillamp <i>Smashed</i>	\$ 491.00
26		RHR Taillamp Panel <i>Distorted</i>	\$ 190.00
27		RHR Fender	\$ 1,873.00
28		RHR Fender Liner <i>Rehd</i>	\$ 45.00
29		RHR Wheel House <i>Rys</i>	\$ 990.00

30	RHR Chasis		\$ 1,040.00	+
31	Rear Windscreen	new	\$ 776.00	+
32	Rear Windscreen Moulding	new	\$ 129.00	+
33	Rear Bumper	Distorted	\$ 1,241.00	+
34	Rear Bumper Towing Cover	Distorted	\$ 45.00	+
35	Reinforcement Bar	Distorted	\$ 787.00	+
36	LHR Bumper Bracket	Distorted	\$ 65.00	+
37	RHF Bumper Bracket	Distorted	\$ 65.00	+
39	LHR Lower Extension	Repair	\$ 130.00	+
40	LHR Air Ventilator	Repair	\$ 45.00	+
41	RHR Lower Extension	Distorted	\$ 130.00	+
42	RHR Air Ventilator	Distorted	\$ 45.00	+
43	Rear End Panel	Distorted	\$ 910.00	+
44	Rear End Panel Trim	Distorted	\$ 95.00	+
45	RHR Fender Inner Trim	Distorted	\$ 180.00	+
46	Spare Tyre Board Mat	Distorted	\$ 262.00	+
47	Spare Tyre Panel	Repair	\$ 917.00	+
48	Rear Exhaust	new	\$ 1,305.00	+
49	RHR Door	Repair	\$ 1,517.00	+
50	RHR Door Latch	new	\$ 265.00	+
51	RHR Door Striker	new	\$ 45.00	+

Parts Total: \$ 24,246.00

Less 10%: \$ 2,424.60

Total : \$ 21,821.40

Labour

Labour Description

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 550.00	✓
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 450.00	✓
3	To conduct anti rust of under carriage tuff coat	\$ 60.00	+
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 4,400.00	3850
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 3,150.00	3380
3	To conduct anti rust of under carriage tuff coat	\$ 60.00	2250 2700
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	150
6	To remove and refix reverse sensor and conduct test	\$ 80.00	✓
7	To remove and refix reverse camera and conduct test	\$ 80.00	60
8	Conduct chasis alignment of vehicle	\$ 250.00	+
9	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	+
10	To conduct water leakage test after repairs of vehicle	\$ 30.00	+
11	To apply door sealant to door	\$ 80.00	+

12	To remove and replace exhaust pipe	\$ 80.00	x
13	To remove and refit fuel tank to facilitate accident repair	\$ 70.00	✓
14	To remove and refit rear windscreen due to replacement of rear fender	\$ 120.00	✓

8230

Labour Total : \$ 9,850.00

Others

Other Description

No. Qty

Price (SGD)

Front portion

1	1	Number plate with casement	\$ 45.00	+
2	10	Front bumper clip	\$ 65.00	30

Rear portion

1	1	Rear number plate	\$ 45.00	-
2	10	Rear bumper clip	\$ 65.00	30
3	10	Tailgate insulator clip	\$ 65.00	30
4	6	Rear fender liner clips	\$ 39.00	-
5	8	Rear end panel trim clip	\$ 52.00	15
6	1	Reverse sensor 1 set	\$ 280.00	-
7	1	Rear reverse camera	\$ 320.00	+
8	1	Rear end panel insulation seal	\$ 80.00	✓
9	1	Rear floor panel insulation seal	\$ 120.00	+
10	8	Rear fender inner trim clip	\$ 52.00	30
11	8	Tail gate inner trim board clip	\$ 52.00	+
12	2	Rear exhaust mounting	\$ 13.00	+
13	1	Rear windscreen sealant	\$ 120.00	60
14	1	Rear windscreen film	\$ 180.00	+

Other Total: \$ 1,593.00

639

GRAND TOTAL: \$ 33,264.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Executive
Suhaimi Ong

HP : 8298 8933 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
27/03/18
108mp

tel: 2058430
h/s: 15K



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: VC011297

Our ref: CC6/QBE18005757/Apb3

Date: 26.07.2018

The Motor Claims Department
M/s QBE Insurance (Singapore) Pte Ltd

DearSirs/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKU 2176Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/03/2018 at the premises of M/s 1ST AUTOWORKS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	33,264.40
Revised Estimate Amount	: S\$	15,000.00
"Check" Items Amount	: S\$	
Market Value	: S\$	68,000.00 (est)
LTA Reimbursement Value	: S\$	53,000.00 (est)
Nett Value	: S\$	15,000.00 (est)

Description of Damage:

The vehicle sustained damages at the
Rear Portion & Front N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 days

Yours faithfully,

ADRIAN LING

Licensed Appraiser

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 27 July 2018 8:25 AM
To: 'jenny.toh@qbe.com'
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF -CC6/QBE18005757/Apb3) on 19.03.2018
Attachments: TP ESTIMATE_MARKED.pdf; Preliminary Advice - SKU 2176Y.pdf; LKK Survey Photos.pdf; PARF_COE REBATE.pdf

Your Ref: **VC011297**
LKK REF: CC6/QBE18005757/Apb3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Wednesday, 4 July, 2018 2:45 PM
To: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

Our ref: VC011297


Hi Shu Pei

Please find attached as per requested.

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, 3 July, 2018 10:33 AM

To: Jenny Toh <jenny.toh@qbe.com>

Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Tuesday, 24 April 2018 10:15 AM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Wednesday, 28 March 2018 6:26 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKU 2176Y at M/s 1st Autoworks Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Shu Pei (LKKAuto)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Wednesday, 4 July 2018 2:45 PM
To: Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF -CC6/QBE18005757/Anb3) on 19.03.2018
Attachments: GBE5294K.pdf

Our ref: VC011297


Hi Shu Pei

Please find attached as per requested.

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 3 July, 2018 10:33 AM
To: Jenny Toh <jenny.toh@qbe.com>
Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Tuesday, 24 April 2018 10:15 AM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Wednesday, 28 March 2018 6:26 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKU 2176Y at M/s 1st Autoworks Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Friday, 6 July 2018 7:53 AM
To: 'ronnie.tan@firstautoworks.com.sg'; 'suhaimi@firstautoworks.com.sg'
Cc: Admin A; Vic (LKKAUTO)
Subject: ACCIDENT INVOLVING GBE 5294K(QBE) AND SKU 2176Y ON 19/03/2018 *Our Ref: CC6/QBE18005757/Apb3

Your Ref: **SKU 2176Y**
Our Ref: CC6/QBE18005757/Apb3

Without Prejudice

Dear Sirs,

ACCIDENT INVOLVING GBE 5294K(QBE) AND SKU 2176Y ON 19/03/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Letter of Authorisation & Indemnity

Accident Involving Vehicle no. SK4 2176Y and G-BE 52441L On 19/3/2018

At International Business Park Boon Lay way

1. I/We, the owner of vehicle no. SK4 2176Y hereby instruct and authorize 1st Automobiles Pte Ltd ("the workshop") to commence repairs to the said vehicle. Pending the outcome of my/our claim against the third party, I/we forthwith pay you the sum of \$ _____ being refundable deposit of the repair to my/our said vehicle.
2. You are further authorized to appoint solicitors on my/our behalf and give the solicitors full instructions as if the appointment is made and instructions are given by me/us with respect to the conduct of my/our claim against the third party driver and/or his insurers including if necessary, to commence legal proceedings in court in my/our name against the third party.
3. You have my/our full authority to instruct my/our solicitors to negotiate a settlement with the third party and/or his insurers on such terms as you deem fit.
4. Upon resolving my/our claim, you are authorized to agree with my/our solicitors on the amount of their professional costs and disbursement for acting for me/us and to receive payment of the balance of the settlement sum on my/our behalf directly into your account. In the event that my/our claim or legal costs of the third party as well as the professional costs and disbursements of my/our solicitors notwithstanding that my/our solicitors were appointed by you on our behalf.
5. I/we also hereby instruct and authorise you deduct directly from the claim monies received from the third party all outstanding balances that are still owing to you, namely the balance of repair costs and rental of substitute vehicles.
6. In the event that I/we am/are required to attend at my/our solicitors office or to attend court in connection with my/our claim, I/we shall render full co-operation.
7. In the event that my/our claim against the third party and/or his insurers is not successful or cannot be proceeded with and/or if any Judgement or settlement is not honoured or satisfied by the third party, I/we authorise you to revert the claim against my/our own insurers for the cost of repairs and any other losses recoverable under my/our policy of insurance. In this respect, I/we understand and accept that the excess amount applicable under policy of insurance shall be borne by me/us.
8. If for whatever reasons, my/our insurers reject my/our claim for indemnity for the cost of repairs and/or any other losses recoverable under the policy of insurance or make an offer to pay less than the amount claimed by you, I/we agree and undertake to pay the full amount of your repair bill and survey fees and any other expenses reasonably incurred on my/our behalf or to pay you the difference in amount, as the case may be.
9. I/we shall keep you informed of any correspondences and/or summons that I may receive due to this action agreeing to pay or receive any monies due to this claim.

Dated this 20 day of 03 2018

Signature of vehicle owner

Name - _____

IC No : _____

(Company stamp, if applicable)

Address : 7461 Clove, Alpine

Centre, S'pore 408 604

Tel : 6511 3021

Witnessed by :

Sethini

Hsiao Tong (LKKAUTO)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Monday, 22 October 2018 10:20 AM
To: Hsiao Tong (LKKAUTO)
Subject: FW: Direct Settlement - Accident Involving GBE5294K (OI : QBE - VC011297) AND SKU2176Y (TP : LKK REF -CC6/QBE18005757/Apb3) on 19.03.2018
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos 1.pdf; LKK Resurvey Photos 2.pdf; LKK Resurvey Photos 3.pdf; TP LOD_SKU2176Y.pdf


Hi Hsiao Tong

Kindly proceed for the settlement.

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, 13 October 2018 12:40 PM
To: Jenny Toh <jenny.toh@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - VC011297) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Apb3) on 19.03.2018

Your ref : **VC011297**

Our ref : CC6/QBE18005757/Apb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GBE 5294K(OI) & SKU 2176Y(TP) ON 19/03/2018

We refer to the above matter.

The accident occurred when our insured driver hit onto third party parked vehicle. Liability is not in our insured driver's favour.

We seek your approval to offer Third Party repairer " 1ST AUTOWORKS PTE LTD" at \$16,652.00(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 35,592.91	\$ 16,050.00
2. Loss of Use (10days x \$100.00)	\$ 1,000.00	\$ 600.00 (10days x \$60.00)
3. LTA/GIA search fee	\$ 2.00	\$ 2.00
Total	\$ 36,594.91	\$ 16,652.00

**10days recommendation for repair.

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Friday, 27 July 2018 8:26 AM

To: 'jenny.toh@qbe.com' <jenny.toh@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Apb3) on 19.03.2018

Your Ref: **VC011297**

LKK REF: CC6/QBE18005757/Apb3

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh <jenny.toh@qbe.com>

Sent: Wednesday, 4 July, 2018 2:45 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

Our ref: VC011297

Hi Shu Pei

Please find attached as per requested.

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, 3 July, 2018 10:33 AM

To: Jenny Toh <jenny.toh@qbe.com>

Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Tuesday, 24 April 2018 10:15 AM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Wednesday, 28 March 2018 6:26 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBE5294K (OI : QBE - TBA) AND SKU2176Y (TP : LKK REF - CC6/QBE18005757/Anb3) on 19.03.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKU 2176Y at M/s 1st Autoworks Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Hsiao Tong (LKKAUTO)

From: Suhaimi <suhaimi@firstautoworks.com.sg>
Sent: Thursday, 25 October 2018 8:32 AM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A; Vic (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING GBE 5294K(QBE) AND SKU 2176Y ON 19/03/2018 *Our Ref: CC6/QBE18005757/Apb3

Hi Hsiao Tong,
Without prejudice to any personal injury claim, we accept your offer of \$16 650.00.

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4,
#04-01 (South Wing)
Singapore 415933
Tel : 6844 1985

chewht@lkkauto.com

suhaimi@firstautoworks.com.sg suhaimi@firstautoworks.com.sg
admin-a@lkkauto.com vicalpeh@lkkauto.com

Without Prejudice

Hi Suhaimi,

We refer to the above matter.

We propose settlement at a global sum of **\$16,650.00(all-in)**.

Please confirm.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Suhaimi <suhaimi@firstautoworks.com.sg>

Sent: Tuesday, 9 October 2018 12:48 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING GBE 5294K(QBE) AND SKU 2176Y ON 19/03/2018 *Our Ref: CC6/QBE18005757/Apb3

Hi Hsiao Tong,

Have you received all original documents such as LOD and invoices from Adrian?

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4,
#04-01 (South Wing)
S'pore 415933
Tel : 6844 1985
Fax : 6844 5185

chewht@lkkauto.com

ronnie.tan@firstautoworks.com.sg
suhaimi@firstautoworks.com.sg
admin-a@lkkauto.com

ronnie.tan@firstautoworks.com.sg

suhaimi@firstautoworks.com.sg

vicalpeh@lkkauto.com

Without Prejudice

Hi,

We refer to the above matter.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)
Sent: Friday, 6 July 2018 7:53 AM
To: 'ronnie.tan@firstautoworks.com.sg' <ronnie.tan@firstautoworks.com.sg>; 'suhaimi@firstautoworks.com.sg' <suhaimi@firstautoworks.com.sg>
Cc: Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: ACCIDENT INVOLVING GBE 5294K(QBE) AND SKU 2176Y ON 19/03/2018 *Our Ref: CC6/QBE18005757/Apb3

Your Ref: **SKU 2176Y**

Without Prejudice

Our Ref: CC6/QBE18005757/Apb3

Dear Sirs,

ACCIDENT INVOLVING GBE 5294K(QBE) AND SKU 2176Y ON 19/03/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC6/QBE18005757/Apb3s2

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 08-11-2018



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 5294K	Veh. Inspected	SKU 2176Y
Policy No.	8-V0014427-MVA-R001	Coverage (\$)	0.00
Claim No.	VC011297	Excess (\$)	0.00
Assign From		Assign Date	27/03/2018

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET SONIC	c.c	1398
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KL1TA69FJFB152037	Colour	BROWN
Odometer	10480	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R16	BRIDGESTONE	6 mm
L/H Front Tyre	215/55R16	BRIDGESTONE	6 mm
R/H Rear Tyre	215/55R16	BRIDGESTONE	6 mm
L/H Rear Tyre	215/55R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/03/2018	Inspection Date	27/03/2018
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 2176Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,341.00	1,341.00
1	FRONT BUMPER LOWER RADIATOR GRILLE AND CHROME	CUT	321.00	321.00
1	LHF FOGLAMP	NOT NECESSARY	332.00	-
1	LHF FOGLAMP COVER	NOT NECESSARY	50.00	-
1	BOOTLID	DISTORTED	2,026.00	2,026.00
1	BOOTLID CHROME HANDLE	DEFORMED	445.00	445.00
1	LETTERING "CHEVROLET"	NECESSARY	45.00	45.00
1	LETTERING "SONIC LTZ"	NECESSARY	65.00	65.00
1	LTZ LETTERING	NECESSARY	30.00	30.00
1	CHEVROLET EMBLEM	NECESSARY	96.00	96.00
1	BOOTLID INNER TRIM	DEFORMED	110.00	110.00
1	BOOTLID HINGE LH	BENT	121.00	121.00
1	BOOTLID HINGE RH	BENT	121.00	121.00
1	BOOTLID STRIKER	BENT	111.00	111.00
1	BOOTLID LATCH	DAMAGED	107.00	107.00
1	BOOTLID WEATHERSTRIP	CUT	135.00	135.00
1	LHR GUTTER	TO REPAIR SEE LABOUR	289.00	-
1	LHR TAILLAMP	CRACKED	491.00	491.00
1	LHR TAILLAMP PANEL	DISTORTED	190.00	190.00
1	LHR FENDER	TO REPAIR SEE LABOUR	1,873.00	-
1	LHR FENDER LINER	NOT NECESSARY	45.00	-
1	LHR WHEEL HOUSE	NOT NECESSARY	990.00	-
1	LHR CHASSIS	TO REPAIR SEE LABOUR	1,040.00	-
1	RHR GUTTER	DISTORTED	289.00	289.00
1	RHR TAILLAMP	SMASHED	491.00	491.00
1	RHR TAILLAMP PANEL	DISTORTED	190.00	190.00
1	RHR FENDER	DISTORTED	1,873.00	1,873.00
1	RHR FENDER LINER	DEFORMED	45.00	45.00

Report Ref No. CC6/QBE18005757/Apb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RHR WHEEL HOUSE	TO REPAIR SEE LABOUR	990.00	-
1	RHR CHASSIS	TO REPAIR SEE LABOUR	1,040.00	-
1	REAR WINDSCREEN	NOT NECESSARY	776.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	129.00	129.00
1	REAR BUMPER	DISTORTED	1,241.00	1,241.00
1	REAR BUMPER TOWING COVER	DISTORTED	45.00	45.00
1	REINFORCEMENT BAR	BENT	787.00	787.00
1	LHR BUMPER BRACKET	NECESSARY	65.00	65.00
1	RHF BUMPER BRACKET	NECESSARY	65.00	65.00
1	LHR LOWER EXTENSION	TO REPAIR SEE LABOUR	130.00	-
1	LHR AIR VENTILATOR	NOT NECESSARY	45.00	-
1	RHR LOWER EXTENSION	DISTORTED	130.00	130.00
1	RHR AIR VENTILATOR	DAMAGED	45.00	45.00
1	REAR END PANEL	DISTORTED	910.00	910.00
1	REAR END PANEL TRIM	DEFORMED	95.00	95.00
1	RHR FENDER INNER TRIM	DEFORMED	180.00	180.00
1	SPARE TYRE BOARD MAT	DEFORMED	262.00	262.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	917.00	-
1	REAR EXHAUST	NOT NECESSARY	1,305.00	-
1	RHR DOOR	TO REPAIR SEE LABOUR	1,517.00	-
1	RHR DOOR LATCH	NOT NECESSARY	265.00	-
1	RHR DOOR STRIKER	NOT NECESSARY	45.00	-
	LESS 10% DISCOUNT		-2,424.60	-1,259.70
			21,821.40	11,337.30
	SPECIAL NETT ITEMS			
1	NUMBER PLATE WITH CASEMENT (SN)	NOT NECESSARY	45.00	-
10	FRONT BUMPER CLIP (SN)	NECESSARY	65.00	30.00
1	REAR NUMBER PLATE (SN)	CUT	45.00	45.00
10	REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00

Report Ref No. CC6/QBE18005757/Apb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	TAILGATE INSULATOR CLIP (SN)	NECESSARY	65.00	30.00
6	REAR FENDER LINER CLIPS (SN)	NECESSARY	39.00	39.00
8	REAR END PANEL TRIM CLIP (SN)	NECESSARY	52.00	15.00
1	SET REVERSE SENSOR (SN)	DAMAGED	280.00	280.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	320.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	80.00	80.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
8	REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	52.00	30.00
8	TAIL GATE INNER TRIM BOARD CLIP (SN)	REPEATED	52.00	-
2	REAR EXHAUST MOUNTING (SN)	NOT NECESSARY	13.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
1	REAR WINDSCREEN FILM (SN)	NOT NECESSARY	180.00	-
			1,593.00	639.00
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND REALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF LHR GUTTER, LHR FENDER, LHR CHASSIS, RHR WHEEL HOUSE, LHR LOWER EXTENSION, SPARE TYRE PANEL AND RHR DOOR.		4,950.00	4,400.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		3,600.00	3,150.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		120.00	60.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		60.00	60.00
	REMOVE AND REFIX SEAT CUSHION / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.		250.00	150.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	80.00
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.		80.00	60.00
	CONDUCT CHASSIS ALIGNMENT OF VEHICLE.	NOT NECESSARY	250.00	-
	TO CONDUCT TRANSFER OF PARTS FROM OLD BOOTLID TO NEW BOOTLID.		80.00	80.00

Report Ref No. CC6/QBE18005757/Apb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	30.00	-
	TO APPLY DOOR SEALANT TO DOOR.	NOT NECESSARY	80.00	-
	TO REMOVE AND REPLACE EXHAUST PIPE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT FUEL TANK TO FACILITATE ACCIDENT REPAIR.		70.00	70.00
	TO REMOVE AND REFIT REAR WINDSCREEN DUE TO REPLACEMENT OF REAR FENDER.		120.00	120.00
			9,850.00	8,230.00
GRAND TOTAL			33,264.40	20,206.30

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00
---	--	--	--	------------------

Report Ref No. CC6/QBE18005757/Apb3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.