

QBE

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 27/3/2018

Reference: SKU2176Y
CHEVROLET
SONIC NB 1.4
Make: A/T 2WD

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SKU2176Y
CHASSIS NO.: KL1TA69FJFB152037
ENGINE NO.: A14XER150470166

Name of insured : Alpine Car Rental Pte Ltd
Date of accident.: 19/03/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1		Front Bumper <i>Rehd</i>	\$ 1,341.00
2		Front Bumper Lower Radiator Grille and Chrome <i>lt</i>	\$ 321.00
3		LHF Foglamp <i>new</i>	\$ 332.00
4		LHF Foglamp Cover <i>new</i>	\$ 50.00
5		Bootlid <i>Distorted</i>	\$ 2,026.00
6		Bootlid Chrome Handle <i>Rehd</i>	\$ 445.00
7		Lettering "CHEVROLET" <i>3mm</i>	\$ 45.00
8		Lettering "SONIC LTZ" <i>3mm</i>	\$ 65.00
9		LTZ Lettering <i>3mm</i>	\$ 30.00
10		Chevrolet Emblem <i>3mm</i>	\$ 96.00
11		Bootlid Inner Trim <i>Rehd</i>	\$ 110.00
12		Bootlid Hinge LH <i>3 Bent</i>	\$ 121.00
13		Bootlid Hinge RH <i>3 Bent</i>	\$ 121.00
14		Bootlid Striker <i>Bent</i>	\$ 111.00
15		Bootlid Latch <i>Rehd</i>	\$ 107.00
16		Bootlid Weatherstrip <i>lt</i>	\$ 135.00
17		LHR Gutter <i>Distorted Rys</i>	\$ 289.00
18		LHR Taillamp <i>Smashed crimp</i>	\$ 491.00
19		LHR Taillamp Panel <i>Distorted</i>	\$ 190.00
20		LHR Fender <i>Distorted Rys</i>	\$ 1,873.00
21		LHR Fender Liner <i>Rehd</i>	\$ 45.00
22		LHR Wheel House <i>Rehd</i>	\$ 990.00
23		LHR Chasis <i>Rys</i>	\$ 1,040.00
24		RHR Gutter <i>Distorted</i>	\$ 289.00
25		RHR Taillamp <i>Smashed</i>	\$ 491.00
26		RHR Taillamp Panel <i>3 Distorted</i>	\$ 190.00
27		RHR Fender <i>Rehd</i>	\$ 1,873.00
28		RHR Fender Liner <i>Rehd</i>	\$ 45.00
29		RHR Wheel House <i>Rys</i>	\$ 990.00

30	RHR Chasis	Repair	\$ 1,040.00	+
31	Rear Windscreen	new	\$ 776.00	+
32	Rear Windscreen Moulding	new	\$ 129.00	+
33	Rear Bumper	Distorted	\$ 1,241.00	+
34	Rear Bumper Towing Cover	Distorted	\$ 45.00	+
35	Reinforcement Bar	Bent	\$ 787.00	+
36	LHR Bumper Bracket	new	\$ 65.00	+
37	RHF Bumper Bracket	new	\$ 65.00	+
39	LHR Lower Extension	Repair	\$ 130.00	+
40	LHR Air Ventilator	new	\$ 45.00	+
41	RHR Lower Extension	Distorted	\$ 130.00	+
42	RHR Air Ventilator	Bent	\$ 45.00	+
43	Rear End Panel	Distorted	\$ 910.00	+
44	Rear End Panel Trim	Bent	\$ 95.00	+
45	RHR Fender Inner Trim	Bent	\$ 180.00	+
46	Spare Tyre Board Mat	Bent	\$ 262.00	+
47	Spare Tyre Panel	Repair	\$ 917.00	+
48	Rear Exhaust	new	\$ 1,305.00	+
49	RHR Door	Repair	\$ 1,517.00	+
50	RHR Door Latch	new	\$ 265.00	+
51	RHR Door Striker	new	\$ 45.00	+

Parts Total: \$ 24,246.00

Less 10%: \$ 2,424.60

Total : \$ 21,821.40

Labour

Labour Description

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 550.00	✓
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 450.00	✓
3	To conduct anti rust of under carriage tuff coat	\$ 60.00	+
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 4,400.00	3850 3300
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 3,150.00	2250 2700
3	To conduct anti rust of under carriage tuff coat	\$ 60.00	✓
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	150
6	To remove and refix reverse sensor and conduct test	\$ 80.00	✓
7	To remove and refix reverse camera and conduct test	\$ 80.00	60
8	Conduct chasis alignment of vehicle	\$ 250.00	+
9	To conduct transfer of parts from old bootlid to new bootlid	\$ 80.00	+
10	To conduct water leakage test after repairs of vehicle	\$ 30.00	+
11	To apply door sealant to door	\$ 80.00	+

12	To remove and replace exhaust pipe	\$	80.00	x
13	To remove and refit fuel tank to facilitate accident repair	\$	70.00	✓
14	To remove and refit rear windscreen due to replacement of rear fender	\$	120.00	✓

8230

Labour Total : \$ 9,850.00

Others

Other Description

No. Qty

Price (SGD)

Front portion

1	1	Number plate with casement	\$	45.00	+
2	10	Front bumper clip	\$	65.00	30

Rear portion

1	1	Rear number plate	\$	45.00	✓
2	10	Rear bumper clip	\$	65.00	30
3	10	Tailgate insulator clip	\$	65.00	30
4	6	Rear fender liner clips	\$	39.00	✓
5	8	Rear end panel trim clip	\$	52.00	15
6	1	Reverse sensor 1 set	\$	280.00	✓
7	1	Rear reverse camera	\$	320.00	+
8	1	Rear end panel insulation seal	\$	80.00	✓
9	1	Rear floor panel insulation seal	\$	120.00	+
10	8	Rear fender inner trim clip	\$	52.00	30
11	8	Tail gate inner trim board clip	\$	52.00	+
12	2	Rear exhaust mounting	\$	13.00	+
13	1	Rear windscreen sealant	\$	120.00	60
14	1	Rear windscreen film	\$	180.00	+

Other Total: \$ 1,593.00

GRAND TOTAL: \$ 33,264.40

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax: 6844 5185

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
P/P 27/03/18
10 days

tel: 2058430
h/s: 15K

639