

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	5	TAIL GATE SEALANT	Reviewing	0	NOT NECESSARY	
	6	REVERSE SENSOR	Reviewing	300	DAMAGED	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
	10	2			REAR NUMBER PLATE LAMP			Serviceable	0		25		0
	11	1			AERAS EMBLEM			Necessary	55.9		25		41.93
	12	1			ESTIMA EMBLEM			Necessary	97.1		25		72.83
	13	1			REAR BOOT LID TOYOTA LOGO			Necessary	82.1		25		61.58
	14	2			REAR BOOT LID LAMP			Serviceable	0		25		0
	15	2			TAIL LAMP			Serviceable	0		25		0
	16	1			REAR BUMPER			Deformed	1339.5		25		1004.63
	17	1			REAR BUMPER REFLECTOR (N/S)			Cracked	166.7		25		125.03
	18	1			REAR BUMPER TOWING COVER			Serviceable	0		25		0
	19	1			SET REAR BUMPER CLIPS			Necessary	30		25		22.5
	20	2			REAR BUMPER SIDE HOLDER			Necessary	96.1		25		144.15
	21	1			REAR END PANEL			Damaged	683.1		25		512.33
	22	1			REAR END PANEL UPPER GARNISH			Deformed	249.1		25		186.83
	23	1			REAR END PANEL LOWER GARNISH			Deformed	176.8		25		132.6

Detailed Assessment

Inspection Date *

03/27/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes

No

Steering (Serviceable)

Yes

No

Towing Charges

0

Footbrake (Serviceable)

Yes

No

Voluntary Excess

0

Handbrake (Serviceable)

Yes

No

Compulsory Excess

0

Engine Modification

Yes

No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/60R16

Rear Tyre Size

215/60R16

FNOL INFORMATI...
BLK 333 KANG CHING ROAD, #02-272,
610333, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...
Personal Correspondence

POST SURVEY INF ...

CATEGORY

Gender

FNOL INFORMATI...
Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...
Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...
S8117702C

POLICY INFORMAT ... TPVD TOYOTA

ASSESSMENT INFO...

TOYOTA

CATEGORY

Model

POLICY INFORMAT ... ESTIMA 2.4X A

ASSESSMENT INFO...

ESTIMA 2.4X A

CATEGORY

Type

POLICY INFORMAT ...

ASSESSMENT INFO...



CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

ACR500050403

CATEGORY

Date of Birth

FNOL INFORMATI...

June 12, 1981

POST SURVEY INF...

mm/dd/yyyy



CATEGORY

Age

FNOL INFORMATI...

37

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF ...

CATEGORY

Driving Experience

Direct settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

- Messages
- Assessment
- Invoices
- Metrics
- History
- Notes
- Documents
- Add

Additional Instructions

please proceed with DS

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	8/1/18 3:32 PM	3800	3800	Open	Share	Clone
NG Stacey	4/10/18 10:04 AM	4809.04	4809.04	Open	Share	Clone

Direct settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Additional Instructions

please proceed with DS

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement	Accident statement	Merimen	
Immediate Advice (with mandate) dd 300618.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 30, 2018
PARF_COE Rebate Enquiry.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 30, 2018