

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SFJ678X

Chassis No : JHMF16306S209608

Model : CIVIC 1.8L VTI-S AUTO

Owner's Name : S GANASAN S/O M SOKALINGAM

Ins Policy No. :

Date of Accident : 27/3/2018

Document No. : SQT18001282

Date : 27. Mar 2018

Customer No. : WZI007

Svc Advisor : JASON HENG

Engine No : R18A11030303

Date | Time : 27. Mar 2018 2:21:27 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: S GANASAN S/O M SOKALINGAM OWNER INSURER: AXA ACC DATE: 27/03/2018 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INT'L INS TP VEH: SH8121P							
68500-SNB-G00ZZ	LIDTRUNK ✓ DT	1	610.70	25	458.02	32.06	490.08	
74865-SNA-003	W/STRIPTRUNK LID ✓ Deform.	1	89.90	25	67.42	4.72	72.14	
84640-SNA-A01ZA	LININGRR.PANEL X	1	61.80	25	46.35	3.24	49.59	
75701-SNB-003	EMBLEMRR (H) ✓ NEC.	1	28.90	25	21.67	1.52	23.19	
91512-SR3-004	CLIP TUBULAR ?	1	2.30	25	1.72	0.12	1.84	
75722-SNB-J01	EMBLEMRR (CIVIC) ✓ NEC	1	31.40	25	23.55	1.65	25.20	
75731-SNA-K01	EMBLEMRR (1.8) ✓ NEC	1	18.40	25	13.80	0.97	14.77	
75725-SNA-K01	EMBLEMRR (I-VTEC) ✓ NEC.	1	34.70	25	26.02	1.82	27.84	
34156-SNB-023	LAMP UNITL. ?	1	152.70	25	114.52	8.02	122.54	
34151-SNB-023	LAMP UNITR. ?	1	152.70	25	114.52	8.02	122.54	
33551-SNB-003	LAMP UNIT L ?	1	236.70	25	177.52	12.43	189.95	
33501-SNB-003	LAMP UNIT R ?	1	236.70	25	177.52	12.43	189.95	
04711-SNB-000ZZ	FACEFR.BUMPER ✓ CRK.	1	715.70	25	536.77	37.57	574.34	
71593-SNA-A01	SPACERR.RR.BUMPER SIDE ✓ NEC.	1	15.30	25	11.47	0.80	12.27	
71598-SNA-A01	SPACERL RR BPR SIDE ✓ NEC.	1	15.30	25	11.47	0.80	12.27	
91503-SZ3-003	CLIP ABUMPER ✓ NEC.	8	3.90	25	23.40	1.64	25.04	
66100-SNA-U00ZZ	PANELREAR ?	1	276.60	25	207.45	14.52	221.97	
RS-2P	BUMPER SENSOR 2PCS ✓ DMG	1	150.00		150.00	10.50	160.50	
					Sum Item	2183.19	152.83	2,336.02
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00	

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SFJ678X
Chassis No : JHMFD16306S209608
Model : CIVIC 1.8L VTI-S AUTO
Owner's Name : S GANASAN S/O M SOKALINGAM
Ins Policy No :
Date of Accident : 27/3/2018

Document No. : SQT18001282 Page 2
Date : 27. Mar 2018
Customer No. : WZI007
Svc Advisor : JASON HENG
Engine No : R18A11030303
Date | Time : 27. Mar 2018 2:21:27 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	80	100.00	7.00	107.00
BA01R	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR REAR END PANEL	1	100.00	80	100.00	7.00	107.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	420	800.00	56.00	856.00
BKTRR	REMOVE & RENEW TRUNK LID.	1	800.00	560	800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	3000.00	Repair 1120 cut 2240	3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00	Repair 1350 cut 2250	2500.00	175.00	2675.00
Sum Labor					7500.00	525.00	8,025.00

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,683.19 677.83 10,361.02

Total (Inclusive of GST) 10,361.02

Sebastian
9/4/18.
- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint
- Subject to repair Salvage value.

90036121
sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/3/2018 5:03:39 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)