

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SFJ678X

Chassis No : JHMF16306S209608

Model : CIVIC 1.8L VTI-S AUTO

Owner's Name : S GANASAN S/O M SOKALINGAM

Ins Policy No. :

Date of Accident : 27/3/2018

Document No. : SQT18001282 **Page** 1

Date : 27. Mar 2018

Customer No. : WZI007

Svc Advisor : JASON HENG

Engine No : R18A11030303

Date | Time : 27. Mar 2018 2:21:27 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: S GANASAN S/O M SOKALINGAM OWNER INSURER: AXA ACC DATE: 27/03/2018 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INT'L INS TP VEH: SH8121P						
68500-SNB-G00ZZ	LIDTRUNK	1	610.70	25	458.02	32.06	490.08
74865-SNA-003	W/STRIPTRUNK LID	1	89.90	25	67.42	4.72	72.14
84640-SNA-A01ZA	LININGRR.PANEL	1	61.80	25	46.35	3.24	49.59
75701-SNB-003	EMBLEMRR (H)	1	28.90	25	21.67	1.52	23.19
91512-SR3-004	CLIP TUBULAR	1	2.30	25	1.72	0.12	1.84
75722-SNB-J01	EMBLEMRR (CIVIC)	1	31.40	25	23.55	1.65	25.20
75731-SNA-K01	EMBLEMRR (1.8)	1	18.40	25	13.80	0.97	14.77
75725-SNA-K01	EMBLEMRR (I-VTEC)	1	34.70	25	26.02	1.82	27.84
34156-SNB-023	LAMP UNITL.	1	152.70	25	114.52	8.02	122.54
34151-SNB-023	LAMP UNITR.	1	152.70	25	114.52	8.02	122.54
33551-SNB-003	LAMP UNIT L	1	236.70	25	177.52	12.43	189.95
33501-SNB-003	LAMP UNIT R	1	236.70	25	177.52	12.43	189.95
04711-SNB-000ZZ	FACEFR.BUMPER	1	715.70	25	536.77	37.57	574.34
71593-SNA-A01	SPACERR.RR.BUMPER SIDE	1	15.30	25	11.47	0.80	12.27
71598-SNA-A01	SPACERL RR BPR SIDE	1	15.30	25	11.47	0.80	12.27
91503-SZ3-003	CLIP ABUMPER	8	3.90	25	23.40	1.64	25.04
66100-SNA-U00ZZ	PANELREAR	1	276.60	25	207.45	14.52	221.97
RS-2P	BUMPER SENSOR 2PCS	1	150.00		150.00	10.50	160.50
Sum Item					<u>2183.19</u>	<u>152.83</u>	<u>2,336.02</u>
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SFJ678X

Chassis No : JHMF16306S209608

Model : CIVIC 1.8L VTI-S AUTO

Owner's Name : S GANASAN S/O M SOKALINGAM

Ins Policy No. :

Date of Accident : 27/3/2018

Document No. : SQT18001282 **Page** 2

Date : 27. Mar 2018

Customer No. : WZI007

Svc Advisor : JASON HENG

Engine No : R18A11030303

Date | Time : 27. Mar 2018 2:21:27 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00		100.00	7.00	107.00
BA01R	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR REAR END PANEL	1	100.00		100.00	7.00	107.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00		800.00	56.00	856.00
BKTRR	REMOVE & RENEW TRUNK LID.	1	800.00		800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	3000.00		3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00		2500.00	175.00	2675.00
Sum Labor					<u>7500.00</u>	<u>525.00</u>	<u>8,025.00</u>

Survey By

Date & Time

Excess

Status

Signature

Total Amount 9,683.19 677.83 10,361.02**Total (Inclusive of GST)** 10,361.02

Printed on 27/3/2018 5:03:39 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)