



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLK 7409 J

Parts	(a) Cost / List Price Items	\$	2,164.30
	Plus/Less 25%	\$	541.08
	Total of Cost / List	\$	1,623.23
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	1,823.23
Labour		\$	1,370.00
Total		\$	3,193.23

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : UKIC
Survey conducted on : 9/4/18 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 1-2 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : Sc Date: 9/4/18

Not Authorized
I.B.I
Resurvey By parts



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLK 7409 J**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU003540154**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	2	\$200.00	S.N	?
2	Rear bumper	1	\$497.50		?
3	Rear bumper lower garnish RH	1	\$149.70		X
4	Rear bumper lower garnish centre	1	\$582.60		✓
5	Rear bumper clip	10	\$40.00		?
6	Rear bumper side retainer LH	1	\$112.70		X
7	Rear bumper side retainer RH	1	\$112.70		X
8	Rear bumper reinforcement	1	\$398.90		?
9	Rear bumper under cover RH	1	\$256.20		X
10	Rear bumper under cover clip	4	\$14.00		X
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SLK 7409 J Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL)	\$500.00	2000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,END PANEL)	\$500.00	2000
3	To tuff coat <i>nn</i>	\$50.00	X
4	To check wiring	\$50.00	150
5	To remove & refit reverse sensor to assist work load	\$120.00	500
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.