

H3140 15m1

XINYA AUTO SERVICES PTE LTD

Add: BLK 1002, BUKIT MERAH LANE 3 #01 -75, Singapore 159719 Tel: 6273 3810 Fax: 6278 7522
E-mail : xinyaauto@singnet.com.sg

Date : 27-Mar-18

Address : AZMAN BIN MOHD ARIFFIN
BLK 20 TEBAN GARDENS ROAD
11-109
SINGAPORE 600020

Reference : TP 1153/03/18
Vehicle No : SGF 9417H
Make/Model : KIA CERATO
Insurance Co. : DIRECT ASIA

RE : QUOTATION REPAIRS TO SGF 9417H FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY		AMT \$
1)	REAR BUMPER	1	\$	390.00 DE ✓
2)	REAR BUMPER RETAINER	2	\$	50.00 X suc
3)	REAR ENFORCEMENT	1	\$	404.00 X suc
	LIST PRICE TOTAL			
	LESS DISCOUNT 20%		\$	844.00 390
	LIST PRICE TOTAL AFTER LESS		\$	168.80 20%
			\$	675.20 312
4)	REVERSE SENSOR	1	\$	150.00 ? X
	NETT PRICE TOTAL		\$	150.00 0
	TOTAL PARTS COST		\$	825.20

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE REAR BUMPER, ENFORCEMENT AND TO PANEL BEAT BOOT COVER.	\$	600.00 350 (3 DAYS)
2)	TO PUTTY & SPRAY PAINT REAR BUMPER AND BOOT COVER AND OTHER AFFECTED AREA.	\$	600.00 400 (3 Panel)
3)	TO CHECK & RECTIFY WIRING & FIT REVERSE SENSOR.	\$	100.00 60
	LABOUR TOTAL	\$	1,300.00

TOTAL ESTIMATED REPAIR COST

\$ 2,125.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
3 days
4/5
28/03/18 @ 1720
Resurvey after repair

312
810
1122
209
897.60
4/5 - 900
3 days