

# XINYA AUTO SERVICES PTE LTD

Add: BLK 1002, BUKIT MERAH LANE 3 #01 -75, Singapore 159719 Tel: 6273 3810 Fax: 6278 7522  
E-mail : xinyaauto@singnet.com.sg

Date : 27-Mar-18

Address : AZMAN BIN MOHD ARIFFIN  
BLK 20 TEBAN GARDENS ROAD  
# 11-109  
SINGAPORE 600020

Reference : TP 1153/03/18  
Vehicle No : SGF 9417H  
Make/Model : KIA CERATO  
Insurance Co. : DIRECT ASIA

## RE : QUOTATION REPAIRS TO SGF 9417H FOR THIRD PARTY CLAIMS.

| PARTS REQUIRED              | QTY | AMT \$         |
|-----------------------------|-----|----------------|
| 1) REAR BUMPER              | 1   | \$ 390.00 DE ✓ |
| 2) REAR BUMPER RETAINER     | 2   | \$ 50.00 X     |
| 3) REAR ENFORCEMENT         | 1   | \$ 404.00 ?    |
| LIST PRICE TOTAL            |     | \$ 844.00      |
| LESS DISCOUNT 20%           |     | \$ 168.80      |
| LIST PRICE TOTAL AFTER LESS |     | \$ 675.20      |
| 4) REVERSE SENSOR           | 1   | \$ 150.00 ?    |
| NETT PRICE TOTAL            |     | \$ 150.00      |
| TOTAL PARTS COST            |     | \$ 825.20      |

## LABOUR AND MISCELLANEOUS CHARGES

|                                                                               |                         |
|-------------------------------------------------------------------------------|-------------------------|
| 1) TO REMOVE & REPLACE REAR BUMPER, ENFORCEMENT AND TO PANEL BEAT BOOT COVER. | \$ 600.00 (3 DAYS) 350  |
| 2) TO PUTTY & SPRAY PAINT REAR BUMPER AND BOOT COVER AND OTHER AFFECTED AREA. | \$ 600.00 (3 Panel) 400 |
| 3) TO CHECK & RECTIFY WIRING & FIT REVERSE SENSOR.                            | \$ 100.00 60            |
| LABOUR TOTAL                                                                  | \$ 1,300.00             |

TOTAL ESTIMATED REPAIR COST

\$ 2,125.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

RASW  
HP 90010067  
3 days  
48  
28/03/18 @ 1720  
Resurvey after repair