



*Not filmed
black*

GST / ROC Company No : 201101753C

Third Party Insurer : AIG

Insured's Veh No : SJH6897D

Date of accident : 25.03.2018

*Take photo before
rainy.
3 days
28/3/18*

Quotation No : AR/QO18/03-1042

Quotation Date : 26.03.2018

Grab Rentals Pte Ltd
18 Sin Ming Lane
#01-08 Midview City
Singapore 573960

Estimate To Repair

Honda Vezei

Vehicle No :

SLR1815Y

Chassis No :

RU1223574

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
LIST ITEM			
1	1 PC	REAR GATE <i>3.05 m</i>	\$1,010.00
2	1 PC	REAR WINDOW MOULDING <i>neu</i>	\$160.00
3	1 PC	REAR GATE 'VEZEL' EMBLEM <i>neu</i>	\$45.00
4	1 PC	REAR GATE 'HYBRID' EMBLEM <i>neu</i>	\$60.00
5	1 PC	REAR GATE LOCK	\$105.00
6	1 PC	REAR BUMPER CENTRE	\$810.00
7	10 PCS	REAR BUMPER CLIPS @ \$5.50 <i>11</i>	\$55.00
			\$2,245.00
LESS 20%			\$(449.00)
			\$1,796.00
SPECIAL NETT ITEM			
8	1 PC	REAR WINDSCREEN GUM <i>neu</i>	<i>40</i> \$60.00
9	1 PC	REVERSE SENSOR	<i>?</i> \$250.00
			\$310.00
LABOUR & MISC. CHARGES			
1		WIRE CHECKING	<i>20</i> \$30.00
2		REMOVE & REFIX REAR WINDSCREEN	<i>✓</i> \$120.00
3		LABOUR CHARGE	<i>300</i> \$500.00
4		SPRAY PAINTING CHARGE	<i>400</i> \$500.00
			\$1,150.00
Sub Total			\$3,256.00
GST (7.00%)			\$227.92
Total			\$3,483.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

Acknowledged by Repairer