

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7502S**AAD1803-214***Not Authorized
C1 Lamp & 3700L*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 7502S
KL1LA69RJBB072628
CHEVROLET
EPICA 2.0
23.3.2018
INDIA

PART**LIST**

1	1	Rear Bumper	\$	<i>Buclm</i>	1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>Bu</i>	239.94	✓
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i>	260.00	X
4	1	Rear Bumper Side Retainer RH	\$	<i>Sn</i>	68.76	X
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i>	68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i>	119.74	X
7	1	Rear Bumper Reflectors LH	\$	<i>Sn</i>	119.74	X
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i>	93.00	X
9	1	Rear End Panel Outer	\$	<i>Bu</i>	623.76	✓
10	1	Rear End Panel Inner Trim	\$	<i>Sn</i>	263.84	X
11	1	Rear Luggage Floor Panel	\$	<i>R</i>	973.00	X
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i>	63.50	X
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i>	378.00	X
14	1	Bootlid	\$	<i>Bu</i>	973.00	✓
15	1	Bootlid inner trim board	\$	<i>Sn</i>	400.00	X
16	1	Bootlid Weatherstrip	\$	<i>Sn</i>	344.28	X
17	1	Bootlid Lock - Top	\$	<i>R</i>	466.56	X
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>Sn</i>	120.62	✓
19	1	Bootlid Logo	\$	<i>Sn</i>	138.84	✓
20	1	Bootlid 'EPICA LT' Badge	\$	<i>Sn</i>	119.84	✓
21	1	Bootlid Reflector Centre	\$	<i>Sn</i>	217.97	} X
22	1	Bootlid Reflector RH	\$	<i>Sn</i>	128.40	
23	1	Bootlid Reflector LH	\$	<i>Sn</i>	128.40	
24	1	Rear Tail Lamp RH	\$	<i>Sn</i>	479.30	
25	1	Rear Tail Lamp LH	\$	<i>Sn</i>	479.30	
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i>	1,110.00	} X
27	1	Rear Fender RH	\$	<i>R</i>	1,145.00	
28	1	Rear Fender Inner Trim RH	\$	<i>Sn</i>	418.44	
29	1	Rear Fender LH	\$	<i>R</i>	1,145.00	

Trans-cab Auto Services Pte Ltd

AAD1803-214

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7502S

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44 <i>X</i>
----	---	---------------------------	----	---------------------------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>na</i> 40.00 <i>X</i>
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sn</i> 300.00 <i>X</i>
3	1Set	Rear Bumper Fastener Clip	\$	<i>na</i> 44.00 <i>✓</i>
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>na</i> 30.00 <i>X</i>
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>na</i> 30.00 <i>X</i>
6	1	Rear Boot Sticker 'Trans-cab'	\$	<i>na</i> 30.00 <i>✓</i>
7	1	Rear Boot Sticker '6555-3333'	\$	<i>na</i> 30.00 <i>✓</i>
8	1	Rear Exhaust Mounting	\$	<i>Sn</i> 10.00 <i>X</i>
9	2	Rear Windscreen Sealant	\$	<i>na</i> 80.00 <i>X</i>
10	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i> 100.00 <i>X</i>
11	1	Spare Tyre	\$	<i>Sn</i> 180.00 <i>X</i>
12	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74 <i>X</i>

TOTAL	\$	1,000.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,437.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>600</i>
----	----------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>200</i>
----	--------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>600</i>
----	--------	------------

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	<i>600</i>
----	----------	------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>600</i>
----	--------	------------

Trans-cab Auto Services Pte Ltd**AAD1803-214**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7502S

To transfer of end panel fittings and conduct
water seepage test. \$ 170.00 *601*

To transfer of boot fittings and conduct water
seepage test. \$ 170.00 *601*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 *X*

To check steering geometry and computer
wheel alignment \$ *nn* 220.00 *X*

\$ 8,150.00

TOTAL \$ 20,587.43

(Lump Sum)**Repair Days***10 Days**5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: