



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

LEE CHUEN NAM

20/03/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP III

Xiao Tony

YV1DZ47HBE2524622

Accident date: 23/03/2018

Estimated repair cost for vehicle no: SKL2840K VOLVO XC60 T5 2.0 A '13

CHASSIS: YV1DZ47HBE2524622

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Not New</i>		\$3,156.10 X
2	2	Front Head Lamp <i>LH ut</i>	<i>\$2095</i>	<i>\$4190</i> <i>-2095</i>
3	2	Front Head Lamp Lower Bracket <i>cracked</i>	\$88.40	\$176.80 ✓
4	1	Front Bumper <i>Deformed</i>		\$1,624.20 ✓
5	10	Front Bumper Clip <i>new</i>	\$6.50	<i>\$65.00</i> <i>30</i>
6	2	Front Bumper Side Retainer <i>new</i>	\$88.70	\$177.40 ✓
7	1	Front Bumper Number Plate <i>Best</i>		\$50.00 ✓
8	1	Front Bumper Lower Centre Garnish <i>3 ut</i>		\$171.80 ✓
9	2	Front Bumper Lower Side Garnish Cover	\$80.40	\$160.80 ✓
10	1	Front Bumper Inner <i>Garnish</i> <i>Deformed</i>		\$216.90 ✓
11	1	Front Bumper Reinforcement <i>Best</i>		\$1,226.40 ✓
12	1	Front Bumper Lower Spoiler <i>Deformed</i>		\$647.70 ✓
13	1	Front L/H Bumper Fog Lamp <i>cracked</i>		\$487.00 ✓
14	1	Front L/H Bumper Wiper Nozzle Cover <i>Dehd</i>		\$35.70 ✓
15	1	Front L/H Bumper Wiper Nozzle & Bracket Assy <i>hangd</i>		\$121.00 ✓
16	1	Front Grille <i>ut</i>		\$745.30 ✓
17	1	Front Grille Emblem Logo <i>new</i>		\$55.00 ✓
18	1	Front Support Panel <i>3 ut</i>		\$1,240.70 X
19	1	Front Support Panel Top Cover <i>new</i>		\$387.70 X

Subtotal :- \$13,426.90

8021

7619.95

Labour charges

To remove & refit air-con condenser, radiator, fan motor
& top up gas

\$450.00 +

To check wiring

~~\$80.00~~ 30

Tuff kote

\$150.00 +

Panel beating

880

~~\$1,400.00~~ 460

Spray painting

~~\$1,000.00~~ 450

Subtotal :- \$3,080.00

Total:- \$3,080.00

Adrian G

28/03/18

04 hrs.

L/S

total 8479.95

L/S 68K

68K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

acknowledged by Repairer